

**LCRR Master Customer Account List (as of 2024.09.12)**  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-0001	1005	Woodcrest Heights Dr	Residential	1005 Woodcrest Heights Dr	N	C	N	1.25"	2010	P	1.25"	8/12/2020	SF	UNK	O	8/12/2020	Installation Record	Y	8/12/2020	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2020	Visual Insp During Install or Repair
000-0002	1911	Midway Rd	TBD	1911 Midway Rd	N	C	N	2"	1995	P	2"	1995	NONRES	UNK	C	Post 1984	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
000-0003	1205	Province Ter	Commercial	1205 Province Ter	N	C	N	4"	2021	P	4"	10/1/2021	NONRES	UNK	O	2021	Installation Record	Y	10/1/2021	Visual Insp During Install or Repair	Field Inspection Only	Y	10/1/2021	Visual Insp During Install or Repair
000-0005	1305	Oneida St	Commercial	1305 Oneida St	N	P	N	1.5"	2022	P	1.5"	5/20/2022	NONRES	UNK	O	2022	Installation Record	Y	5/20/2022	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/2022	Visual Insp During Install or Repair
000-0010	N8742	Firelane 1	Public Auth.	N8742 Firelane 1	N	C	N	1"	1984	C	1"	post-1984	NONRES	UNK	C	prior-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/6/2022	Cross Connection Survey
000-0011	N8742	Firelane 1	Public Auth.	N8742 Firelane 1	N	C	N	1"	1984	C	1"	post-1984	NONRES	UNK	C	prior-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/6/2022	Cross Connection Survey
000-0020	N8770	Firelane 1	Commercial	N8770 Firelane 1	N	C	N	6"	2014	P	6"	2014	NONRES	UNK	C	2022	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	12/14/2023	Cross Connection Survey
000-0030	N8774	Firelane 1	Commercial	N8774 Firelane 1	N	C	N	2"	1984	P	2"	post-1984	NONRES	UNK	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Cross Connection Survey
000-0031	N8774	Firelane 1	Commercial	N8774 Firelane 1	N	C	N	2"	1984	P	2"	post-1984	NONRES	UNK	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Cross Connection Survey
000-0080	W7293	HWY 10 & 114	Commercial	W7293 HWY 10 & 114	N	C	N	1"	1984	P	1.25"	post-1984	NONRES	UNK	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/2/2023	Cross Connection Survey
000-0090	W7289	HWY 10 & 114	Commercial	W7289 HWY 10 & 114	N	C	N	2"	1984	P	2"	post-1984	NONRES	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Cross Connection Survey
000-0110	W7257	HWY 10 & 114	Commercial	W7257 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2023	Cross Connection Survey
000-0130	W7223	HWY 10 & 114	Commercial	W7223 HWY 10 & 114	N	C	N	1"	1984	P	1"	post-1984	NONRES	N	O	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-0150	W7195	HWY 10 & 114	Commercial	W7195 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/16/2023	Cross Connection Survey
000-0151	W7195	HWY 10 & 114	Commercial	W7195 HWY 10 & 114	N	C	N	1"	1984	P	1"	post-1984	NONRES	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/26/2024	Cross Connection Survey
000-0152	W7191	HWY 10 & 114	Commercial	W7191 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2023	Cross Connection Survey
000-0170	W7185	HWY 10 & 114	Commercial	W7185 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2023	Cross Connection Survey
000-0200	W7150	HWY 10 & 114	Commercial	W7150 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2023	Cross Connection Survey
000-0210	W7158	HWY 10 & 114	Commercial	W7158 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	CLS	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-0220	W7170	HWY 10 & 114	Commercial	W7170 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	NONRES	N	CLS	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Cross Connection Survey
000-0230	N8808	HWY 10 & 114	Residential	N8808 HWY 10 & 114	N	C	N	1"	1984	C	1"	post-1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-0240	N8816 C	HWY 10 & 114	Residential	N8816 C HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1984	Visual Insp During Install or Repair
000-0241	N8816 A	HWY 10 & 114	Residential	N8816 A HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1984	Visual Insp During Install or Repair
000-0242	N8816 B	HWY 10 & 114	Residential	N8816 B HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1984	Visual Insp During Install or Repair
000-0250	N8824	HWY 10 & 114	Residential	N8824 HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2021	Cross Connection Survey
000-0300	N8853	HWY 10 & 114	Residential	N8853 HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/11/2021	Cross Connection Survey
000-0310	N8847	HWY 10 & 114	Residential	N8847 HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-0330	N8833	HWY 10 & 114	Residential	N8833 HWY 10 & 114	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/3/2022	Cross Connection Survey
000-0340	W6748	HWY 10 & 114	Residential	W6748 HWY 10 & 114	N	P	N	1.25"	2014	P	1.25"	12/5/2014	SF	N	C	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/5/2014	Visual Insp During Install or Repair
000-0370	W7265	Firelane 2	Residential	W7265 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Cross Connection Survey
000-0380	W7263	Firelane 2	Residential	W7263 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/12/2022	Cross Connection Survey
000-0400	W7259	Firelane 2	Residential	W7259 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/12/2024	Cross Connection Survey
000-0410	W7255	Firelane 2	Residential	W7255 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/2016	Visual Insp During Install or Repair
000-0420	W7251	Firelane 2	Residential	W7251 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2024	Cross Connection Survey
000-0430	W7249	Firelane 2	Residential	W7249 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/8/2021	Cross Connection Survey
000-0440	W7243	Firelane 2	Residential	W7243 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/2021	Cross Connection Survey
000-0450	W7239	Firelane 2	Residential	W7239 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/21/2024	Cross Connection Survey
000-0460	W7235	Firelane 2	Residential	W7235 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/12/2022	Cross Connection Survey
000-0470	W7233 A	Firelane 2	Residential	W7233 A Firelane 2	N	C	N	1"	1984	P	1"	pre-1982	SF	N	O	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/20/2019	Cross Connection Survey
000-0480	W7233 B	Firelane 2	Residential	W7233 B Firelane 2	N	C	N	1"	1984	C	1"	pre-1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/26/2021	Cross Connection Survey
000-0490	W7231	Firelane 2	Residential	W7231 Firelane 2	N	C	N	1"	1984	C	1"	pre-1982	SF	N	O	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2019	Cross Connection Survey
000-0500	W7225	Firelane 2	Residential	W7225 Firelane 2	N	C	N	1"	1984	C	1"	pre-1982	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/5/2019	Cross Connection Survey
000-0510	W7219	Firelane 2	Residential	W7219 Firelane 2	N	C	N	1"	1984	C	1"	pre-1982	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2021	Cross Connection Survey
000-0520	W7215	Firelane 2	Residential	W7215 Firelane 2	N	C	N	1"	1984	P	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/27/2022	Cross Connection Survey
000-0530	W7213	Firelane 2	Residential	W7213 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/24/2021	Cross Connection Survey
000-0540	W7205	Firelane 2	Residential	W7205 Firelane 2	N	C	N	1"	1984	C	1"	post-1984	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/5/2019	Cross Connection Survey
000-0550	W7199	Firelane 2	Residential	W7199 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/13/2021	Cross Connection Survey
000-0560	W7195	Firelane 2	Residential	W7195 Firelane 2	N	C	N	1"	1984	C	1"	Pre - 1982	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/24/2021	Cross Connection Survey
000-0570	W7191	Firelane 2	Residential	W7191 Firelane 2	N	C	N	1"	1984	C	1"	post-1984	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984					

**LCRR Master Customer Account List (as of 2024.09.12)**  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-1030	W6997	Firelane 3	Residential	W6997 Firelane 3	N	C	N	1"	1984	C	1"	post-1984	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
000-1040	W6995	Firelane 3	Residential	W6995 Firelane 3	N	C	N	1"	1984	C	1"	post-1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/23/2021	Cross Connection Survey
000-1050	W6987	Firelane 3	Residential	W6987 Firelane 3	N	C	N	1"	1984	C	1"	post-1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/20/2021	Cross Connection Survey
000-1060	W6981	Firelane 3	Residential	W6981 Firelane 3	N	C	N	1"	1984	C	1"	1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	5/22/1985	Visual Insp During Install or Repair
000-1070	W6977	Firelane 3	Residential	W6977 Firelane 3	N	C	N	1"	1984	P	1"	5/22/1985	SF	N	O	5/22/1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
000-1080	W6973	Firelane 3	Residential	W6973 Firelane 3	N	C	N	1"	1984	C	1"	10/26/1984	SF	N	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/31/2021	Cross Connection Survey
000-1090	W6967	Firelane 3	Residential	W6967 Firelane 3	N	C	N	1"	1984	C	1"	10/22/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	10/22/1984	Visual Insp During Install or Repair
000-1100	W6963	Firelane 3	Residential	W6963 Firelane 3	N	C	N	1"	1984	C	1"	8/9/1985	SF	UNK	C	1985	Installation Record	Y	1985	Visual Insp During Install or Repair	Installation Record	Y	8/9/1985	Visual Insp During Install or Repair
000-1110	W6939	Firelane 4	Residential	W6939 Firelane 4	N	C	N	1"	1984	C	1"	12/20/1984	SF	N	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/31/2021	Cross Connection Survey
000-1111	W6941	Firelane 4	Residential	W6941 Firelane 4	N	C	N	1"	1984	C	1"	6/28/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	6/28/1984	Visual Insp During Install or Repair
000-1120	W6935	Firelane 4	Residential	W6935 Firelane 4	N	C	N	1"	1984	C	1"	5/30/1985	SF	N	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/30/1985	Visual Insp During Install or Repair
000-1130	W6929	Firelane 4	Residential	W6929 Firelane 4	N	C	N	1"	1984	C	1"	5/21/1991	SF	N	O	1991	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/13/2021	Cross Connection Survey
000-1140	W6925	Firelane 4	Residential	W6925 Firelane 4	N	C	N	1"	1984	C	1"	6/25/1985	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/25/1985	Visual Insp During Install or Repair
000-1150	W6919	Firelane 4	Residential	W6919 Firelane 4	N	C	N	1"	1984	C	1"	5/22/1985	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	5/22/1985	Visual Insp During Install or Repair
000-1160	W6911	Firelane 4	Residential	W6911 Firelane 4	N	C	N	1"	1984	P	1"	5/22/1985	SF	Y	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2022	Cross Connection Survey
000-1170	W6905	Firelane 4	Residential	W6905 Firelane 4	N	C	N	1"	1984	P	1"	12/10/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/23/2021	Cross Connection Survey
000-1180	W6903	Firelane 4	Residential	W6903 Firelane 4	N	C	N	1"	1984	C	1"	6/25/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/30/2022	Cross Connection Survey
000-1190	W6899	Firelane 4	Residential	W6899 Firelane 4	N	C	N	1"	1984	C	1"	5/8/1985	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	5/8/1985	Visual Insp During Install or Repair
000-1201	W6897	Firelane 4	Residential	W6897 Firelane 4	N	C	N	1"	1984	C	1"	5/7/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/2019	Cross Connection Survey
000-1202	W6893	Firelane 4	Residential	W6893 Firelane 4	N	C	N	1"	1984	C	1"	5/15/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/30/2022	Cross Connection Survey
000-1203	W6887	Firelane 4	Residential	W6887 Firelane 4	N	C	N	1"	1984	C	1"	5/7/1985	SF	UNK	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	5/7/1985	Visual Insp During Install or Repair
000-1204	W6881	Firelane 4	Residential	W6881 Firelane 4	N	C	N	1"	1984	C	1"	5/7/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/13/2023	Cross Connection Survey
000-1205	W6877	Firelane 4	Residential	W6877 Firelane 4	N	C	N	1"	1984	C	1"	5/7/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
000-1206	W6871	Firelane 4	Residential	W6871 Firelane 4	N	C	N	1"	1984	C	1"	5/22/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2021	Cross Connection Survey
000-1207	W6865	Firelane 4	Residential	W6865 Firelane 4	N	C	N	1"	1984	C	1"	5/7/1985	SF	UNK	CLS	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/7/1985	Visual Insp During Install or Repair
000-1208	W6861	Firelane 4	Residential	W6861 Firelane 4	N	C	N	1"	1984	C	1"	5/3/1985	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/2021	Cross Connection Survey
000-1209	W6857	Firelane 4	Residential	W6857 Firelane 4	N	C	N	1"	1984	P	1"	1985	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/26/2019	Cross Connection Survey
000-1210	W6851	Firelane 4	Residential	W6851 Firelane 4	N	C	N	1"	1984	C	1"	7/19/1985	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2021	Cross Connection Survey
000-1230	N8780	Firelane 3	Residential	N8780 Firelane 3	N	C	N	1"	1984	C	1"	11/2/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	11/2/1984	Visual Insp During Install or Repair
000-1240	N8789	Firelane 3	Residential	N8789 Firelane 3	N	C	N	1"	1984	C	1"	10/12/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	10/12/1984	Visual Insp During Install or Repair
000-1250	W7068	HWY 10 & 114	Residential	W7068 HWY 10 & 114	N	C	N	1"	1984	C	1"	8/15/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	8/15/1985	Visual Insp During Install or Repair
000-1260	W7057	HWY 10 & 114	Residential	W7057 HWY 10 & 114	N	C	N	1"	1984	C	1"	10/24/1984	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2019	Cross Connection Survey
000-1261	N8788	Firelane 2	Residential	N8788 Firelane 2	N	C	N	1"	1984	P	1"	9/25/2002	SF	UNK	C	9/25/2002	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	4/30/2024	Cross Connection Survey
000-1270	W7010	HWY 10 & 114	Residential	W7010 HWY 10 & 114	N	C	N	1"	1984	C	1"	11/15/1985	SF	UNK	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	11/15/1985	Visual Insp During Install or Repair
000-1280	W6998	HWY 10 & 114	Residential	W6998 HWY 10 & 114	N	C	N	1"	1984	C	1"	11/12/1984	SF	UNK	CLS	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Installation Record	Y	11/12/1985	Visual Insp During Install or Repair
000-1290	W6992	HWY 10 & 114	Commercial	W6992 HWY 10 & 114	N	C	N	1"	1984	P	1.25"	11/13/1984	NONRES	UNK	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2023	Cross Connection Survey
000-1303	2400	Lake Cottage Ct	Residential	2400 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	1/23/2017	SF	UNK	O	1/23/2017	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2017	Visual Insp During Install or Repair
000-1304	2408	Lake Cottage Ct	Residential	2408 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	10/27/2015	SF	UNK	O	10/27/2015	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/27/2015	Visual Insp During Install or Repair
000-1305	2416	Lake Cottage Ct	Residential	2416 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	5/4/2018	SF	UNK	O	5/4/2018	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	5/4/2018	Visual Insp During Install or Repair
000-1306	2424	Lake Cottage Ct	Residential	2424 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	4/1/2019	SF	UNK	O	4/1/2019	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/1/2019	Visual Insp During Install or Repair
000-1307	2432	Lake Cottage Ct	Residential	2432 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	10/27/2016	SF	UNK	O	11/1/2016	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/27/2016	Visual Insp During Install or Repair
000-1308	2440	Lake Cottage Ct	Residential	2440 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	8/8/2016	SF	UNK	O	11/1/2016	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/2016	Visual Insp During Install or Repair
000-1309	2448	Lake Cottage Ct	Residential	2448 Lake Cottage Ct	N	P	N	1.25"	2006	P	1.25"	10/3/2017	SF	UNK	O	10/3/2017	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/3/2017	Visual Insp During Install or Repair
000-1320	N8803	Kernan Ave	Residential	N8803 Kernan Ave	N	C	N	1"	2000	P	1"	2000	SF	UNK	CLS	2000	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2000	Visual Insp During Install or Repair
000-1350	N8807	Kernan Ave	Residential	N8807 Kernan Ave	N	C	N	1"	1984	P	1"	2001	SF	N	C	2001	Installation Record	Y	2001	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2024	Cross Connection Survey
000-1370	2455	Kelly Lake Dr	Residential	2455 Kelly Lake Dr	N	C	N	1"	2003	P	1"	2004	SF	N	C	2004	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2024	Cross Connection Survey
000-1380	2459	Kelly Lake Dr	Residential	2459 Kelly Lake Dr	N	P	N	1"	2003	P	1"	2/13/2004	SF	UNK	C	2004	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2004	Visual Insp During Install or Repair
000-1381	2463	Kelly Lake Dr	Residential	2463 Kelly Lake Dr	N	P	N	1"	3/12/2004	P	1"	3/12/2004	SF	UNK	C	2004	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2004	Visual Insp During Install or Repair
000-1390	W6789	Firelane 5	Residential	W6789 Firelane 5	N	C	N	1"	1984	C	1"	11/6/1984	SF	UNK	C	pre-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/6/1984	Visual Insp During Install or Repair
000-1400	W6794	HWY 10 & 114	Residential	W6794 HWY 10 & 114	N	C	N	1"	1984	P	1"	4/5/2002	SF	N	O	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2024	Cross Connection Survey
000-1410	W6781	Firelane 5	Residential	W6781 Firelane 5	N	C	N	1"	1984	C	1"	11/28/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/28/1984	Visual Insp During Install or Repair
000-1450	W6767	Firelane 5	Residential	W6767 Firelane 5	N	C	N	1"	1984	C	1"	11/30/1989	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/2021	Cross Connection Survey
000-1470	W6759	Firelane 5	Residential	W6759 Firelane 5	N	C	N	1"	1984	C	1"	12/14/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2024	Cross Connection Survey
000-1480	W6755	Firelane 5	Residential	W6755 Firelane 5	N	C	N	1"	1984	P	1"	10/1/2013	SF	N	O	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/2022	Cross Connection Survey
000-1510	W6751	Firelane 5	Residential	W6751 Firelane 5	N	C	N	1"	1984	P	1"	12/10/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/26/2021	Cross Connection Survey
000-1520	W6747	Firelane 5	Residential	W6747 Firelane 5	N	C	N	1"	1984	P	1"													



**LCRR Master Customer Account List (as of 2024.09.12)**  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-1990	W6537	Firelane 8	Residential	W6537 Firelane 8	N	C	N	1"	1984	P	1"	4/18/1985	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/28/2019	Cross Connection Survey
000-2010	W6529	Firelane 8	Residential	W6529 Firelane 8	N	C	N	1"	1984	C	1"	5/30/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/30/1985	Visual Insp During Install or Repair
000-2020	W6523	Firelane 8	Residential	W6523 Firelane 8	N	C	N	1"	1984	C	1"	11/5/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/5/1984	Visual Insp During Install or Repair
000-2030	W6519	Firelane 8	Residential	W6519 Firelane 8	N	C	N	1"	1984	C	1"	5/1/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/1985	Visual Insp During Install or Repair
000-2040	W6515	Firelane 8	Residential	W6515 Firelane 8	N	C	N	1"	1984	C	1"	5/24/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/24/1985	Visual Insp During Install or Repair
000-2060	W6505	Firelane 8	Residential	W6505 Firelane 8	N	C	N	1"	1984	C	1"	6/29/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2024	Cross Connection Survey
000-2070	W6501	Firelane 8	Residential	W6501 Firelane 8	N	C	N	1"	1984	C	1"	5/24/1985	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-2080	W6495	Firelane 8	Residential	W6495 Firelane 8	N	C	N	1"	1984	P	1"	12/7/2021	SF	N	O	12/7/2021	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2022	Cross Connection Survey
000-2100	W6485	Firelane 8	Residential	W6485 Firelane 8	N	C	N	1"	1984	C	1"	10/23/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/24/2021	Cross Connection Survey
000-2110	W6477	Firelane 8	Residential	W6477 Firelane 8	N	C	N	1"	1984	C	1"	10/23/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/29/2021	Cross Connection Survey
000-2150	W6461	Firelane 8	Residential	W6461 Firelane 8	N	C	N	1"	1984	C	1"	10/12/1984	SF	UNK	CLS	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/12/1984	Cross Connection Survey
000-2160	W6455	Firelane 8	Residential	W6455 Firelane 8	N	C	N	1"	1984	C	1"	10/19/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/19/1984	Visual Insp During Install or Repair
000-2170	W6442	Firelane 8	Residential	W6442 Firelane 8	N	C	N	1"	1984	C	1"	11/12/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/20/2021	Cross Connection Survey
000-2180	W6438	Firelane 8	Residential	W6438 Firelane 8	N	C	N	1"	1984	C	1"	11/5/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/18/2019	Cross Connection Survey
000-2190	W6441	Firelane 8	Residential	W6441 Firelane 8	N	C	N	1"	1984	C	1"	12/26/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2021	Cross Connection Survey
000-2200	W6429	Firelane 8	Residential	W6429 Firelane 8	N	C	N	1"	1984	P	1"	10/23/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/12/2022	Cross Connection Survey
000-2210	W6419	Firelane 8	Residential	W6419 Firelane 8	N	C	N	1"	1984	C	1"	11/8/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/8/1984	Visual Insp During Install or Repair
000-2220	W6411	Firelane 8	Residential	W6411 Firelane 8	N	C	N	1"	1984	C	1"	8/23/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/23/1985	Visual Insp During Install or Repair
000-2240	W6403	Firelane 8	Residential	W6403 Firelane 8	N	C	N	1"	1984	C	1"	11/5/1984	SF	Y	C	1995	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2023	Cross Connection Survey
000-2250	W6400	Firelane 8	Residential	W6400 Firelane 8	N	C	N	1"	1984	C	1"	6/16/1988	SF	UNK	C	1988	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/16/1988	Visual Insp During Install or Repair
000-2260	W6390	Firelane 8	Residential	W6390 Firelane 8	N	C	N	1"	1984	C	1"	8/31/1992	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/31/2021	Cross Connection Survey
000-2270	W6393	Firelane 8	Residential	W6393 Firelane 8	N	C	N	1"	1984	C	1"	9/3/1985	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/21/2021	Cross Connection Survey
000-2280	W6385	Firelane 8	Residential	W6385 Firelane 8	N	C	N	1"	1984	C	1"	3/12/2019	SF	N	CLS	pre1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2019	Cross Connection Survey
000-2290	W6380	Firelane 8	Residential	W6380 Firelane 8	N	C	N	1"	1984	C	1"	2/27/1989	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2021	Cross Connection Survey
000-2300	W6370	Firelane 8	Residential	W6370 Firelane 8	N	C	N	1"	1984	C	1"	8/24/2021	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/24/2021	Cross Connection Survey
000-2310	W6366	Firelane 8	Residential	W6366 Firelane 8	N	C	N	1"	1984	C	1"	8/20/1988	SF	Y	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/20/2021	Cross Connection Survey
000-2320	W6375	Firelane 8	Residential	W6375 Firelane 8	N	C	N	1"	1984	C	1"	8/25/1988	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2021	Cross Connection Survey
000-2330	W6365	Firelane 8	Residential	W6365 Firelane 8	N	C	N	1"	1984	C	1"	7/6/1990	SF	UNK	C	1990	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/6/1990	Visual Insp During Install or Repair
000-2360	W6353	Firelane 8	Residential	W6353 Firelane 8	N	C	N	1"	1984	C	1"	10/22/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/2021	Cross Connection Survey
000-2380	W6350	Firelane 8	Residential	W6350 Firelane 8	N	C	N	1"	1984	C	1"	10/24/1984	SF	N	CLS	Pre - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2021	Cross Connection Survey
000-2390	N8597	Firelane 9	Residential	N8597 Firelane 9	N	C	N	1"	1984	P	1"	2/15/2005	SF	UNK	O	2005	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2005	Visual Insp During Install or Repair
000-2400	N8585	Firelane 9	Residential	N8585 Firelane 9	N	C	N	1"	1984	C	1"	11/21/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/21/1984	Visual Insp During Install or Repair
000-2410	W6309	Firelane 9	Residential	W6309 Firelane 9	N	C	N	1"	1984	C	1"	12/20/1985	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2022	Cross Connection Survey
000-2411	W6309	Firelane 9	Residential	W6309 Firelane 9	N	C	N	1"	1984	C	1"	12/20/1985	SF	N	C	Post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2022	Cross Connection Survey
000-2420	W6303	Firelane 9	Residential	W6303 Firelane 9	N	C	N	1"	1984	P	1.25"	2012	SF	N	O	2012	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2024	Cross Connection Survey
000-2450	W6287	Firelane 9	Residential	W6287 Firelane 9	N	C	N	1"	1984	C	1"	6/14/1985	SF	UNK	CLS	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/14/1985	Visual Insp During Install or Repair
000-2460	W6281	Firelane 9	Residential	W6281 Firelane 9	N	C	N	1"	1984	P	1"	12/26/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2022	Cross Connection Survey
000-2480	W6265	Firelane 9	Residential	W6265 Firelane 9	N	C	N	1"	1984	C	1"	1/29/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/1985	Visual Insp During Install or Repair
000-2510	W6251	Firelane 9	Residential	W6251 Firelane 9	N	C	N	1"	1984	C	1"	10/30/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/1984	Visual Insp During Install or Repair
000-2520	W6243	Firelane 9	Residential	W6243 Firelane 9	N	C	N	1"	1984	C	1"	11/12/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/12/1984	Visual Insp During Install or Repair
000-2521	W6233	Firelane 9	Residential	W6233 Firelane 9	N	C	N	1"	1984	C	1"	11/30/1994	SF	UNK	C	1994	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/30/1994	Visual Insp During Install or Repair
000-2530	W6244	Firelane 9	Residential	W6244 Firelane 9	N	C	N	1"	1984	C	1"	6/17/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/17/1985	Visual Insp During Install or Repair
000-2541	N8571	Firelane 10	Residential	N8571 Firelane 10	N	C	N	1"	1984	C	1"	3/16/1988	SF	UNK	C	1988	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/1988	Visual Insp During Install or Repair
000-2550	W6227	Firelane 9	Residential	W6227 Firelane 9	N	C	N	1"	1984	C	1"	11/16/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/22/2022	Cross Connection Survey
000-2560	W6217	Firelane 9	Residential	W6217 Firelane 9	N	C	N	1"	1984	C	1"	10/30/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/1984	Visual Insp During Install or Repair
000-2570	W6209	Firelane 9	Residential	W6209 Firelane 9	N	C	N	1"	1984	C	1"	12/26/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/26/1984	Visual Insp During Install or Repair
000-2580	W6205	Firelane 9	Residential	W6205 Firelane 9	N	C	N	1"	1984	C	1"	11/8/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/8/1984	Visual Insp During Install or Repair
000-2590	W6201	Firelane 9	Residential	W6201 Firelane 9	N	C	N	1"	1984	P	1"	11/12/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/7/2019	Cross Connection Survey
000-2591	N8555	Firelane 10	Residential	N8555 Firelane 10	N	C	N	1"	1984	C	1"	8/18/1989	SF	N	O	Post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2022	Cross Connection Survey
000-2610	W6206	Firelane 9	Residential	W6206 Firelane 9	N	C	N	1"	1984	C	1"	2/24/1986	SF	N	C	Post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/2/2022	Cross Connection Survey
000-2620	N8556	Firelane 10	Residential	N8556 Firelane 10	N	C	N	1"	1984	P	1.25"	10/31/2006	SF	UNK	O	2006	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/31/2006	Visual Insp During Install or Repair
000-2640	N8550	Firelane 10	Residential	N8550 Firelane 10	N	C	N	1"	1984	C	1"	11/5/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/5/1984	Visual Insp During Install or Repair
000-2650	N8560	Firelane 10	Residential	N8560 Firelane 10	N	C	N	1"	1984	P	1"	11/5/1984	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2022	Cross Connection Survey
000-2660	N8605	Firelane 10	Residential	N8605 Firelane 10	N	C	N	1"	1984	C	1"	6/17/1985	SF	N	CLS	Pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2022	Cross Connection Survey
000-2680	N8617 A	Firelane 10	Residential	N8617 A Firelane 10	N	C	N	1"	1984	C	1"	3/22/1990	MF	N	C	prior1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/26/2019	Cross Connection Survey
000-2681	N8617 B	Firelane 10	Residential	N8617 B Firelane 10	N	C	N	1"	1984	C	1"	3/22/1990	MF	N	C	prior 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y		

**LCRR Master Customer Account List (as of 2024.09.12)**  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-3082	N8675	Firelane 9	Residential	N8675 Firelane 9	N	C	N	1"	1984	C	1"	9/27/1990	SF	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/29/2022	Cross Connection Survey
000-3083	N8665	Firelane 9	Residential	N8665 Firelane 9	N	C	N	1"	1984	C	1"	2000	SF	N	C	2000	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
000-3084	N8655	Firelane 9	Residential	N8655 Firelane 9	N	C	N	1"	1984	C	1"	Post - 1984	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/30/2021	Cross Connection Survey
000-3085	W6306	Ravine Ct	Residential	W6306 Ravine Ct	N	C	N	1"	1993	C	1"	8/11/1993	SF	UNK	C	1993	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/1993	Visual Insp During Install or Repair
000-3086	W6307	Ravine Ct	Residential	W6307 Ravine Ct	N	C	N	1"	1993	C	1"	3/26/1993	SF	UNK	C	1993	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/26/1993	Visual Insp During Install or Repair
000-3087	N8617	Firelane 9	Residential	N8617 Firelane 9	N	C	N	1"	1984	C	1"	Post - 1984	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/26/2021	Cross Connection Survey
000-3090	N8616	Firelane 9	Residential	N8616 Firelane 9	N	C	N	1"	1984	C	1"	1/29/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/1985	Visual Insp During Install or Repair
000-3100	N8626	Firelane 9	Residential	N8626 Firelane 9	N	C	N	1"	1984	C	1"	6/24/1993	SF	UNK	C	1993	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/24/1993	Visual Insp During Install or Repair
000-3110	N8636	Firelane 9	Residential	N8636 Firelane 9	N	C	N	1"	1984	P	1"	Prior - 1982	SF	N	CLS	Prior - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/30/2021	Cross Connection Survey
000-3120	N8650	Firelane 9	Residential	N8650 Firelane 9	N	C	N	1"	1984	P	1.25"	1/26/2017	SF	UNK	O	2017	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/26/2017	Visual Insp During Install or Repair
000-3140	N8662	Firelane 9	Residential	N8662 Firelane 9	N	C	N	1"	1984	P	1"	Prior - 1982	SF	N	CLS	Prior - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/15/2021	Cross Connection Survey
000-3150	N8692	Firelane 9	Residential	N8692 Firelane 9	N	C	N	1"	1984	C	1"	11/21/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/21/1984	Visual Insp During Install or Repair
000-3160	W6285	Old Highway Rd	Residential	W6285 Old Highway Rd	N	C	N	1"	1984	P	1"	2/22/1985	SF	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/10/2022	Cross Connection Survey
000-3170	W6273	Old Highway Rd	Residential	W6273 Old Highway Rd	N	C	N	1"	1984	P	1"	Prior - 1982	SF	N	O	Prior - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2021	Cross Connection Survey
000-3171	W6257	Old Highway Rd	Residential	W6257 Old Highway Rd	N	C	N	1"	1984	C	1"	2/5/1987	SF	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2022	Cross Connection Survey
000-3172	W6265	Old Highway Rd	Residential	W6265 Old Highway Rd	N	C	N	1"	1984	C	1"	11/8/1988	SF	N	C	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2022	Cross Connection Survey
000-3180	W6251	Old Highway Rd	Residential	W6251 Old Highway Rd	N	C	N	1"	1984	C	1"	5/9/1985	SF	UNK	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/1985	Visual Insp During Install or Repair
000-3191	W6323	Old Highway Rd	Residential	W6323 Old Highway Rd	N	C	N	1"	1984	P	1.25"	11/23/2020	SF	UNK	O	2020	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2020	Visual Insp During Install or Repair
000-3200	W6237	Old Highway Rd	Residential	W6237 Old Highway Rd	N	C	N	1"	1984	C	1"	12/19/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/19/1984	Visual Insp During Install or Repair
000-3220	N8544	Firelane 10	Residential	N8544 Firelane 10	N	C	N	1"	1984	C	1"	11/28/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	11/28/1984	Visual Insp During Install or Repair
000-3231	W6149	Old Highway Rd	Commercial	W6149 Old Highway Rd	N	C	N	8"	post-1984	P	8"	post-1984	NONRES	N	C	post-1984	Installation Record	Y	2009	Visual Insp During Install or Repair	Field Inspection Only	Y	11/14/2023	Cross Connection Survey
000-3250	N8421	North Shore Rd	Commercial	N8421 North Shore Rd	N	P	N	4"	1984	P	4"	10/31/1984	NONRES	N	C	post-1984	Installation Record	Y	post-1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/14/2022	Cross Connection Survey
000-3260	N8357	North Shore Rd	Residential	N8357 North Shore Rd	N	C	N	1"	1984	C	1"	12/9/1984	SF	UNK	C	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	12/9/1984	Visual Insp During Install or Repair
000-3270	N8351	North Shore Rd	Residential	N8351 North Shore Rd	N	C	N	1"	1984	C	1"	12/11/1984	SF	N	CLS	pre-1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
000-3271	N8343	North Shore Rd	Residential	N8343 North Shore Rd	N	C	N	1"	1984	C	1.25"	2/10/1987	SF	Y	C	1987	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/13/2024	Cross Connection Survey
000-3280	N8337	North Shore Rd	Residential	N8337 North Shore Rd	N	C	N	1"	1984	P	1"	1/29/1985	SF	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
000-3290	N8323	North Shore Rd	Residential	N8323 North Shore Rd	N	C	N	1"	1984	C	1"	12/9/1984	SF	Y	CLS	Prior - 1982	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	9/1/2021	Cross Connection Survey
000-3300	N8321	North Shore Rd	Residential	N8321 North Shore Rd	N	C	N	1"	1984	C	1"	12/9/1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/29/2014	Visual Insp During Install or Repair
000-3320	N8425	North Shore Rd	Residential	N8425 North Shore Rd	N	C	N	1"	1984	C	1"	1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1984	Visual Insp During Install or Repair
000-3330	N8427	North Shore Rd	Residential	N8427 North Shore Rd	N	C	N	1"	1984	C	1"	1984	SF	UNK	CLS	1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1984	Visual Insp During Install or Repair
000-3340	N8431	North Shore Rd	Residential	N8431 North Shore Rd	N	C	N	1"	1984	C	1"	3/14/1996	SF	UNK	C	1996	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/1996	Visual Insp During Install or Repair
000-3341	W6330	Ravine Ct	Residential	W6330 Ravine Ct	N	C	N	1"	1993	P	1.25"	1/21/2009	SF	Y	O	1993	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2019	Cross Connection Survey
000-3342	W6334	Ravine Ct	Residential	W6334 Ravine Ct	N	C	N	1"	1993	C	1.25"	8/26/2002	SF	N	O	2002	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/2024	Cross Connection Survey
000-3343	W6338	Ravine Ct	Residential	W6338 Ravine Ct	N	C	N	1"	1993	C	1"	10/24/1996	SF	UNK	C	1996	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/24/1996	Visual Insp During Install or Repair
000-3344	W6342	Ravine Ct	Residential	W6342 Ravine Ct	N	C	N	1"	1993	P	1"	5/20/2003	SF	UNK	O	2003	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/2003	Visual Insp During Install or Repair
000-3346	W6354	Ravine Ct	Residential	W6354 Ravine Ct	N	C	N	1"	1993	C	1"	7/20/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/20/1994	Visual Insp During Install or Repair
000-3347	W6362	Ravine Ct	Residential	W6362 Ravine Ct	N	C	N	1"	1993	P	1"	10/28/1999	SF	N	C	1999	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
000-3351	W6347	Ravine Ct	Residential	W6347 Ravine Ct	N	C	N	1"	1993	C	1"	3/4/1997	SF	UNK	O	1997	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/1997	Visual Insp During Install or Repair
000-3352	W6337	Ravine Ct	Residential	W6337 Ravine Ct	N	C	N	1"	1993	C	1"	5/25/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/25/1994	Visual Insp During Install or Repair
000-3353	W6327	Ravine Ct	Residential	W6327 Ravine Ct	N	C	N	1"	1993	C	1"	10/18/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/1994	Visual Insp During Install or Repair
000-3354	W6317	Ravine Ct	Residential	W6317 Ravine Ct	N	C	N	1"	1993	C	1"	3/29/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/29/1994	Visual Insp During Install or Repair
000-3370	N8435	North Shore Rd	Residential	N8435 North Shore Rd	N	C	N	1"	1984	C	1"	6/1/1995	SF	UNK	C	1995	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/1/1995	Visual Insp During Install or Repair
000-3380	N8441	North Shore Rd	Residential	N8441 North Shore Rd	N	C	N	1"	1984	C	1"	6/27/1994	SF	UNK	C	1994	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/27/1994	Visual Insp During Install or Repair
000-3390	N8439	North Shore Rd	Residential	N8439 North Shore Rd	N	C	N	1"	1984	C	1"	10/18/1994	SF	UNK	C	1994	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/1994	Visual Insp During Install or Repair
000-3400	N8407	North Shore Rd	Residential	N8407 North Shore Rd	N	C	N	1"	1984	C	1"	1994	SF	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	3/22/2019	Cross Connection Survey
000-3410	N8405	North Shore Rd	Residential	N8405 North Shore Rd	N	C	N	1"	1984	C	1"	1994	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2021	Cross Connection Survey
000-3420	N8401	North Shore Rd	Residential	N8401 North Shore Rd	N	C	N	1"	1984	C	1"	5/31/1995	SF	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	5/12/2022	Cross Connection Survey
000-3450	N8391	North Shore Rd	Residential	N8391 North Shore Rd	N	C	N	1"	1984	C	1"	4/30/1996	SF	UNK	C	1996	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	4/30/1996	Visual Insp During Install or Repair
000-3460	N8385	North Shore Rd	Residential	N8385 North Shore Rd	N	C	N	1"	1984	C	1"	1985	SF	N	C	1985	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	2/10/2023	Cross Connection Survey
000-3470	N8383	North Shore Rd	Residential	N8383 North Shore Rd	N	C	N	1"	1984	C	1"	1985	SF	Y	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2022	Cross Connection Survey
000-3480	N8415	North Shore Rd	Residential	N8415 North Shore Rd	N	C	N	1"	1984	P	1"	3/15/1999	SF	N	C	post-1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
000-4010	W5893	Augusta Pl	Residential	W5893 Augusta Pl	N	C	N	1"	1984	P	1"	6/4/2000	SF	N	C	Post - 1984	Installation Record	Y	1984	Visual Insp During Install or Repair	Field Inspection Only	Y	7/21/2021	Cross Connection Survey
000-4020	W5883	Augusta Pl	Residential	W5883 Augusta Pl	N	C	N	1"	1993	P	1"	2001	SF	Y	O	2001	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2024	Cross Connection Survey
000-4030	W5871	Royaltrout Dr	Residential	W5871 Royaltrout Dr	N	C	N	1"	1993	P	1"	2/2/2000	SF	N	C	post-1984	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/5/2022	Cross Connection Survey
000-4040	W5867	Royaltrout Dr	Residential	W5867 Royaltrout Dr	N	C	N	1"	1993	P	1.25"	2/19/2015	SF	UNK	O	2015	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/19/2015	Visual Insp During Install or Repair
000-4050	W5861	Royaltrout Dr	Residential	W5861 Royaltrout Dr	N	C	N	1"	1993	P	1"	9/3/1997	SF	UNK	C	1997	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	9/3/1997	Visual Insp During Install or Repair
000-4060	W5853	Royaltrout Dr	Residential	W5853 Royaltrout Dr	N	C	N	1"	1993	P	1.25"	4/12/2002	SF	N	C	2002	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/26/2024	C



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-4430	W5834	Turnberry Dr	Residential	W5834 Turnberry Dr	N	P	N	1"	2003	P	1.25"	8/15/2013	SF	UNK	O	2013	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/14/2014	Visual Insp During Install or Repair
000-4440	W5826	Turnberry Dr	Residential	W5826 Turnberry Dr	N	P	N	1"	2003	P	1.25"	4/24/2013	SF	UNK	O	2013	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/24/2013	Visual Insp During Install or Repair
000-4450	W5820	Turnberry Dr	Residential	W5820 Turnberry Dr	N	P	N	1"	2003	P	1.25"	11/15/2012	SF	UNK	O	2012	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	11/15/2012	Visual Insp During Install or Repair
000-4460	W5812	Turnberry Dr	Residential	W5812 Turnberry Dr	N	P	N	1"	2003	P	1.25"	8/29/2012	SF	UNK	O	2012	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2012	Visual Insp During Install or Repair
000-4470	W5804	Turnberry Dr	Residential	W5804 Turnberry Dr	N	P	N	1"	2003	P	1.25"	7/15/2013	SF	UNK	O	2013	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2013	Visual Insp During Install or Repair
000-4480	W5794	Turnberry Dr	Residential	W5794 Turnberry Dr	N	P	N	1"	2003	P	1.25"	10/9/2013	SF	UNK	O	2013	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/9/2013	Visual Insp During Install or Repair
000-4490	W5786	Turnberry Dr	Residential	W5786 Turnberry Dr	N	P	N	1"	2003	P	1.25"	10/1/2007	SF	UNK	O	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/1/2007	Visual Insp During Install or Repair
000-4500	W5780	Turnberry Dr	Residential	W5780 Turnberry Dr	N	P	N	1"	2003	P	1.25"	2/4/2016	SF	UNK	O	2016	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	2/4/2016	Visual Insp During Install or Repair
000-4510	W5774	Turnberry Dr	Residential	W5774 Turnberry Dr	N	P	N	1"	2003	P	1.25"	8/18/2010	SF	N	C	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/11/2022	Cross Connection Survey
000-4520	W5768	Turnberry Dr	Residential	W5768 Turnberry Dr	N	P	N	1"	2003	P	1.25"	5/1/2017	SF	UNK	O	2017	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/2017	Visual Insp During Install or Repair
000-4540	W5775	Turnberry Dr	Residential	W5775 Turnberry Dr	N	P	N	1"	2003	P	1.25"	7/14/2005	SF	UNK	C	2005	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/14/2005	Visual Insp During Install or Repair
000-4550	W5781	Turnberry Dr	Residential	W5781 Turnberry Dr	N	P	N	1"	2003	P	1.25"	7/9/2008	SF	UNK	O	2008	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/9/2008	Visual Insp During Install or Repair
000-4560	W5789	Turnberry Dr	Residential	W5789 Turnberry Dr	N	P	N	1"	2003	P	1"	1/11/2005	SF	UNK	C	2005	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2005	Visual Insp During Install or Repair
000-4580	N8399	Firestone Way	Residential	N8399 Firestone Way	N	P	N	1"	2003	P	1.25"	6/2/2005	SF	UNK	C	2005	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	6/2/2005	Visual Insp During Install or Repair
000-4590	N8413	Firestone Way	Residential	N8413 Firestone Way	N	P	N	1"	2003	P	1.25"	1/24/2007	SF	UNK	C	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2007	Visual Insp During Install or Repair
000-4600	W5817	Turnberry Dr	Residential	W5817 Turnberry Dr	N	P	N	1"	2003	P	1"	7/18/2005	SF	UNK	C	2005	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/18/2005	Visual Insp During Install or Repair
000-4610	W5825	Turnberry Dr	Residential	W5825 Turnberry Dr	N	P	N	1"	2003	P	1.25"	5/30/2007	SF	UNK	C	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/30/2007	Visual Insp During Install or Repair
000-4620	W5835	Turnberry Dr	Residential	W5835 Turnberry Dr	N	P	N	1"	2003	P	1.25"	8/30/2007	SF	UNK	C	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/30/2007	Visual Insp During Install or Repair
000-4630	W5847	Turnberry Dr	Residential	W5847 Turnberry Dr	N	P	N	1"	2003	P	1.25"	9/14/2006	SF	UNK	C	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	9/14/2006	Visual Insp During Install or Repair
000-4640	N8422	Muirfield Way	Residential	N8422 Muirfield Way	N	P	N	1"	2003	P	1.25"	10/6/2015	SF	UNK	O	2016	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/6/2015	Visual Insp During Install or Repair
000-4650	N8414	Muirfield Way	Residential	N8414 Muirfield Way	N	P	N	1"	2003	P	1.25"	8/17/2007	SF	UNK	C	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/17/2007	Visual Insp During Install or Repair
000-4660	N8408	Muirfield Way	Residential	N8408 Muirfield Way	N	P	N	1"	2003	P	1.25"	3/2/2007	SF	UNK	C	2007	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2007	Visual Insp During Install or Repair
000-4670	N8411	Muirfield Way	Residential	N8411 Muirfield Way	N	P	N	1"	2003	P	1.25"	10/12/2013	SF	UNK	O	2013	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/12/2013	Visual Insp During Install or Repair
000-4710	N8439	Muirfield Way	Residential	N8439 Muirfield Way	N	P	N	1"	2003	P	1.25"	7/2/2012	SF	UNK	O	2012	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/2/2012	Visual Insp During Install or Repair
000-5010	1153	Southfield Dr	Residential	1153 Southfield Dr	N	C	N	1"	1992	C	1"	4/21/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/1994	Visual Insp During Install or Repair
000-5020	1145	Southfield Dr	Residential	1145 Southfield Dr	N	C	N	1"	1992	C	1"	4/15/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/15/1994	Visual Insp During Install or Repair
000-5030	1135	Southfield Dr	Residential	1135 Southfield Dr	N	C	N	1"	1992	C	1"	5/24/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/24/1994	Visual Insp During Install or Repair
000-5040	1127	Southfield Dr	Residential	1127 Southfield Dr	N	C	N	1"	1992	C	1"	9/27/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	9/27/1993	Visual Insp During Install or Repair
000-5050	1117	Southfield Dr	Residential	1117 Southfield Dr	N	C	N	1"	1992	C	1"	12/1/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/1/1994	Visual Insp During Install or Repair
000-5060	2090	Ridgecrest Ln	Residential	2090 Ridgecrest Ln	N	C	N	1"	1992	C	1"	12/13/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/13/1993	Visual Insp During Install or Repair
000-5070	2098	Ridgecrest Ln	Residential	2098 Ridgecrest Ln	N	C	N	1"	1992	C	1"	8/15/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/1994	Visual Insp During Install or Repair
000-5080	2106	Ridgecrest Ln	Residential	2106 Ridgecrest Ln	N	C	N	1"	1992	C	1"	7/28/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/28/1993	Visual Insp During Install or Repair
000-5090	2116	Ridgecrest Ln	Residential	2116 Ridgecrest Ln	N	C	N	1"	1992	C	1"	5/16/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/16/1995	Visual Insp During Install or Repair
000-5100	2124	Ridgecrest Ln	Residential	2124 Ridgecrest Ln	N	C	N	1"	1992	C	1"	9/27/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	9/27/1995	Visual Insp During Install or Repair
000-5110	2134	Ridgecrest Ln	Residential	2134 Ridgecrest Ln	N	C	N	1"	1992	C	1"	8/15/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/1996	Visual Insp During Install or Repair
000-5120	1002	Southfield Dr	Residential	1002 Southfield Dr	N	C	N	1"	1992	C	1"	7/14/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/14/1994	Visual Insp During Install or Repair
000-5130	1006	Southfield Dr	Residential	1006 Southfield Dr	N	C	N	1"	1992	C	1"	1/30/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/1995	Visual Insp During Install or Repair
000-5140	1012	Southfield Dr	Residential	1012 Southfield Dr	N	C	N	1"	1992	C	1"	5/20/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/1994	Visual Insp During Install or Repair
000-5150	1018	Southfield Dr	Residential	1018 Southfield Dr	N	C	N	1"	1992	C	1"	8/4/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/4/1993	Visual Insp During Install or Repair
000-5160	1022	Southfield Dr	Residential	1022 Southfield Dr	N	C	N	1"	1992	C	1"	7/14/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/14/1994	Visual Insp During Install or Repair
000-5170	1028	Southfield Dr	Residential	1028 Southfield Dr	N	C	N	1"	1992	C	1"	5/2/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/1995	Visual Insp During Install or Repair
000-5180	1032	Southfield Dr	Residential	1032 Southfield Dr	N	C	N	1"	1992	C	1"	4/10/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/10/1996	Visual Insp During Install or Repair
000-5190	1035	Mosshaven Ct	Residential	1035 Mosshaven Ct	N	C	N	1"	1992	P	1"	7/31/2000	SF	N	C	post-1984	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/31/2022	Cross Connection Survey
000-5200	1025	Mosshaven Ct	Residential	1025 Mosshaven Ct	N	C	N	1"	1992	C	1"	2/16/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/16/1995	Visual Insp During Install or Repair
000-5210	1015	Mosshaven Ct	Residential	1015 Mosshaven Ct	N	C	N	1"	1992	C	1"	3/10/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/1995	Visual Insp During Install or Repair
000-5220	1005	Mosshaven Ct	Residential	1005 Mosshaven Ct	N	C	N	1"	1992	P	1"	11/4/2004	SF	UNK	O	2004	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	11/4/2004	Visual Insp During Install or Repair
000-5230	1000	Mosshaven Ct	Residential	1000 Mosshaven Ct	N	C	N	1"	1992	P	1"	7/6/1999	SF	N	C	Post - 1984	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
000-5240	1010	Mosshaven Ct	Residential	1010 Mosshaven Ct	N	C	N	1"	1992	C	1"	8/16/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/16/1994	Visual Insp During Install or Repair
000-5250	1020	Mosshaven Ct	Residential	1020 Mosshaven Ct	N	C	N	1"	1992	C	1"	11/3/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	11/3/1994	Visual Insp During Install or Repair
000-5260	1044	Southfield Dr	Residential	1044 Southfield Dr	N	C	N	1"	1992	C	1"	5/20/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/1994	Visual Insp During Install or Repair
000-5270	1035	Purple Sage Ct	Residential	1035 Purple Sage Ct	N	C	N	1"	1992	C	1"	8/16/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/16/1994	Visual Insp During Install or Repair
000-5280	1025	Purple Sage Ct	Residential	1025 Purple Sage Ct	N	C	N	1"	1992	C	1"	9/28/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	9/28/1993	Visual Insp During Install or Repair
000-5290	1015	Purple Sage Ct	Residential	1015 Purple Sage Ct	N	C	N	1"	1992	C	1"	11/16/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	11/16/1994	Visual Insp During Install or Repair
000-5300	1005	Purple Sage Ct	Residential	1005 Purple Sage Ct	N	C	N	1"	1992	C	1"	2/18/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/18/1994	Visual Insp During Install or Repair
000-5310	1010	Purple Sage Ct	Residential	1010 Purple Sage Ct	N	C	N	1"	1992	C	1"	8/31/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/31/1993	Visual Insp During Install or Repair
000-5320	1020	Purple Sage Ct	Residential	1020 Purple Sage Ct	N	C	N	1"	1992	C	1"	10/26/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	10/26/1995	Visual Insp During Install or Repair
000-5330	1030	Purple Sage Ct	Residential	1030 Purple Sage Ct	N	C	N	1"	1992	C	1"													

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-5780	2043	Manitowoc Rd	Commercial	2043 Manitowoc Rd	N	C	N	1"	1993	C	1"	8/10/1994	NONRES	N	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/2023	Cross Connection Survey
000-5820	2059	Manitowoc Rd	Residential	2059 Manitowoc Rd	N	C	N	1"	1993	C	1"	11/11/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/11/1994	Visual Insp During Install or Repair
000-5970	2092	Manitowoc Rd	Residential	2092 Manitowoc Rd	N	C	N	1"	1993	P	1"	10/31/2000	SF	N	C	2000	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2019	Cross Connection Survey
000-5980	2087	Manitowoc Rd	Residential	2087 Manitowoc Rd	N	C	N	1"	1993	C	1"	10/6/1993	SF	UNK	C	1993	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/6/1993	Visual Insp During Install or Repair
000-6000	2137	Manitowoc Rd	Residential	2137 Manitowoc Rd	N	C	N	1"	1993	C	1"	12/2/1993	SF	UNK	C	1993	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	12/2/1993	Visual Insp During Install or Repair
000-6011	W2281	Manitowoc Rd	Public Auth.	W2281 Manitowoc Rd	N	C	N	1"	1993	C	1"	12/4/1992	SF	UNK	C	1992	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/4/1992	Visual Insp During Install or Repair
000-6020	2155	Plank Rd	Residential	2155 Plank Rd	N	C	N	1"	1993	C	1"	5/13/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/13/1993	Visual Insp During Install or Repair
000-6021	2164	Manitowoc Rd	Residential	2164 Manitowoc Rd	N	C	N	1"	1992	P	1"	2/2/2000	SF	N	C	2000	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2022	Cross Connection Survey
000-6022	2152	Plank Rd	Residential	2152 Plank Rd	N	C	N	1"	1993	C	1"	12/29/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/29/1994	Visual Insp During Install or Repair
000-6023	2171	Plank Rd	Residential	2171 Plank Rd	N	C	N	1"	1992	P	1"	1/6/2000	SF	N	C	2000	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/8/2022	Cross Connection Survey
000-6024	2163	Plank Rd	Residential	2163 Plank Rd	N	C	N	1"	1993	C	1"	12/16/1999	SF	Y	C	1999	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2023	Cross Connection Survey
000-6025	2159	Plank Rd	Residential	2159 Plank Rd	N	C	N	1"	1993	P	1"	2002	SF	N	C	2002	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2024	Cross Connection Survey
000-6026	2160	Manitowoc Rd	Residential	2160 Manitowoc Rd	N	C	N	1"	1992	P	1"	4/9/2003	SF	UNK	C	2003	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/9/2003	Visual Insp During Install or Repair
000-6027	2168 1	Manitowoc Rd	Residential	2168 1 Manitowoc Rd	N	C	N	1"	1992	P	1.25"	7/30/2019	SF	UNK	O	7/30/2019	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/30/2019	Visual Insp During Install or Repair
000-6028	2168 2	Manitowoc Rd	Residential	2168 2 Manitowoc Rd	N	C	N	1"	1992	P	1.25"	7/30/2019	SF	UNK	O	7/30/2019	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/30/2019	Visual Insp During Install or Repair
000-6030	1200	Carpenter St	Residential	1200 Carpenter St	N	C	N	1"	1992	C	1"	2/5/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/1996	Visual Insp During Install or Repair
000-6031	1204	Carpenter St	Residential	1204 Carpenter St	N	C	N	1"	1992	C	1"	2/5/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/1996	Visual Insp During Install or Repair
000-6032	1210	Carpenter St	Residential	1210 Carpenter St	N	C	N	1"	1992	C	1"	12/26/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/26/1995	Visual Insp During Install or Repair
000-6033	1214	Carpenter St	Residential	1214 Carpenter St	N	C	N	1"	1992	C	1"	12/26/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/26/1995	Visual Insp During Install or Repair
000-6034	1220	Carpenter St	Residential	1220 Carpenter St	N	C	N	1"	1992	C	1"	12/26/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/26/1995	Visual Insp During Install or Repair
000-6035	1224	Carpenter St	Residential	1224 Carpenter St	N	C	N	1"	1992	C	1"	12/26/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/26/1995	Visual Insp During Install or Repair
000-6040	W7094	Manitowoc Rd	Residential	W7094 Manitowoc Rd	N	C	N	1"	1992	C	1"	6/1/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	6/1/1993	Visual Insp During Install or Repair
000-6050	W7086	Manitowoc Rd	Residential	W7086 Manitowoc Rd	N	C	N	1"	1992	C	1"	1/28/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/1993	Visual Insp During Install or Repair
000-6060	W7080	Manitowoc Rd	Residential	W7080 Manitowoc Rd	N	C	N	1"	1992	C	1"	1/27/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/1993	Visual Insp During Install or Repair
000-6070	W7068	Manitowoc Rd	Residential	W7068 Manitowoc Rd	N	C	N	1"	1992	C	1"	6/12/1997	SF	UNK	C	1997	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/1997	Visual Insp During Install or Repair
000-6080	W7058	Manitowoc Rd	Residential	W7058 Manitowoc Rd	N	C	N	1"	1992	C	1"	2/4/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/4/1993	Visual Insp During Install or Repair
000-6090	N9103	Harmon Rd	Residential	N9103 Harmon Rd	N	C	N	1"	1992	C	1"	4/5/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/1993	Visual Insp During Install or Repair
000-6100	W7098	Manitowoc Rd	Residential	W7098 Manitowoc Rd	N	C	N	1"	1992	C	1"	1/22/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/1993	Visual Insp During Install or Repair
000-6110	W7095	Shea Rd	Residential	W7095 Shea Rd	N	C	N	1"	1992	C	1"	5/2/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/1995	Visual Insp During Install or Repair
000-6120	W7089	Shea Rd	Residential	W7089 Shea Rd	N	C	N	1"	1992	C	1"	12/17/1992	SF	UNK	C	1992	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/17/1992	Visual Insp During Install or Repair
000-6130	W7081	Shea Rd	Residential	W7081 Shea Rd	N	C	N	1"	1992	C	1"	7/31/1998	SF	UNK	C	1998	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/31/1998	Visual Insp During Install or Repair
000-6140	W7073	Shea Rd	Residential	W7073 Shea Rd	N	C	N	1"	1992	C	1"	7/12/1994	SF	UNK	C	1994	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/12/1994	Visual Insp During Install or Repair
000-6150	W7067	Shea Rd	Residential	W7067 Shea Rd	N	C	N	1"	1992	C	1"	5/3/1999	SF	N	C	1999	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/13/2019	Cross Connection Survey
000-6160	W7061	Shea Rd	Residential	W7061 Shea Rd	N	C	N	1"	1992	C	1"	2/4/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/4/1993	Visual Insp During Install or Repair
000-6170	W7057	Shea Rd	Residential	W7057 Shea Rd	N	C	N	1"	1992	C	1"	4/13/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/1993	Visual Insp During Install or Repair
000-6180	W7061	Verna Rd	Residential	W7061 Verna Rd	N	C	N	1"	1992	C	1"	6/4/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	6/4/1993	Visual Insp During Install or Repair
000-6190	W7090	Shea Rd	Residential	W7090 Shea Rd	N	C	N	1"	1992	C	1"	1/29/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/1993	Visual Insp During Install or Repair
000-6210	W7076	Verna Rd	Residential	W7076 Verna Rd	N	C	N	1"	1992	C	1"	2/1/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/1993	Visual Insp During Install or Repair
000-6220	W7070	Verna Rd	Residential	W7070 Verna Rd	N	C	N	1"	1992	C	1"	1/27/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/1993	Visual Insp During Install or Repair
000-6230	W7064	Verna Rd	Residential	W7064 Verna Rd	N	C	N	1"	1992	C	1"	1/15/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/1993	Visual Insp During Install or Repair
000-6240	W7060	Verna Rd	Residential	W7060 Verna Rd	N	C	N	1"	1992	C	1"	2/8/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/1993	Visual Insp During Install or Repair
000-6250	N9145	Harmon Rd	Residential	N9145 Harmon Rd	N	C	N	1"	1992	C	1"	1/28/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/1993	Visual Insp During Install or Repair
000-6260	W7097	Plank Rd	Residential	W7097 Plank Rd	N	C	N	1"	1992	C	1"	4/5/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/1993	Visual Insp During Install or Repair
000-6270	W7095	Plank Rd	Residential	W7095 Plank Rd	N	C	N	1"	1992	C	1"	2/15/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/1993	Visual Insp During Install or Repair
000-6280	W7093	Plank Rd	Residential	W7093 Plank Rd	N	C	N	1"	1992	C	1"	1/29/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/1993	Visual Insp During Install or Repair
000-6290	W7089	Plank Rd	Residential	W7089 Plank Rd	N	C	N	1"	1992	C	1"	4/12/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/1993	Visual Insp During Install or Repair
000-6300	W7085	Plank Rd	Residential	W7085 Plank Rd	N	C	N	1"	1992	C	1"	2/8/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/1993	Visual Insp During Install or Repair
000-6301	W7088	Plank Rd	Residential	W7088 Plank Rd	N	C	N	1"	1992	C	1"	8/7/1997	SF	UNK	C	1997	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/1997	Visual Insp During Install or Repair
000-6302	W7038	Plank Rd	Residential	W7038 Plank Rd	N	C	N	1"	1992	P	1"	7/25/2001	SF	N	C	2001	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2023	Cross Connection Survey
000-6306	W7096	Plank Rd	Residential	W7096 Plank Rd	N	C	N	1"	1992	P	1"	11/22/2013	SF	UNK	C	2013	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	11/22/2013	Visual Insp During Install or Repair
000-6310	W7079	Plank Rd	Residential	W7079 Plank Rd	N	C	N	1"	1992	C	1"	12/4/1995	SF	N	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2023	Cross Connection Survey
000-6311	W7073	Plank Rd	Residential	W7073 Plank Rd	N	C	N	1"	1992	C	1"	12/4/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/4/1995	Visual Insp During Install or Repair
000-6320	W7061	Plank Rd	Residential	W7061 Plank Rd	N	C	N	1"	1992	C	1"	4/26/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/1993	Visual Insp During Install or Repair
000-6330	N9164	Harmon Rd	Residential	N9164 Harmon Rd	N	C	N	1"	1992	C	1"	8/2/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/2/1993	Visual Insp During Install or Repair
000-6340	W7033	Plank Rd	Residential	W7033 Plank Rd	N	C	N	1"	1992	C	1"	7/13/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/13/1993	Visual Insp During Install or Repair
000-6360	N9154	Harmon Rd	Residential	N9154 Harmon Rd	N	C	N	1"	1992	C	1"	5/2/1995	SF	UNK	C	1995	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/1995	Visual Insp During Install or Repair
000-6361	N9148	Harmon Rd	Residential	N9148 Harmon Rd	N	C	N	1"	1992	C	1"	11/14/1996	SF	UNK	C	1996	Installation Record	Y						



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-6880	N9075	Kernan Ave	Residential	N9075 Kernan Ave	N	C	N	1"	1996	C	1"	8/27/1997	SF	UNK	C	1997	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/1997	Visual Insp During Install or Repair
000-6890	N9069	Kernan Ave	Residential	N9069 Kernan Ave	N	C	N	1"	1996	C	1"	8/21/1997	SF	UNK	C	1997	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/1997	Visual Insp During Install or Repair
000-6900	N9061	Kernan Ave	Residential	N9061 Kernan Ave	N	C	N	1"	1996	C	1"	10/23/1996	SF	UNK	C	1996	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	10/23/1996	Visual Insp During Install or Repair
000-6950	N9094	Kernan Ave	Residential	N9094 Kernan Ave	N	C	N	1"	1996	P	1"	10/30/2001	SF	N	C	2001	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2023	Cross Connection Survey
000-6960	N9086	Kernan Ave	Residential	N9086 Kernan Ave	N	C	N	1"	1996	P	1"	7/26/2001	SF	UNK	C	2001	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	7/26/2001	Visual Insp During Install or Repair
000-6970	N9078	Kernan Ave	Residential	N9078 Kernan Ave	N	C	N	1"	1996	P	1"	12/18/2001	SF	N	C	2003	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	2/22/2023	Cross Connection Survey
000-6980	N9072	Kernan Ave	Residential	N9072 Kernan Ave	N	C	N	1"	1996	C	1"	5/3/1999	SF	N	C	1999	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
000-6990	N9064	Kernan Ave	Residential	N9064 Kernan Ave	N	C	N	1"	1996	P	1"	7/14/1999	SF	N	C	1999	Installation Record	Y	1996	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2019	Cross Connection Survey
000-7000	W6867	Manitowoc Rd	Residential	W6867 Manitowoc Rd	N	C	N	1"	1992	C	1"	12/9/1992	SF	UNK	C	1992	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/9/1992	Visual Insp During Install or Repair
000-7010	W6859	Manitowoc Rd	Residential	W6859 Manitowoc Rd	N	C	N	1"	1992	P	1"	2002	SF	N	C	2002	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2024	Cross Connection Survey
000-7020	W6863	Manitowoc Rd	Residential	W6863 Manitowoc Rd	N	C	N	1"	1992	P	1"	10/15/2002	SF	N	C	2003	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/7/2023	Cross Connection Survey
000-7100	W6845	Manitowoc Rd	Residential	W6845 Manitowoc Rd	N	C	N	1"	1992	P	1"	7/16/1999	SF	N	C	1999	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2020	Cross Connection Survey
000-7400	W6753	Manitowoc Rd	Residential	W6753 Manitowoc Rd	N	C	N	1"	1992	C	1"	1/21/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	1/21/1993	Visual Insp During Install or Repair
000-7401	W6753	Manitowoc Rd	Agricultural	W6753 Manitowoc Rd	N	C	N	1"	1992	C	1"	7/14/1993	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/14/1993	Visual Insp During Install or Repair
000-7402	W6707	Manitowoc Rd	Residential	W6707 Manitowoc Rd	N	C	N	1"	1992	P	1"	6/13/2002	SF	UNK	C	1993	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	6/13/2002	Visual Insp During Install or Repair
000-7403	W6711	Manitowoc Rd	Residential	W6711 Manitowoc Rd	N	C	N	1"	1992	P	1"	10/13/2004	SF	UNK	C	2004	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	10/13/2004	Visual Insp During Install or Repair
000-7430	2889	Manitowoc Rd	Residential	2889 Manitowoc Rd	N	C	N	1"	1992	P	1.25"	10/30/2007	SF	UNK	C	2007	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/2007	Visual Insp During Install or Repair
000-7500	N9111	Johann Dr	Residential	N9111 Johann Dr	N	C	N	1"	1992	C	1"	12/28/1992	SF	UNK	C	1992	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	12/28/1992	Visual Insp During Install or Repair
000-7540	N9141	Johann Dr	Residential	N9141 Johann Dr	N	C	N	1"	1992	C	1"	4/4/1994	SF	UNK	C	1992	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/1994	Visual Insp During Install or Repair
000-7550	N9153	Berryfield Ln	Residential	N9153 Berryfield Ln	N	C	N	1"	1993	C	1"	7/11/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/11/1995	Visual Insp During Install or Repair
000-7560	N9159	Berryfield Ln	Residential	N9159 Berryfield Ln	N	C	N	1"	1993	C	1"	11/7/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/1994	Visual Insp During Install or Repair
000-7570	N9167	Berryfield Ln	Residential	N9167 Berryfield Ln	N	C	N	1"	1993	C	1"	11/7/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/1994	Visual Insp During Install or Repair
000-7580	N9173	Berryfield Ln	Residential	N9173 Berryfield Ln	N	C	N	1"	1993	C	1"	1/24/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/1995	Visual Insp During Install or Repair
000-7590	N9181	Berryfield Ln	Residential	N9181 Berryfield Ln	N	C	N	1"	1993	C	1"	6/1/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	6/1/1995	Visual Insp During Install or Repair
000-7600	N9187	Berryfield Ln	Residential	N9187 Berryfield Ln	N	C	N	1"	1993	C	1"	7/19/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/19/1995	Visual Insp During Install or Repair
000-7610	N9193	Berryfield Ln	Residential	N9193 Berryfield Ln	N	C	N	1"	1993	C	1"	7/19/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/19/1995	Visual Insp During Install or Repair
000-7620	N9201	Berryfield Ln	Residential	N9201 Berryfield Ln	N	C	N	1"	1993	C	1"	3/10/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/1995	Visual Insp During Install or Repair
000-7630	N9207	Berryfield Ln	Residential	N9207 Berryfield Ln	N	C	N	1"	1993	C	1"	1/24/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/1995	Visual Insp During Install or Repair
000-7640	3719	S Berryfield Ln	Residential	3719 S Berryfield Ln	N	C	N	1"	1993	C	1"	10/18/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/1994	Visual Insp During Install or Repair
000-7650	3717	S Berryfield Ln	Residential	3717 S Berryfield Ln	N	C	N	1"	1993	C	1"	10/18/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/1994	Visual Insp During Install or Repair
000-7660	3709	S Berryfield Ln	Residential	3709 S Berryfield Ln	N	C	N	1"	1993	C	1"	3/29/2000	SF	N	C	2000	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/24/2023	Cross Connection Survey
000-7670	3711	S Berryfield Ln	Residential	3711 S Berryfield Ln	N	C	N	1"	1993	C	1"	3/29/2000	SF	N	C	2000	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/18/2023	Cross Connection Survey
000-7680	1703	E Hulke Dr	Residential	1703 E Hulke Dr	N	C	N	1"	1993	C	1"	11/7/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/1994	Visual Insp During Install or Repair
000-7690	1701	E Hulke Dr	Residential	1701 E Hulke Dr	N	C	N	1"	1993	C	1"	11/7/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/1994	Visual Insp During Install or Repair
000-7700	N9154	Berryfield Ln	Residential	N9154 Berryfield Ln	N	C	N	1"	1993	C	1"	8/11/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/1994	Visual Insp During Install or Repair
000-7710	N9160	Berryfield Ln	Residential	N9160 Berryfield Ln	N	C	N	1"	1993	C	1"	7/19/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/19/1995	Visual Insp During Install or Repair
000-7720	N9168	Berryfield Ln	Residential	N9168 Berryfield Ln	N	C	N	1"	1993	C	1"	7/11/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/11/1995	Visual Insp During Install or Repair
000-7730	N9174	Berryfield Ln	Residential	N9174 Berryfield Ln	N	C	N	1"	1993	C	1"	3/29/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/29/1995	Visual Insp During Install or Repair
000-7740	N9182	Berryfield Ln	Residential	N9182 Berryfield Ln	N	C	N	1"	1993	C	1"	7/20/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	7/20/1995	Visual Insp During Install or Repair
000-7750	N9188	Berryfield Ln	Residential	N9188 Berryfield Ln	N	C	N	1"	1993	C	1"	10/18/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/1994	Visual Insp During Install or Repair
000-7760	N9194	Berryfield Ln	Residential	N9194 Berryfield Ln	N	C	N	1"	1993	C	1"	11/7/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/1994	Visual Insp During Install or Repair
000-7770	N9202	Berryfield Ln	Residential	N9202 Berryfield Ln	N	C	N	1"	1993	C	1"	1/24/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/1995	Visual Insp During Install or Repair
000-7780	N9208	Berryfield Ln	Residential	N9208 Berryfield Ln	N	C	N	1"	1993	C	1"	5/23/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/23/1995	Visual Insp During Install or Repair
000-7790	N9153	Johann Dr	Residential	N9153 Johann Dr	N	C	N	1"	1993	C	1"	8/11/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/1994	Visual Insp During Install or Repair
000-7800	N9159	Johann Dr	Residential	N9159 Johann Dr	N	C	N	1"	1993	C	1"	4/12/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/1994	Visual Insp During Install or Repair
000-7810	N9167	Johann Dr	Residential	N9167 Johann Dr	N	C	N	1"	1993	C	1"	6/12/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/1994	Visual Insp During Install or Repair
000-7820	N9173	Johann Dr	Residential	N9173 Johann Dr	N	C	N	1"	1993	C	1"	8/26/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/1994	Visual Insp During Install or Repair
000-7830	N9181	Johann Dr	Residential	N9181 Johann Dr	N	C	N	1"	1993	C	1"	8/26/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/1994	Visual Insp During Install or Repair
000-7840	N9187	Johann Dr	Residential	N9187 Johann Dr	N	C	N	1"	1993	C	1"	5/20/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/1994	Visual Insp During Install or Repair
000-7850	N9193	Johann Dr	Residential	N9193 Johann Dr	N	C	N	1"	1993	C	1"	5/20/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/1994	Visual Insp During Install or Repair
000-7860	N9201	Johann Dr	Residential	N9201 Johann Dr	N	C	N	1"	1993	C	1"	5/4/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	5/4/1994	Visual Insp During Install or Repair
000-7870	3725	S Johann Dr	Residential	3725 S Johann Dr	N	C	N	1"	1993	C	1"	3/18/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/18/1994	Visual Insp During Install or Repair
000-7880	3717	S Johann Dr	Residential	3717 S Johann Dr	N	C	N	1"	1993	C	1"	12/28/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	12/28/1994	Visual Insp During Install or Repair
000-7890	3709	S Johann Dr	Residential	3709 S Johann Dr	N	C	N	1"	1993	C	1"	4/21/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/1995	Visual Insp During Install or Repair
000-7900	3701	S Johann Dr	Residential	3701 S Johann Dr	N	C	N	1"	1993	C	1"	4/21/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/1995	Visual Insp During Install or Repair
000-7910	1709	E Hulke Dr	Residential	1709 E Hulke Dr	N	C	N	1"	1993	C	1"	2/12/1997	SF	UNK	C	1997	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/1997	Visual Insp During Install or Repair
000-7920	1707	E Hulke Dr	Residential	1707 E Hulke Dr	N	C	N	1"	1993	C	1"	2/12/1997	SF	UNK	C	1997	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/199	

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-8340	W6856	Basswood Ln	Residential	W6856 Basswood Ln	N	C	N	1"	1998	P	1"	4/27/2001	SF	N	C	post-1984	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2022	Cross Connection Survey
000-8350	W6862	Basswood Ln	Residential	W6862 Basswood Ln	N	C	N	1"	1998	P	1"	6/25/1999	SF	N	C	post-1984	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2020	Cross Connection Survey
000-8360	N9161	Mountainash Ln	Residential	N9161 Mountainash Ln	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/3/2023	Cross Connection Survey
000-8370	N9155	Mountainash Ln	Residential	N9155 Mountainash Ln	N	C	N	1"	1998	P	1"	1998	SF	N	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2024	Cross Connection Survey
000-8380	N9149	Mountainash Ln	Residential	N9149 Mountainash Ln	N	C	N	1"	1998	P	1"	7/6/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2020	Cross Connection Survey
000-8390	N9143	Mountainash Ln	Residential	N9143 Mountainash Ln	N	C	N	1"	1998	P	1"	6/25/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
000-8400	N9135	Mountainash Ln	Residential	N9135 Mountainash Ln	N	C	N	1"	1998	P	1"	6/22/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/25/2020	Cross Connection Survey
000-8410	N9129	Mountainash Ln	Residential	N9129 Mountainash Ln	N	C	N	1"	1998	P	1"	6/12/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/7/2022	Cross Connection Survey
000-8420	N9123	Mountainash Ln	Residential	N9123 Mountainash Ln	N	C	N	1"	1998	P	1"	5/8/2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/3/2023	Cross Connection Survey
000-8430	N9115	Mountainash Ln	Residential	N9115 Mountainash Ln	N	C	N	1"	1998	P	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/1999	Visual Insp During Install or Repair
000-8440	W6863	Alder Way	Residential	W6863 Alder Way	N	C	N	1"	1998	P	1"	2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2024	Cross Connection Survey
000-8450	W6855	Alder Way	Residential	W6855 Alder Way	N	C	N	1"	1998	P	1"	12/7/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2023	Cross Connection Survey
000-8460	W6849	Alder Way	Residential	W6849 Alder Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2023	Cross Connection Survey
000-8470	W6841	Alder Way	Residential	W6841 Alder Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2023	Cross Connection Survey
000-8480	W6835	Alder Way	Residential	W6835 Alder Way	N	C	N	1"	1998	P	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
000-8490	W6827	Alder Way	Residential	W6827 Alder Way	N	C	N	1"	1998	P	1"	11/30/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
000-8500	W6819	Alder Way	Residential	W6819 Alder Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/22/2023	Cross Connection Survey
000-8510	W6813	Alder Way	Residential	W6813 Alder Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2023	Cross Connection Survey
000-8520	N9118	Cherry Meadow Dr	Residential	N9118 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/18/2020	Cross Connection Survey
000-8530	N9126	Cherry Meadow Dr	Residential	N9126 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	11/20/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2020	Cross Connection Survey
000-8540	N9132	Cherry Meadow Dr	Residential	N9132 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	11/15/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
000-8550	N9138	Cherry Meadow Dr	Residential	N9138 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2023	Cross Connection Survey
000-8560	N9146	Cherry Meadow Dr	Residential	N9146 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	2002	SF	N	C	2002	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/18/2024	Cross Connection Survey
000-8570	W6820	Alder Way	Residential	W6820 Alder Way	N	C	N	1"	1998	P	1"	6/2/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/22/2022	Cross Connection Survey
000-8580	W6828	Alder Way	Residential	W6828 Alder Way	N	C	N	1"	1998	P	1"	12/12/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2020	Cross Connection Survey
000-8590	W6836	Alder Way	Residential	W6836 Alder Way	N	C	N	1"	1998	P	1"	8/30/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2022	Cross Connection Survey
000-8600	W6844	Alder Way	Residential	W6844 Alder Way	N	C	N	1"	1998	P	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2020	Cross Connection Survey
000-8610	W6852	Alder Way	Residential	W6852 Alder Way	N	C	N	1"	1998	P	1"	2/26/2001	SF	UNK	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2001	Visual Insp During Install or Repair
000-8620	W6853	Willowglen Way	Residential	W6853 Willowglen Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2023	Cross Connection Survey
000-8630	W6845	Willowglen Way	Residential	W6845 Willowglen Way	N	C	N	1"	1998	P	1"	5/5/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2020	Cross Connection Survey
000-8640	W6837	Willowglen Way	Residential	W6837 Willowglen Way	N	C	N	1"	1998	P	1"	1/26/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/2/2023	Cross Connection Survey
000-8650	W6829	Willowglen Way	Residential	W6829 Willowglen Way	N	C	N	1"	1998	P	1"	4/19/2004	SF	UNK	C	2004	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/19/2004	Visual Insp During Install or Repair
000-8660	W6821	Willowglen Way	Residential	W6821 Willowglen Way	N	C	N	1"	1998	P	1"	1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2023	Cross Connection Survey
000-8670	W6822	Willowglen Way	Residential	W6822 Willowglen Way	N	C	N	1"	1998	P	1"	4/11/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2022	Cross Connection Survey
000-8680	W6830	Willowglen Way	Residential	W6830 Willowglen Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2023	Cross Connection Survey
000-8690	W6838	Willowglen Way	Residential	W6838 Willowglen Way	N	C	N	1"	1998	P	1"	2/10/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2024	Cross Connection Survey
000-8700	W6846	Willowglen Way	Residential	W6846 Willowglen Way	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/2023	Cross Connection Survey
000-8710	W6854	Willowglen Way	Residential	W6854 Willowglen Way	N	C	N	1"	1998	P	1"	5/5/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/24/2020	Cross Connection Survey
000-8720	N9158	Mountainash Ln	Residential	N9158 Mountainash Ln	N	C	N	1"	1998	P	1"	12/1/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2020	Cross Connection Survey
000-8730	W6847	Basswood Ln	Residential	W6847 Basswood Ln	N	C	N	1"	1998	P	1"	1998	SF	N	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	9/3/2021	Cross Connection Survey
000-8740	W6839	Basswood Ln	Residential	W6839 Basswood Ln	N	C	N	1"	1998	P	1"	1998	SF	N	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
000-8750	W6831	Basswood Ln	Residential	W6831 Basswood Ln	N	C	N	1"	1998	P	1"	1998	SF	N	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	9/8/2021	Cross Connection Survey
000-8760	W6823	Basswood Ln	Residential	W6823 Basswood Ln	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/2024	Cross Connection Survey
000-8770	N9160	Cherry Meadow Dr	Residential	N9160 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/26/2023	Cross Connection Survey
000-8780	N9168	Cherry Meadow Dr	Residential	N9168 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	6/4/1999	SF	Y	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2020	Cross Connection Survey
000-8790	N9174	Cherry Meadow Dr	Residential	N9174 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	7/7/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2020	Cross Connection Survey
000-8810	N9186	Cherry Meadow Dr	Residential	N9186 Cherry Meadow Dr	N	C	N	1"	1998	P	1"	2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2023	Cross Connection Survey
000-8820	W6818	Hazelnut Ln	Residential	W6818 Hazelnut Ln	N	C	N	1"	1998	P	1"	10/10/1999	SF	N	O	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2020	Cross Connection Survey
000-8830	W6826	Hazelnut Ln	Residential	W6826 Hazelnut Ln	N	C	N	1"	1998	P	1"	7/19/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/10/2020	Cross Connection Survey
000-8840	W6834	Hazelnut Ln	Residential	W6834 Hazelnut Ln	N	C	N	1"	1998	P	1"	10/21/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
000-8850	W6842	Hazelnut Ln	Residential	W6842 Hazelnut Ln	N	C	N	1"	1998	P	1"	12/1/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2020	Cross Connection Survey
000-8860	W6850	Hazelnut Ln	Residential	W6850 Hazelnut Ln	N	C	N	1"	1998	P	1"	7/28/1999	SF	UNK	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	7/28/1999	Visual Insp During Install or Repair
000-8870	W6858	Hazelnut Ln	Residential	W6858 Hazelnut Ln	N	C	N	1"	1998	P	1"	9/10/1999	SF	N	O	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2020	Cross Connection Survey
000-8880	W6864	Hazelnut Ln	Residential	W6864 Hazelnut Ln	N	C	N	1"	1998	P	1"	7/12/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
000-8890	W6870	Hazelnut Ln	Residential	W6870 Hazelnut Ln	N	C	N	1"	1998	P	1"	7/21/1999	SF	N	C	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2020	Cross Connection Survey
000-8950	N9217	Telulah Ave	Commercial	N9217 Telulah Ave	N	C	N	1"	1995	P	1"	6/28/2001	NONRES	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/2023	Cross Connection Survey
000-9010	W6728	Jordan St	Residential	W6728 Jordan St	N	C	N	1"	1995	P	1"	9/6/1995	SF	UNK	C	1995	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/6/1995	Visual Insp During Install or Repair
000-9020	W6736	Jordan St	Residential	W6736 Jordan St	N	C	N	1"	1993	C	1"	9/22/1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	9/22/1995	



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
000-9380	N9166	Jordan St	Residential	N9166 Jordan St	N	C	N	1"	1995	P	1"	4/28/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2024	Cross Connection Survey
000-9390	N9162	Jordan St	Residential	N9162 Jordan St	N	C	N	1"	1995	C	1"	6/12/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/1997	Visual Insp During Install or Repair
000-9400	N9158	Jordan St	Residential	N9158 Jordan St	N	C	N	1"	1995	C	1"	5/27/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	5/27/1997	Visual Insp During Install or Repair
000-9410	N9154	Jordan St	Residential	N9154 Jordan St	N	C	N	1"	1995	C	1"	4/10/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/10/1998	Visual Insp During Install or Repair
000-9420	N9153	Jordan St	Residential	N9153 Jordan St	N	C	N	1"	1995	C	1"	2/3/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/1998	Visual Insp During Install or Repair
000-9430	N9157	Jordan St	Residential	N9157 Jordan St	N	C	N	1"	1995	C	1"	9/25/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/25/1997	Visual Insp During Install or Repair
000-9440	N9161	Jordan St	Residential	N9161 Jordan St	N	C	N	1"	1995	C	1"	10/22/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	10/22/1998	Visual Insp During Install or Repair
000-9450	N9165	Jordan St	Residential	N9165 Jordan St	N	C	N	1"	1995	C	1"	6/30/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	6/30/1998	Visual Insp During Install or Repair
000-9460	N9169	Jordan St	Residential	N9169 Jordan St	N	C	N	1"	1995	C	1"	2/3/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/1998	Visual Insp During Install or Repair
000-9470	N9171	Jordan St	Residential	N9171 Jordan St	N	C	N	1"	1995	C	1"	11/10/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/10/1998	Visual Insp During Install or Repair
000-9480	N9175	Jordan St	Residential	N9175 Jordan St	N	C	N	1"	1995	C	1"	11/20/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/20/1997	Visual Insp During Install or Repair
000-9490	N9185	Jordan St	Residential	N9185 Jordan St	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2023	Cross Connection Survey
000-9500	N9208	Cedar Hollow Ct	Residential	N9208 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	9/23/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/1998	Visual Insp During Install or Repair
000-9510	N9200	Cedar Hollow Ct	Residential	N9200 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	9/16/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/16/1998	Visual Insp During Install or Repair
000-9520	N9194	Cedar Hollow Ct	Residential	N9194 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	2/12/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/1997	Visual Insp During Install or Repair
000-9530	N9188	Cedar Hollow Ct	Residential	N9188 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	9/30/1996	SF	UNK	C	1996	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/30/1996	Visual Insp During Install or Repair
000-9540	N9180	Cedar Hollow Ct	Residential	N9180 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	5/5/1999	SF	UNK	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	5/5/1999	Visual Insp During Install or Repair
000-9550	N9172	Cedar Hollow Ct	Residential	N9172 Cedar Hollow Ct	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
000-9560	N9164	Cedar Hollow Ct	Residential	N9164 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	9/23/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/1998	Visual Insp During Install or Repair
000-9570	N9160	Cedar Hollow Ct	Residential	N9160 Cedar Hollow Ct	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2024	Cross Connection Survey
000-9580	N9163	Cedar Hollow Ct	Residential	N9163 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	11/10/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/20/2024	Cross Connection Survey
000-9590	N9171	Cedar Hollow Ct	Residential	N9171 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	11/12/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/12/1998	Visual Insp During Install or Repair
000-9600	N9179	Cedar Hollow Ct	Residential	N9179 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	12/9/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	12/9/1997	Visual Insp During Install or Repair
000-9610	N9187	Cedar Hollow Ct	Residential	N9187 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	8/26/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	8/26/1997	Visual Insp During Install or Repair
000-9620	N9193	Cedar Hollow Ct	Residential	N9193 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	11/26/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/26/1997	Visual Insp During Install or Repair
000-9630	N9199	Cedar Hollow Ct	Residential	N9199 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	2/3/1998	SF	UNK	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/1998	Visual Insp During Install or Repair
000-9640	N9207	Cedar Hollow Ct	Residential	N9207 Cedar Hollow Ct	N	C	N	1"	1995	C	1"	7/29/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	7/29/1997	Visual Insp During Install or Repair
000-9650	N9204	Johann Dr	Residential	N9204 Johann Dr	N	C	N	1"	1995	C	1"	3/4/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/1997	Visual Insp During Install or Repair
000-9660	N9196	Johann Dr	Residential	N9196 Johann Dr	N	C	N	1"	1992	C	1"	3/4/1997	SF	UNK	C	1997	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/1997	Visual Insp During Install or Repair
000-9670	N9190	Johann Dr	Residential	N9190 Johann Dr	N	C	N	1"	1992	C	1"	9/30/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	9/30/1996	Visual Insp During Install or Repair
000-9680	N9184	Johann Dr	Residential	N9184 Johann Dr	N	C	N	1"	1992	C	1"	8/15/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/1996	Visual Insp During Install or Repair
000-9690	N9178	Johann Dr	Residential	N9178 Johann Dr	N	C	N	1"	1992	C	1"	8/15/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/1996	Visual Insp During Install or Repair
000-9700	N9170	Johann Dr	Residential	N9170 Johann Dr	N	C	N	1"	1992	C	1"	7/26/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	7/26/1996	Visual Insp During Install or Repair
000-9710	N9162	Johann Dr	Residential	N9162 Johann Dr	N	C	N	1"	1992	C	1"	9/30/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	9/30/1996	Visual Insp During Install or Repair
000-9720	N9154	Johann Dr	Residential	N9154 Johann Dr	N	C	N	1"	1992	C	1"	10/29/1996	SF	UNK	C	1996	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/1996	Visual Insp During Install or Repair
000-9730	3913	S Jordan St	Residential	3913 S Jordan St	N	C	N	1"	1993	P	1.25"	2001	SF	N	C	2001	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/12/2024	Cross Connection Survey
000-9740	3916	S Jordan St	Residential	3916 S Jordan St	N	C	N	1"	1993	P	1"	Post - 1984	SF	N	C	Post - 1984	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2024	Cross Connection Survey
000-9750	3924	S Jordan St	Residential	3924 S Jordan St	N	C	N	1"	1993	P	1.25"	2003	SF	N	C	2003	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
000-9760	3933	S Jordan St	Residential	3933 S Jordan St	N	C	N	1"	1995	P	1"	12/23/2002	SF	N	C	2002	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/13/2024	Cross Connection Survey
000-9770	1905	E Jordan St	Residential	1905 E Jordan St	N	P	N	1"	1995	P	1"	3/15/2004	SF	UNK	C	2004	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2004	Visual Insp During Install or Repair
000-9780	1901	E Jordan St	Residential	1901 E Jordan St	N	C	N	1"	1995	P	1.25"	2002	SF	N	C	2002	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2024	Cross Connection Survey
000-9790	1902	E Lydia Ln	Residential	1902 E Lydia Ln	N	C	N	1"	1995	P	1.25"	2002	SF	N	C	2002	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2024	Cross Connection Survey
000-9800	1910	E Lydia Ln	Residential	1910 E Lydia Ln	N	C	N	1"	1995	P	1"	4/8/2002	SF	N	C	2002	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/16/2024	Cross Connection Survey
000-9810	1918	E Lydia Ln	Residential	1918 E Lydia Ln	N	C	N	1"	1995	P	1"	3/10/2003	SF	UNK	C	2003	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/2003	Visual Insp During Install or Repair
000-9820	1919	E Lydia Ln	Residential	1919 E Lydia Ln	N	C	N	1"	1995	P	1"	3/1/2004	SF	UNK	C	2004	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/1/2004	Visual Insp During Install or Repair
000-9830	1911	E Lydia Ln	Residential	1911 E Lydia Ln	N	C	N	1"	1995	P	1.25"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2024	Cross Connection Survey
000-9840	1903	E Lydia Ln	Residential	1903 E Lydia Ln	N	C	N	1"	1995	P	1"	8/12/2003	SF	UNK	C	2003	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2003	Visual Insp During Install or Repair
000-9850	N9224	Christopher Ln	Residential	N9224 Christopher Ln	N	C	N	1"	1995	P	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2024	Cross Connection Survey
000-9860	N9218	Christopher Ln	Residential	N9218 Christopher Ln	N	C	N	1"	1995	P	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
000-9870	N9212	Christopher Ln	Residential	N9212 Christopher Ln	N	C	N	1"	1995	P	1"	2007	SF	N	C	2007	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/2/2024	Cross Connection Survey
000-9880	N9206	Christopher Ln	Residential	N9206 Christopher Ln	N	C	N	1"	1995	P	1"	1/21/2003	SF	UNK	C	2003	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/21/2003	Visual Insp During Install or Repair
000-9890	N9205	Christopher Ln	Residential	N9205 Christopher Ln	N	C	N	1"	1995	P	1"	2002	SF	N	C	2002	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2024	Cross Connection Survey
000-9900	N9211	Christopher Ln	Residential	N9211 Christopher Ln	N	C	N	1"	1995	C	1"	2007	SF	N	C	2007	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
000-9910	N9217	Christopher Ln	Residential	N9217 Christopher Ln	N	C	N	1"	1995	P	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2023	Cross Connection Survey
000-9920	N9223	Christopher Ln	Residential	N9223 Christopher Ln	N	C	N	1"	1995	P	1"	2000	SF	N	C	Post-1984	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	9/9/2021	Cross Connection Survey
001-0001	1185	Southfield Dr	Residential	1185 Southfield Dr	N	C	N	1"	1992	C	1"	1995	SF	UNK	C	1995	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/20/1995	Visual Insp During Install or Repair
001-0002	1175	Southfield Dr	Residential	1175 Southfield Dr	N	C	N	1"	1993	C	1"	12/1/1994	SF	UNK	C	1994	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	12/1/1994	Visual Insp During Install or Repair
001-0003	1165	Southfield Dr	Residential	1165 Southfield Dr	N	C	N	1"	1993	P	1"	11/2/1999	SF	N	C	1999	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/2020	Cross Connection Survey

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0039	2048	Dreamfield Ln	Residential	2048 Dreamfield Ln	N	C	N	1"	1993	P	1"	3/4/1997	SF	UNK	C	1997	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/1997	Visual Insp During Install or Repair
001-0040	1180	Southfield Dr	Residential	1180 Southfield Dr	N	C	N	1"	1993	C	1"	9/11/1996	SF	UNK	C	1996	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	9/11/1996	Visual Insp During Install or Repair
001-0041	1118	Fieldview Dr	Residential	1118 Fieldview Dr	N	C	N	1"	1993	P	1.25"	5/18/2010	SF	N	O	2010	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/7/2022	Cross Connection Survey
001-0042	1124	Fieldview Dr	Residential	1124 Fieldview Dr	N	C	N	1"	1993	P	1.25"	5/18/2010	SF	N	O	2010	Installation Record	Y	1993	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/2022	Cross Connection Survey
001-0050	2324	Sugarbridge Ct	Residential	2324 Sugarbridge Ct	N	C	N	1"	1997	P	1"	8/21/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/1997	Visual Insp During Install or Repair
001-0051	2320	Sugarbridge Ct	Residential	2320 Sugarbridge Ct	N	C	N	1"	1997	P	1"	7/8/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	7/8/1997	Visual Insp During Install or Repair
001-0052	2316	Sugarbridge Ct	Residential	2316 Sugarbridge Ct	N	C	N	1"	1997	P	1"	12/1/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	12/1/1997	Visual Insp During Install or Repair
001-0053	2312	Sugarbridge Ct	Residential	2312 Sugarbridge Ct	N	C	N	1"	1997	P	1"	2/3/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/1998	Visual Insp During Install or Repair
001-0054	2308	Sugarbridge Ct	Residential	2308 Sugarbridge Ct	N	C	N	1"	1997	P	1"	9/19/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/19/1997	Visual Insp During Install or Repair
001-0055	2304	Sugarbridge Ct	Residential	2304 Sugarbridge Ct	N	C	N	1"	1997	P	1"	9/19/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/19/1997	Visual Insp During Install or Repair
001-0056	2305	Sugarbridge Ct	Residential	2305 Sugarbridge Ct	N	C	N	1"	1997	P	1"	11/5/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	11/5/1998	Visual Insp During Install or Repair
001-0057	2309	Sugarbridge Ct	Residential	2309 Sugarbridge Ct	N	C	N	1"	1997	P	1"	7/17/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	7/17/1998	Visual Insp During Install or Repair
001-0058	2313	Sugarbridge Ct	Residential	2313 Sugarbridge Ct	N	C	N	1"	1997	P	1"	2001	SF	N	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/2024	Cross Connection Survey
001-0059	2317	Sugarbridge Ct	Residential	2317 Sugarbridge Ct	N	C	N	1"	1997	P	1"	2/22/2000	SF	N	C	2000	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	4/15/2024	Cross Connection Survey
001-0060	2325	Sugarbridge Ct	Residential	2325 Sugarbridge Ct	N	C	N	1"	1997	P	1"	7/20/1999	SF	N	C	1999	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	2/18/2020	Cross Connection Survey
001-0061	1118	Stillmeadow Ln	Residential	1118 Stillmeadow Ln	N	C	N	1"	1997	P	1"	7/20/1999	SF	N	C	1999	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/2020	Cross Connection Survey
001-0062	1114	Stillmeadow Ln	Residential	1114 Stillmeadow Ln	N	C	N	1"	1997	P	1"	6/1/2001	SF	N	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	7/11/2022	Cross Connection Survey
001-0063	1110	Stillmeadow Ln	Residential	1110 Stillmeadow Ln	N	C	N	1"	1997	P	1"	6/1/2001	SF	N	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2023	Cross Connection Survey
001-0064	1106	Stillmeadow Ln	Residential	1106 Stillmeadow Ln	N	C	N	1"	1997	C	1"	2000	SF	N	C	2000	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/2024	Cross Connection Survey
001-0065	1102	Stillmeadow Ln	Residential	1102 Stillmeadow Ln	N	C	N	1"	1997	P	1"	2000	SF	N	C	2000	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2024	Cross Connection Survey
001-0066	2314	Bittersweet Ct	Residential	2314 Bittersweet Ct	N	C	N	1"	1997	P	1"	10/5/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/1998	Visual Insp During Install or Repair
001-0067	2310	Bittersweet Ct	Residential	2310 Bittersweet Ct	N	C	N	1"	1997	P	1"	12/2/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	12/2/1998	Visual Insp During Install or Repair
001-0068	2306	Bittersweet Ct	Residential	2306 Bittersweet Ct	N	C	N	1"	1997	P	1"	9/28/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/28/1998	Visual Insp During Install or Repair
001-0069	2302	Bittersweet Ct	Residential	2302 Bittersweet Ct	N	C	N	1"	1997	P	1"	9/28/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/28/1998	Visual Insp During Install or Repair
001-0070	2303	Bittersweet Ct	Residential	2303 Bittersweet Ct	N	C	N	1"	1997	P	1"	7/17/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	7/17/1998	Visual Insp During Install or Repair
001-0071	2307	Bittersweet Ct	Residential	2307 Bittersweet Ct	N	C	N	1"	1997	P	1"	7/17/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	7/17/1998	Visual Insp During Install or Repair
001-0072	2311	Bittersweet Ct	Residential	2311 Bittersweet Ct	N	C	N	1"	1997	P	1"	12/7/2000	SF	UNK	C	2000	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	12/7/2000	Visual Insp During Install or Repair
001-0073	2315	Bittersweet Ct	Residential	2315 Bittersweet Ct	N	C	N	1"	1997	P	1"	12/7/2000	SF	N	C	2002	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	4/23/2024	Cross Connection Survey
001-0074	1094	Stillmeadow Ln	Residential	1094 Stillmeadow Ln	N	C	N	1"	1997	P	1"	2002	SF	N	C	2002	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2023	Cross Connection Survey
001-0075	1090	Stillmeadow Ln	Residential	1090 Stillmeadow Ln	N	C	N	1"	1997	P	1"	2001	SF	N	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2023	Cross Connection Survey
001-0077	1087	Stillmeadow Ln	Residential	1087 Stillmeadow Ln	N	C	N	1"	1997	P	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	2/10/2020	Cross Connection Survey
001-0078	1091	Stillmeadow Ln	Residential	1091 Stillmeadow Ln	N	C	N	1"	1997	P	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2020	Cross Connection Survey
001-0079	1095	Stillmeadow Ln	Residential	1095 Stillmeadow Ln	N	C	N	1"	1997	P	1"	2/15/2001	SF	N	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	4/1/2024	Cross Connection Survey
001-0080	1099	Stillmeadow Ln	Residential	1099 Stillmeadow Ln	N	C	N	1"	1997	P	1"	2/9/2001	SF	UNK	C	2001	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	2/9/2001	Visual Insp During Install or Repair
001-0081	1103	Stillmeadow Ln	Residential	1103 Stillmeadow Ln	N	C	N	1"	1997	P	1"	12/23/2003	SF	UNK	C	2003	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	12/23/2003	Visual Insp During Install or Repair
001-0082	1107	Stillmeadow Ln	Residential	1107 Stillmeadow Ln	N	C	N	1"	1997	P	1"	12/15/2003	SF	UNK	C	2003	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	12/15/2003	Visual Insp During Install or Repair
001-0083	1111	Stillmeadow Ln	Residential	1111 Stillmeadow Ln	N	C	N	1"	1997	P	1"	9/14/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/14/1998	Visual Insp During Install or Repair
001-0084	1115	Stillmeadow Ln	Residential	1115 Stillmeadow Ln	N	C	N	1"	1997	P	1"	9/14/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	9/14/1998	Visual Insp During Install or Repair
001-0085	1119	Stillmeadow Ln	Residential	1119 Stillmeadow Ln	N	C	N	1"	1997	P	1"	11/5/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	11/5/1998	Visual Insp During Install or Repair
001-0086	1123	Stillmeadow Ln	Residential	1123 Stillmeadow Ln	N	C	N	1"	1997	P	1"	11/12/1998	SF	UNK	C	1998	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	11/12/1998	Visual Insp During Install or Repair
001-0101	1435	Southfield Dr	Residential	1435 Southfield Dr	N	C	N	1"	1994	P	1.25"	9/23/2014	SF	UNK	C	9/23/2014	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/2014	Visual Insp During Install or Repair
001-0102	1425	Southfield Dr	Residential	1425 Southfield Dr	N	C	N	1"	1994	P	1"	2/3/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/1998	Visual Insp During Install or Repair
001-0103	1417	Southfield Dr	Residential	1417 Southfield Dr	N	C	N	1"	1994	P	1"	9/23/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/1998	Visual Insp During Install or Repair
001-0104	1409	Southfield Dr	Residential	1409 Southfield Dr	N	C	N	1"	1994	P	1"	9/23/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/1998	Visual Insp During Install or Repair
001-0105	1401	Southfield Dr	Residential	1401 Southfield Dr	N	C	N	1"	1994	C	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2024	Cross Connection Survey
001-0106	1410	Stadler Ct	Residential	1410 Stadler Ct	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2023	Cross Connection Survey
001-0107	1420	Stadler Ct	Residential	1420 Stadler Ct	N	C	N	1"	1994	P	1"	9/30/1996	SF	UNK	C	9/30/1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/30/1996	Visual Insp During Install or Repair
001-0108	1428	Stadler Ct	Residential	1428 Stadler Ct	N	C	N	1"	1994	P	1.25"	2/22/2022	SF	UNK	O	2/22/2022	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/22/2022	Visual Insp During Install or Repair
001-0109	1435	Stadler Ct	Residential	1435 Stadler Ct	N	C	N	1"	1994	P	1"	2007	SF	N	C	2007	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/19/2023	Cross Connection Survey
001-0110	1427	Stadler Ct	Residential	1427 Stadler Ct	N	C	N	1"	1994	P	1"	7/26/2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2023	Cross Connection Survey
001-0111	1419	Stadler Ct	Residential	1419 Stadler Ct	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/16/2023	Cross Connection Survey
001-0112	1409	Stadler Ct	Residential	1409 Stadler Ct	N	C	N	1"	1994	P	1"	5/28/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	5/28/1997	Visual Insp During Install or Repair
001-0113	2150	Moonlight Ct	Residential	2150 Moonlight Ct	N	C	N	1"	1994	P	1"	3/12/2004	SF	UNK	C	2004	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2004	Visual Insp During Install or Repair
001-0114	2158	Moonlight Ct	Residential	2158 Moonlight Ct	N	C	N	1"	1994	P	1"	3/8/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
001-0115	2166	Moonlight Ct	Residential	2166 Moonlight Ct	N	C	N	1"	1994	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-0116	2159	Moonlight Ct	Residential	2159 Moonlight Ct	N	C	N	1"	1994	C	1"	2/5/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/1996	Visual Insp During Install or Repair
001-0117	2151	Moonlight Ct	Residential	2151 Moonlight Ct	N	C	N	1"	1994	P	1"	1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/2/2023	Cross Connection Survey
001-0118	1351	Applewood Dr	Residential	1351 Applewood Dr	N	C	N	1																



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0154	1350	Southfield Dr	Residential	1350 Southfield Dr	N	C	N	1"	1994	C	1"	1995	SF	UNK	C	1995	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	8/16/1995	Visual Insp During Install or Repair
001-0155	1358	Southfield Dr	Residential	1358 Southfield Dr	N	C	N	1"	1994	P	1"	8/21/2003	SF	UNK	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/2003	Visual Insp During Install or Repair
001-0156	1406	Southfield Dr	Residential	1406 Southfield Dr	N	C	N	1"	1994	P	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/16/2023	Cross Connection Survey
001-0157	1408	Southfield Dr	Residential	1408 Southfield Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2024	Cross Connection Survey
001-0158	1416	Southfield Dr	Residential	1416 Southfield Dr	N	C	N	1"	1994	C	1"	4/18/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/1996	Visual Insp During Install or Repair
001-0159	1424	Southfield Dr	Residential	1424 Southfield Dr	N	C	N	1"	1994	C	1"	4/18/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/1996	Visual Insp During Install or Repair
001-0160	1434	Southfield Dr	Residential	1434 Southfield Dr	N	C	N	1"	1994	C	1"	4/18/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/1996	Visual Insp During Install or Repair
001-0161	1335	Tuckaway Ct	Residential	1335 Tuckaway Ct	N	C	N	1"	1995	P	1"	7/7/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2020	Cross Connection Survey
001-0162	1341	Tuckaway Ct	Residential	1341 Tuckaway Ct	N	C	N	1"	1995	C	1"	3/11/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2020	Cross Connection Survey
001-0163	1347	Tuckaway Ct	Residential	1347 Tuckaway Ct	N	C	N	1"	1995	P	1"	2/15/2000	SF	UNK	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2000	Visual Insp During Install or Repair
001-0164	1351	Tuckaway Ct	Residential	1351 Tuckaway Ct	N	C	N	1"	1995	P	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2024	Cross Connection Survey
001-0165	1355	Tuckaway Ct	Residential	1355 Tuckaway Ct	N	C	N	1"	1995	P	1"	2/13/2004	SF	UNK	C	2004	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2004	Visual Insp During Install or Repair
001-0166	1356	Tuckaway Ct	Residential	1356 Tuckaway Ct	N	C	N	1"	1995	P	1"	1/8/2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2022	Cross Connection Survey
001-0167	1350	Tuckaway Ct	Residential	1350 Tuckaway Ct	N	C	N	1"	1995	P	1.25"	6/5/2019	SF	UNK	C	2019	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	6/5/2019	Visual Insp During Install or Repair
001-0168	1344	Tuckaway Ct	Residential	1344 Tuckaway Ct	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2024	Cross Connection Survey
001-0169	1338	Tuckaway Ct	Residential	1338 Tuckaway Ct	N	C	N	1"	1995	P	1"	11/4/1998	SF	UNK	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	11/4/1998	Visual Insp During Install or Repair
001-0170	2156	Cottonwood Dr	Residential	2156 Cottonwood Dr	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2024	Cross Connection Survey
001-0171	2150	Cottonwood Dr	Residential	2150 Cottonwood Dr	N	C	N	1"	1995	C	1"	11/17/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2020	Cross Connection Survey
001-0172	1269	Southfield Dr	Residential	1269 Southfield Dr	N	C	N	1"	1994	P	1.25"	2000	SF	Y	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-0173	1278	Southfield Dr	Residential	1278 Southfield Dr	N	C	N	1"	1994	C	1"	8/7/1997	SF	UNK	C	1997	Installation Record	Y	1997	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/1997	Visual Insp During Install or Repair
001-0174	1270	Southfield Dr	Residential	1270 Southfield Dr	N	C	N	1"	1994	P	1"	11/19/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	11/19/1998	Visual Insp During Install or Repair
001-0175	1260	Southfield Dr	Residential	1260 Southfield Dr	N	C	N	1"	1994	C	1"	11/4/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	11/4/1996	Visual Insp During Install or Repair
001-0176	1250	Southfield Dr	Residential	1250 Southfield Dr	N	C	N	1"	1994	P	1"	1994	SF	N	C	Post-1984	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/2021	Cross Connection Survey
001-0177	1242	Southfield Dr	Residential	1242 Southfield Dr	N	C	N	1"	1994	C	1"	2/12/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/1997	Visual Insp During Install or Repair
001-0178	1234	Southfield Dr	Residential	1234 Southfield Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/12/2024	Cross Connection Survey
001-0179	1226	Southfield Dr	Residential	1226 Southfield Dr	N	C	N	1"	1994	P	1"	10/22/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	10/22/1998	Visual Insp During Install or Repair
001-0180	1218	Southfield Dr	Residential	1218 Southfield Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2024	Cross Connection Survey
001-0181	1210	Southfield Dr	Residential	1210 Southfield Dr	N	C	N	1"	1994	P	1"	11/19/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	11/19/1998	Visual Insp During Install or Repair
001-0182	1202	Southfield Dr	Residential	1202 Southfield Dr	N	C	N	1"	1994	C	1"	1994	SF	N	C	Post-1984	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/29/2021	Cross Connection Survey
001-0183	1201	Southfield Dr	Residential	1201 Southfield Dr	N	C	N	1"	1994	P	1"	12/22/1998	SF	UNK	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	12/22/1998	Visual Insp During Install or Repair
001-0184	1209	Southfield Dr	Residential	1209 Southfield Dr	N	C	N	1"	1994	C	1"	8/7/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/1997	Visual Insp During Install or Repair
001-0185	1217	Southfield Dr	Residential	1217 Southfield Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2024	Cross Connection Survey
001-0186	1225	Southfield Dr	Residential	1225 Southfield Dr	N	C	N	1"	1994	C	1"	6/26/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	6/26/1997	Visual Insp During Install or Repair
001-0187	1233	Southfield Dr	Residential	1233 Southfield Dr	N	C	N	1"	1994	C	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
001-0188	1241	Southfield Dr	Residential	1241 Southfield Dr	N	C	N	1"	1994	C	1"	8/7/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/1997	Visual Insp During Install or Repair
001-0189	1253	Southfield Dr	Residential	1253 Southfield Dr	N	C	N	1"	1994	P	1.25"	3/30/2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2023	Cross Connection Survey
001-0190	1250	Chelsea Ct	Residential	1250 Chelsea Ct	N	C	N	1"	1999	P	1"	2002	SF	N	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2024	Cross Connection Survey
001-0191	1242	Chelsea Ct	Residential	1242 Chelsea Ct	N	C	N	1"	1999	P	1"	2002	SF	N	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2024	Cross Connection Survey
001-0192	1234	Chelsea Ct	Residential	1234 Chelsea Ct	N	C	N	1"	1999	P	1"	8/13/2001	SF	N	O	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2022	Cross Connection Survey
001-0193	1226	Chelsea Ct	Residential	1226 Chelsea Ct	N	C	N	1"	1999	P	1"	6/4/2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	9/27/2022	Cross Connection Survey
001-0194	1218	Chelsea Ct	Residential	1218 Chelsea Ct	N	C	N	1"	1999	P	1"	4/4/2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2022	Cross Connection Survey
001-0195	1210	Chelsea Ct	Residential	1210 Chelsea Ct	N	C	N	1"	1999	P	1"	8/13/2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2023	Cross Connection Survey
001-0196	1202	Chelsea Ct	Residential	1202 Chelsea Ct	N	C	N	1"	1999	P	1"	8/22/2001	SF	UNK	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	8/22/2001	Visual Insp During Install or Repair
001-0197	1201	Chelsea Ct	Residential	1201 Chelsea Ct	N	C	N	1"	1999	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-0198	1209	Chelsea Ct	Residential	1209 Chelsea Ct	N	C	N	1"	1999	P	1"	2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2024	Cross Connection Survey
001-0199	1217	Chelsea Ct	Residential	1217 Chelsea Ct	N	C	N	1"	1999	P	1"	2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/26/2024	Cross Connection Survey
001-0200	1225	Chelsea Ct	Residential	1225 Chelsea Ct	N	C	N	1"	1999	P	1"	7/25/2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	8/16/2022	Cross Connection Survey
001-0201	2133	Deer Haven Dr	Residential	2133 Deer Haven Dr	N	C	N	1"	1999	P	1"	1/15/2003	SF	UNK	C	2003	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/15/2003	Visual Insp During Install or Repair
001-0202	2141	Deer Haven Dr	Residential	2141 Deer Haven Dr	N	C	N	1"	1999	P	1"	9/22/2004	SF	UNK	C	2004	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	9/22/2004	Visual Insp During Install or Repair
001-0203	2149	Deer Haven Dr	Residential	2149 Deer Haven Dr	N	C	N	1"	1999	P	1"	2002	SF	N	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2024	Cross Connection Survey
001-0204	2157	Deer Haven Dr	Residential	2157 Deer Haven Dr	N	C	N	1"	1999	P	1"	2000	SF	N	C	2000	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	5/22/2023	Cross Connection Survey
001-0205	2165	Deer Haven Dr	Residential	2165 Deer Haven Dr	N	C	N	1"	1999	P	1"	2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2023	Cross Connection Survey
001-0206	2173	Deer Haven Dr	Residential	2173 Deer Haven Dr	N	C	N	1"	1999	P	1"	8/12/2003	SF	UNK	C	2003	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2003	Visual Insp During Install or Repair
001-0207	2162	Deer Haven Dr	Residential	2162 Deer Haven Dr	N	C	N	1"	1999	P	1"	11/11/2002	SF	UNK	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	11/11/2002	Visual Insp During Install or Repair
001-0208	2158	Deer Haven Dr	Residential	2158 Deer Haven Dr	N	C	N	1"	1999	P	1"	2002	SF	N	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2024	Cross Connection Survey
001-0209	2150	Deer Haven Dr	Residential	2150 Deer Haven Dr	N	C	N	1"	1999	P	1"	7/15/2005	SF	UNK	C	2005	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2005	Visual Insp During Install or Repair
001-0210	2142	Deer Haven Dr	Residential	2142 Deer Haven Dr	N	C	N	1"	1999	P	1"	2002	SF	N	C	2002	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2024	Cross Connection Survey
001-0211	2134	Deer Haven Dr	Residential	2134 Deer Haven Dr	N	C	N	1"	1999	P	1"	2001	SF	N	C	2001	Installation Record	Y	1999	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2023	Cross Connection Survey
001-0212	21																							

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0253	2050	Sweetbriar Ln	Residential	2050 Sweetbriar Ln	N	P	N	1"	2003	P	1.25"	5/2/2014	SF	UNK	O	5/2/2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2014	Visual Insp During Install or Repair
001-0254	2060	Sweetbriar Ln	Residential	2060 Sweetbriar Ln	N	P	N	1"	2003	P	1"	11/24/2008	SF	N	O	2008	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2019	Cross Connection Survey
001-0255	2070	Sweetbriar Ln	Residential	2070 Sweetbriar Ln	N	P	N	1"	2003	P	1"	3/18/2010	SF	N	O	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2022	Cross Connection Survey
001-0256	2080	Sweetbriar Ln	Residential	2080 Sweetbriar Ln	N	P	N	1"	2003	P	1"	9/14/2009	SF	N	O	2009	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2020	Cross Connection Survey
001-0257	2090	Sweetbriar Ln	Residential	2090 Sweetbriar Ln	N	P	N	1"	2003	P	1"	1/28/2010	SF	N	O	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/2022	Cross Connection Survey
001-0258	2083	Sweetbriar Ln	Residential	2083 Sweetbriar Ln	N	P	N	1"	2003	P	1"	1/3/2006	SF	UNK	C	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/3/2006	Visual Insp During Install or Repair
001-0259	2067	Sweetbriar Ln	Residential	2067 Sweetbriar Ln	N	P	N	1"	2003	P	1"	8/31/2011	SF	N	O	2011	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2023	Cross Connection Survey
001-0260	2051	Sweetbriar Ln	Residential	2051 Sweetbriar Ln	N	P	N	1"	2003	P	1"	2010	SF	N	O	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/19/2023	Cross Connection Survey
001-0261	2037	Chloe Ct	Residential	2037 Chloe Ct	N	P	N	1"	2003	P	1"	8/27/2006	SF	UNK	C	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2006	Visual Insp During Install or Repair
001-0262	2028	Chloe Ct	Residential	2028 Chloe Ct	N	P	N	1"	2003	P	1"	4/30/2008	SF	N	O	2008	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
001-0263	2038	Chloe Ct	Residential	2038 Chloe Ct	N	P	N	1"	2003	P	1.25"	5/12/2017	SF	UNK	O	2017	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/12/2017	Visual Insp During Install or Repair
001-0264	2048	Chloe Ct	Residential	2048 Chloe Ct	N	P	N	1"	2003	P	1.25"	11/14/2008	SF	UNK	C	2008	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	11/14/2008	Visual Insp During Install or Repair
001-0265	2019	Sweetbriar Ln	Residential	2019 Sweetbriar Ln	N	P	N	1"	2003	P	1.25"	5/3/2012	SF	UNK	C	2012	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2012	Visual Insp During Install or Repair
001-0266	2003	Sweetbriar Ln	Residential	2003 Sweetbriar Ln	N	P	N	1"	2003	P	1.25"	2011	SF	N	C	2011	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2024	Cross Connection Survey
001-0267	1309	Fieldview Dr	Residential	1309 Fieldview Dr	N	P	N	1"	2003	P	1.25"	2006	SF	UNK	C	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	11/30/2006	Visual Insp During Install or Repair
001-0268	1301	Fieldview Dr	Residential	1301 Fieldview Dr	N	P	N	1"	2003	P	1.25"	9/14/2009	SF	N	O	2009	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
001-0269	1293	Fieldview Dr	Residential	1293 Fieldview Dr	N	P	N	1"	2003	P	1.25"	6/29/2010	SF	N	O	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/11/2022	Cross Connection Survey
001-0301	1198	Fieldview Dr	Residential	1198 Fieldview Dr	N	C	N	1"	1994	P	1"	7/9/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/8/2020	Cross Connection Survey
001-0302	1206	Fieldview Dr	Residential	1206 Fieldview Dr	N	C	N	1"	1994	P	1"	1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2024	Cross Connection Survey
001-0303	1214	Fieldview Dr	Residential	1214 Fieldview Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2023	Cross Connection Survey
001-0304	1220	Fieldview Dr	Residential	1220 Fieldview Dr	N	C	N	1"	1994	P	1"	1994	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
001-0305	1226	Fieldview Dr	Residential	1226 Fieldview Dr	N	C	N	1"	1994	P	1"	2002	SF	N	C	2002	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2024	Cross Connection Survey
001-0306	1234	Fieldview Dr	Residential	1234 Fieldview Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2023	Cross Connection Survey
001-0307	1242	Fieldview Dr	Residential	1242 Fieldview Dr	N	C	N	1"	1994	P	1"	1/6/2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/21/2024	Cross Connection Survey
001-0308	1250	Fieldview Dr	Residential	1250 Fieldview Dr	N	C	N	1"	1994	P	1"	9/15/2004	SF	UNK	C	2004	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/15/2004	Visual Insp During Install or Repair
001-0309	1258	Fieldview Dr	Residential	1258 Fieldview Dr	N	C	N	1"	1994	P	1"	5/3/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2020	Cross Connection Survey
001-0310	1266	Fieldview Dr	Residential	1266 Fieldview Dr	N	C	N	1"	1994	P	1"	10/21/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/19/2019	Cross Connection Survey
001-0311	1274	Fieldview Dr	Residential	1274 Fieldview Dr	N	C	N	1"	1994	P	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/10/2023	Cross Connection Survey
001-0312	1282	Fieldview Dr	Residential	1282 Fieldview Dr	N	C	N	1"	1994	P	1"	5/5/2003	SF	UNK	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	5/5/2003	Visual Insp During Install or Repair
001-0313	1290	Fieldview Dr	Residential	1290 Fieldview Dr	N	C	N	1"	1994	P	1"	9/10/2003	SF	UNK	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/10/2003	Visual Insp During Install or Repair
001-0314	2000	Pinewood Ct	Residential	2000 Pinewood Ct	N	C	N	1"	1994	P	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2024	Cross Connection Survey
001-0315	2010	Pinewood Ct	Residential	2010 Pinewood Ct	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-0316	2016	Pinewood Ct	Residential	2016 Pinewood Ct	N	C	N	1"	1994	P	1"	1/28/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
001-0317	2022	Pinewood Ct	Residential	2022 Pinewood Ct	N	C	N	1"	1994	P	1"	1994	SF	N	C	Post-1984	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	10/21/2021	Cross Connection Survey
001-0318	2017	Pinewood Ct	Residential	2017 Pinewood Ct	N	C	N	1"	1994	P	1"	5/5/2003	SF	UNK	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	5/5/2003	Visual Insp During Install or Repair
001-0319	2011	Pinewood Ct	Residential	2011 Pinewood Ct	N	C	N	1"	1994	P	1"	9/18/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2019	Cross Connection Survey
001-0320	2001	Pinewood Ct	Residential	2001 Pinewood Ct	N	C	N	1"	1994	P	1"	3/18/2002	SF	UNK	C	2002	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/18/2002	Visual Insp During Install or Repair
001-0321	1265	Fieldview Dr	Residential	1265 Fieldview Dr	N	C	N	1"	1994	P	1"	5/9/2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2022	Cross Connection Survey
001-0322	1257	Fieldview Dr	Residential	1257 Fieldview Dr	N	C	N	1"	1994	P	1"	7/9/2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2020	Cross Connection Survey
001-0323	1249	Fieldview Dr	Residential	1249 Fieldview Dr	N	C	N	1"	1994	P	1"	9/11/1996	SF	N	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-0324	1241	Fieldview Dr	Residential	1241 Fieldview Dr	N	C	N	1"	1994	P	1"	7/12/1996	SF	UNK	C	1996	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	7/12/1996	Visual Insp During Install or Repair
001-0325	1233	Fieldview Dr	Residential	1233 Fieldview Dr	N	C	N	1"	1994	P	1"	7/5/2001	SF	UNK	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	7/5/2001	Visual Insp During Install or Repair
001-0326	1225	Fieldview Dr	Residential	1225 Fieldview Dr	N	C	N	1"	1994	P	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/24/2023	Cross Connection Survey
001-0327	1217	Fieldview Dr	Residential	1217 Fieldview Dr	N	C	N	1"	1994	P	1"	2003	SF	N	C	2003	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-0328	2000	Deer Haven Dr	Residential	2000 Deer Haven Dr	N	C	N	1"	1994	P	1"	1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/20/2023	Cross Connection Survey
001-0329	2008	Deer Haven Dr	Residential	2008 Deer Haven Dr	N	C	N	1"	1994	P	1"	2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2023	Cross Connection Survey
001-0330	2018	Deer Haven Dr	Residential	2018 Deer Haven Dr	N	C	N	1"	1994	P	1"	7/14/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/2020	Cross Connection Survey
001-0331	1224	Deer Haven Dr	Residential	1224 Deer Haven Dr	N	C	N	1"	1994	P	1"	6/15/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	3/18/2019	Cross Connection Survey
001-0332	1232	Deer Haven Dr	Residential	1232 Deer Haven Dr	N	C	N	1"	1994	P	1"	9/19/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	9/19/1997	Visual Insp During Install or Repair
001-0333	1240	Deer Haven Dr	Residential	1240 Deer Haven Dr	N	C	N	1"	1994	P	1"	9/14/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2019	Cross Connection Survey
001-0334	1248	Deer Haven Dr	Residential	1248 Deer Haven Dr	N	C	N	1"	1994	P	1"	1994	SF	N	C	Post-1984	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	10/6/2021	Cross Connection Survey
001-0335	1258	Deer Haven Dr	Residential	1258 Deer Haven Dr	N	C	N	1"	1994	P	1"	2/12/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/1997	Visual Insp During Install or Repair
001-0336	1266	Deer Haven Dr	Residential	1266 Deer Haven Dr	N	C	N	1"	1994	P	1"	7/21/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	7/21/1997	Visual Insp During Install or Repair
001-0337	1259	Deer Haven Dr	Residential	1259 Deer Haven Dr	N	C	N	1"	1994	P	1"	9/18/1998	SF	N	C	1998	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2019	Cross Connection Survey
001-0338	1241	Deer Haven Dr	Residential	1241 Deer Haven Dr	N	C	N	1"	1994	P	1"	1/11/2000	SF	N	C	2000	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	5/12/2022	Cross Connection Survey
001-0339	1235	Deer Haven Dr	Residential	1235 Deer Haven Dr	N	C	N	1"	1994	P	1"	11/21/1999	SF	N	C	1999	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2020	Cross Connection Survey
001-0340	1229	Deer Haven Dr	Residential	1229 Deer Haven Dr	N	C	N	1"	1994	P	1"	11/21/1997	SF	UNK	C	1997	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection Only	Y	11/21/1997	Visual Insp During Install or Repair
001-0341	1223	Deer Haven Dr	Residential	1223 Deer Haven Dr	N	C	N	1"	1994	P	1"	2001	SF	N	C	2001	Installation Record	Y	1994	Visual Insp During Install or Repair	Field Inspection			





LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0607	N9163	Christopher Ln	Residential	N9163 Christopher Ln	N	C	N	1"	1995	P	1"	5/5/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2020	Cross Connection Survey
001-0608	N9171	Christopher Ln	Residential	N9171 Christopher Ln	N	C	N	1"	1995	C	1"	6/24/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	6/24/1997	Visual Insp During Install or Repair
001-0609	N9177	Christopher Ln	Residential	N9177 Christopher Ln	N	C	N	1"	1995	C	1"	11/13/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2019	Cross Connection Survey
001-0610	N9193	Christopher Ln	Residential	N9193 Christopher Ln	N	C	N	1"	1995	P	1"	11/17/1999	SF	UNK	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/1999	Visual Insp During Install or Repair
001-0611	W6682	Cedar Ridge Dr	Residential	W6682 Cedar Ridge Dr	N	C	N	1"	1995	P	1"	11/9/1998	SF	Y	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2019	Cross Connection Survey
001-0612	W6674	Cedar Ridge Dr	Residential	W6674 Cedar Ridge Dr	N	C	N	1"	1995	P	1"	5/22/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	5/22/1997	Visual Insp During Install or Repair
001-0613	W6666	Cedar Ridge Dr	Residential	W6666 Cedar Ridge Dr	N	C	N	1"	1995	P	1"	9/12/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	9/12/1997	Visual Insp During Install or Repair
001-0614	W6658	Cedar Ridge Dr	Residential	W6658 Cedar Ridge Dr	N	C	N	1"	1995	P	1"	4/3/1998	SF	N	O	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-0615	W6653	Cedar Ridge Dr	Residential	W6653 Cedar Ridge Dr	N	C	N	1"	1995	P	1"	7/28/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2022	Cross Connection Survey
001-0616	N9172	Oak Lawn Dr	Residential	N9172 Oak Lawn Dr	N	C	N	1"	1995	C	1"	9/16/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-0617	N9164	Oak Lawn Dr	Residential	N9164 Oak Lawn Dr	N	C	N	1"	1995	C	1"	5/27/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	5/27/1997	Visual Insp During Install or Repair
001-0618	W6656	Elmview Dr	Residential	W6656 Elmview Dr	N	P	N	1"	1998	P	1"	7/28/1999	SF	N	O	1999	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
001-0619	W6655	Elmview Dr	Residential	W6655 Elmview Dr	N	C	N	1"	1995	C	1"	6/1/1998	SF	N	O	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2019	Cross Connection Survey
001-0620	N9132	Oak Lawn Dr	Residential	N9132 Oak Lawn Dr	N	C	N	1"	1995	C	1"	4/14/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/8/2019	Cross Connection Survey
001-0621	N9126	Oak Lawn Dr	Residential	N9126 Oak Lawn Dr	N	C	N	1"	1995	C	1"	5/3/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/21/2020	Cross Connection Survey
001-0622	N9118	Oak Lawn Dr	Residential	N9118 Oak Lawn Dr	N	C	N	1"	1995	C	1"	3/5/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/21/2020	Cross Connection Survey
001-0623	N9112	Oak Lawn Dr	Residential	N9112 Oak Lawn Dr	N	C	N	1"	1995	P	1"	2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/2023	Cross Connection Survey
001-0624	N9113	Oak Lawn Dr	Residential	N9113 Oak Lawn Dr	N	C	N	1"	1995	P	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2023	Cross Connection Survey
001-0625	N9119	Oak Lawn Dr	Residential	N9119 Oak Lawn Dr	N	C	N	1"	1995	C	1"	5/29/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/2019	Cross Connection Survey
001-0626	N9127	Oak Lawn Dr	Residential	N9127 Oak Lawn Dr	N	C	N	1"	1995	C	1"	7/17/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-0627	N9141	Oak Lawn Dr	Residential	N9141 Oak Lawn Dr	N	C	N	1"	1995	P	1"	7/27/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/2022	Cross Connection Survey
001-0628	W6675	Elmview Dr	Residential	W6675 Elmview Dr	N	C	N	1"	1995	P	1"	3/4/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/1997	Visual Insp During Install or Repair
001-0629	N9134	Christopher Ln	Residential	N9134 Christopher Ln	N	C	N	1"	1995	P	1"	4/11/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/2022	Cross Connection Survey
001-0630	N9122	Christopher Ln	Residential	N9122 Christopher Ln	N	P	N	1"	1995	C	1"	6/16/1998	SF	N	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
001-0631	N9116	Christopher Ln	Residential	N9116 Christopher Ln	N	C	N	1"	1995	C	1"	11/16/1998	SF	N	C	1998	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-0632	N9106	Christopher Ln	Residential	N9106 Christopher Ln	N	C	N	1"	1995	C	1"	2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2023	Cross Connection Survey
001-0633	N9148	Christopher Ln	Residential	N9148 Christopher Ln	N	C	N	1"	1995	P	1"	2/8/2000	SF	Y	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2022	Cross Connection Survey
001-0634	N9156	Christopher Ln	Residential	N9156 Christopher Ln	N	C	N	1"	1995	C	1"	8/19/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	8/19/1997	Visual Insp During Install or Repair
001-0635	N9164	Christopher Ln	Residential	N9164 Christopher Ln	N	C	N	1"	1995	C	1"	11/26/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/26/1997	Visual Insp During Install or Repair
001-0636	N9172	Christopher Ln	Residential	N9172 Christopher Ln	N	C	N	1"	1995	C	1"	8/8/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/1997	Visual Insp During Install or Repair
001-0637	N9178	Christopher Ln	Residential	N9178 Christopher Ln	N	C	N	1"	1995	C	1"	3/3/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2020	Cross Connection Survey
001-0638	N9179	Oak Lawn Dr	Residential	N9179 Oak Lawn Dr	N	C	N	1"	1995	C	1"	11/30/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
001-0639	N9173	Oak Lawn Dr	Residential	N9173 Oak Lawn Dr	N	C	N	1"	1995	P	1"	6/8/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2022	Cross Connection Survey
001-0640	N9165	Oak Lawn Dr	Residential	N9165 Oak Lawn Dr	N	C	N	1"	1995	P	1.25"	11/4/2008	SF	N	C	2008	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	3/13/2019	Cross Connection Survey
001-0641	W6668	Elmview Dr	Residential	W6668 Elmview Dr	N	P	N	1"	1995	P	1"	12/1/1999	SF	N	C	1999	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2020	Cross Connection Survey
001-0642	W6676	Elmview Dr	Residential	W6676 Elmview Dr	N	P	N	1"	1995	C	1"	10/16/1997	SF	UNK	C	1997	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	10/16/1997	Visual Insp During Install or Repair
001-0643	2108	E Cedar Ridge Dr	Residential	2108 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	12/8/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/30/2022	Cross Connection Survey
001-0644	3819	S Woodendale Way	Residential	3819 S Woodendale Way	N	P	N	1"	1998	P	1"	12/8/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2022	Cross Connection Survey
001-0645	2200	E Cedar Ridge Dr	Residential	2200 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	10/25/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2022	Cross Connection Survey
001-0646	2208	E Cedar Ridge Dr	Residential	2208 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	1998	SF	UNK	C	1998	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1998	Visual Insp During Install or Repair
001-0647	2214	E Cedar Ridge Dr	Residential	2214 E Cedar Ridge Dr	N	P	N	1"	1998	C	1"	5/9/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/11/2022	Cross Connection Survey
001-0648	2220	E Cedar Ridge Dr	Residential	2220 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	8/22/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/2022	Cross Connection Survey
001-0649	2226	E Cedar Ridge Dr	Residential	2226 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	4/11/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	3/29/2022	Cross Connection Survey
001-0650	2232	E Cedar Ridge Dr	Residential	2232 E Cedar Ridge Dr	N	P	N	1"	1998	C	1"	8/11/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2022	Cross Connection Survey
001-0651	2229	E Cedar Ridge Dr	Residential	2229 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/27/2023	Cross Connection Survey
001-0652	2219	E Cedar Ridge Dr	Residential	2219 E Cedar Ridge Dr	N	P	N	1"	1998	C	1"	3/23/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/2022	Cross Connection Survey
001-0653	2209	E Cedar Ridge Dr	Residential	2209 E Cedar Ridge Dr	N	P	N	1"	1998	P	1"	7/23/2003	SF	UNK	C	2003	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	7/22/2003	Visual Insp During Install or Repair
001-0655	3914	S Woodendale Way	Residential	3914 S Woodendale Way	N	P	N	1"	1998	P	1"	12/8/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/27/2022	Cross Connection Survey
001-0656	3928	S Woodendale Way	Residential	3928 S Woodendale Way	N	P	N	1"	1998	P	1"	10/23/2000	SF	Y	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/6/2022	Cross Connection Survey
001-0657	2210	E Elmview Dr	Residential	2210 E Elmview Dr	N	C	N	1"	1995	P	1"	7/25/2001	SF	N	C	2001	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2021	Cross Connection Survey
001-0658	2220	E Elmview Dr	Residential	2220 E Elmview Dr	N	C	N	1"	1998	P	1"	2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	1/26/2023	Cross Connection Survey
001-0659	2230	E Elmview Dr	Residential	2230 E Elmview Dr	N	C	N	1"	1998	P	1.25"	8/26/2002	SF	N	C	2002	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	2/22/2024	Cross Connection Survey
001-0660	2231	E Elmview Dr	Residential	2231 E Elmview Dr	N	C	N	1"	1995	P	1"	8/11/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2022	Cross Connection Survey
001-0661	2221	E Elmview Dr	Residential	2221 E Elmview Dr	N	C	N	1"	1995	C	1"	1/26/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/27/2022	Cross Connection Survey
001-0662	2211	E Elmview Dr	Residential	2211 E Elmview Dr	N	C	N	1"	1995	C	1"	12/6/2000	SF	N	C	2000	Installation Record	Y	1995	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2022	Cross Connection Survey
001-0663	2201	E Elmview Dr	Residential	2201 E Elmview Dr	N	P	N	1"	1998	P	1"	2001	SF	N	C	2001	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2023	Cross Connection Survey
001-0664	4010	S Woodendale Way	Residential	4010 S Woodendale Way	N	P	N	1"	1998	P	1"	5/9/2000	SF	N	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/2022	Cross Connection Survey
001-0665	4110	S Woodendale Way	Residential	4110 S Woodendale Way	N	P	N	1"	1998	P	1"	5/25/2000	SF	UNK	C	2000	Installation Record	Y	1998	Visual Insp During Install or Repair	Field Inspection Only	Y	5/25/2000	Visual Insp During Install or



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0701	W6548	Ethan Dr	Residential	W6548 Ethan Dr	N	P	N	1"	2005	P	1.25"	8/17/2006	SF	UNK	O	8/17/2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/17/2006	Visual Insp During Install or Repair
001-0702	W6542	Ethan Dr	Residential	W6542 Ethan Dr	N	P	N	1.25"	5/14/2013	P	1.25"	5/14/2013	SF	UNK	O	5/14/2013	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/14/2013	Visual Insp During Install or Repair
001-0703	W6534	Ethan Dr	Residential	W6534 Ethan Dr	N	P	N	1"	2005	P	1.25"	11/28/2012	SF	N	O	2012	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2021	Cross Connection Survey
001-0704	W6522	Ethan Dr	Residential	W6522 Ethan Dr	N	P	N	1"	2005	P	1.25"	10/2/2017	SF	UNK	O	10/2/2017	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/2/2017	Visual Insp During Install or Repair
001-0705	N9217	Dylan Dr	Residential	N9217 Dylan Dr	N	P	N	1"	2005	P	1.25"	1/28/2010	SF	N	O	1/28/2010	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/10/2022	Cross Connection Survey
001-0706	N9216	Dylan Dr	Residential	N9216 Dylan Dr	N	P	N	1"	2005	P	1.25"	5/12/2006	SF	UNK	O	5/12/2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/12/2006	Visual Insp During Install or Repair
001-0707	N9206	Dylan Dr	Residential	N9206 Dylan Dr	N	P	N	1"	2005	P	1.25"	8/27/2009	SF	N	O	8/27/2009	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2021	Cross Connection Survey
001-0708	N9196	Dylan Dr	Residential	N9196 Dylan Dr	N	P	N	1"	2005	P	1.25"	5/31/2018	SF	UNK	O	5/31/2018	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/31/2018	Visual Insp During Install or Repair
001-0709	N9188	Dylan Dr	Residential	N9188 Dylan Dr	N	P	N	1"	2005	P	1.25"	5/25/2018	SF	UNK	O	5/25/2018	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/25/2018	Visual Insp During Install or Repair
001-0710	N9182	Dylan Dr	Residential	N9182 Dylan Dr	N	P	N	1"	2005	P	1.25"	7/21/2017	SF	UNK	O	7/21/2017	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	7/21/2017	Visual Insp During Install or Repair
001-0711	W6519	Landon Dr	Residential	W6519 Landon Dr	N	P	N	1"	2005	P	1.25"	3/14/2013	SF	UNK	O	3/14/2013	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2013	Visual Insp During Install or Repair
001-0712	W6525	Landon Dr	Residential	W6525 Landon Dr	N	P	N	1"	2005	P	1.25"	12/8/2008	SF	N	O	2008	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
001-0713	W6533	Landon Dr	Residential	W6533 Landon Dr	N	P	N	1"	2005	P	1.25"	10/27/2008	SF	N	O	2008	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/2019	Cross Connection Survey
001-0714	W6541	Landon Dr	Residential	W6541 Landon Dr	N	P	N	1"	2005	P	1.25"	5/9/2006	SF	UNK	C	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2006	Visual Insp During Install or Repair
001-0715	W6549	Landon Dr	Residential	W6549 Landon Dr	N	P	N	1"	2005	P	1.25"	7/3/2006	SF	UNK	C	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	7/3/2006	Visual Insp During Install or Repair
001-0716	W6557	Landon Dr	Residential	W6557 Landon Dr	N	P	N	1"	2005	P	1.25"	5/9/2006	SF	UNK	C	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2006	Visual Insp During Install or Repair
001-0717	W6567	Landon Dr	Residential	W6567 Landon Dr	N	P	N	1"	2005	P	1.25"	10/16/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/16/2006	Visual Insp During Install or Repair
001-0718	W6573	Landon Dr	Residential	W6573 Landon Dr	N	P	N	1"	2005	P	1.25"	12/6/2007	SF	UNK	O	2007	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	12/6/2007	Visual Insp During Install or Repair
001-0719	W6579	Landon Dr	Residential	W6579 Landon Dr	N	P	N	1"	2005	P	1.25"	8/24/2007	SF	UNK	O	2007	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/24/2007	Visual Insp During Install or Repair
001-0720	W6578	Austin Dr	Residential	W6578 Austin Dr	N	P	N	1"	2005	P	1.25"	12/12/2013	SF	UNK	O	2013	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	12/12/2013	Visual Insp During Install or Repair
001-0721	W6572	Austin Dr	Residential	W6572 Austin Dr	N	P	N	1"	2005	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/2023	Cross Connection Survey
001-0722	W6566	Austin Dr	Residential	W6566 Austin Dr	N	P	N	1"	2005	P	1.25"	10/17/2007	SF	UNK	O	2007	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/17/2007	Visual Insp During Install or Repair
001-0723	W6558	Austin Dr	Residential	W6558 Austin Dr	N	P	N	1"	2005	P	1.25"	3/16/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2006	Visual Insp During Install or Repair
001-0724	W6550	Austin Dr	Residential	W6550 Austin Dr	N	P	N	1"	2005	P	1.25"	3/2/2007	SF	UNK	O	2007	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2007	Visual Insp During Install or Repair
001-0725	W6546	Austin Dr	Residential	W6546 Austin Dr	N	P	N	1"	2005	P	1.25"	1/31/2012	SF	N	O	1/31/2012	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/15/2024	Cross Connection Survey
001-0726	W6540	Austin Dr	Residential	W6540 Austin Dr	N	P	N	1"	2005	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-0727	W6532	Austin Dr	Residential	W6532 Austin Dr	N	P	N	1"	2005	P	1.25"	6/6/20102	SF	UNK	O	6/6/2012	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2012	Visual Insp During Install or Repair
001-0728	W6522	Austin Dr	Residential	W6522 Austin Dr	N	P	N	1"	2005	P	1.25"	11/29/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2006	Visual Insp During Install or Repair
001-0729	N9158	Brenda Dr	Residential	N9158 Brenda Dr	N	P	N	1"	2005	P	1.25"	10/10/2013	SF	UNK	O	2013	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/10/2013	Visual Insp During Install or Repair
001-0730	N9152	Brenda Dr	Residential	N9152 Brenda Dr	N	P	N	1"	2005	P	1.25"	8/24/2020	SF	UNK	O	8/24/2020	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/24/2020	Visual Insp During Install or Repair
001-0731	N9146	Brenda Dr	Residential	N9146 Brenda Dr	N	P	N	1"	2005	P	1.25"	5/3/2017	SF	UNK	O	5/3/2017	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2017	Visual Insp During Install or Repair
001-0732	N9138	Brenda Dr	Residential	N9138 Brenda Dr	N	P	N	1"	2005	P	1.25"	10/1/2014	SF	UNK	O	10/1/2014	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/1/2014	Visual Insp During Install or Repair
001-0733	N9132	Brenda Dr	Residential	N9132 Brenda Dr	N	P	N	1"	2005	P	1.25"	4/13/2021	SF	UNK	O	4/13/2021	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2021	Visual Insp During Install or Repair
001-0734	N9126	Brenda Dr	Residential	N9126 Brenda Dr	N	P	N	1"	2005	P	1.25"	1/15/2010	SF	N	O	7/2/1905	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/17/2022	Cross Connection Survey
001-0735	W6521	Brittany Dr	Residential	W6521 Brittany Dr	N	P	N	1"	2005	P	1.25"	6/24/2014	SF	UNK	O	6/24/2014	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	6/24/2014	Visual Insp During Install or Repair
001-0736	W6527	Brittany Dr	Residential	W6527 Brittany Dr	N	P	N	1"	2005	P	1.25"	4/20/2015	SF	UNK	O	4/20/2015	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/20/2015	Visual Insp During Install or Repair
001-0737	W6535	Brittany Dr	Residential	W6535 Brittany Dr	N	P	N	1"	2005	P	1.25"	8/3/2020	SF	UNK	O	8/3/2020	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/3/2020	Visual Insp During Install or Repair
001-0738	W6545	Brittany Dr	Residential	W6545 Brittany Dr	N	P	N	1"	2005	P	1.25"	2022	SF	UNK	O	2022	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2022	Cross Connection Survey
001-0739	W6551	Brittany Dr	Residential	W6551 Brittany Dr	N	P	N	1"	2005	P	1.25"	5/3/2016	SF	UNK	O	5/3/2016	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2016	Visual Insp During Install or Repair
001-0740	W6559	Brittany Dr	Residential	W6559 Brittany Dr	N	P	N	1"	2005	P	1.25"	4/18/2017	SF	UNK	O	4/18/2017	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/2017	Visual Insp During Install or Repair
001-0741	W6567	Brittany Dr	Residential	W6567 Brittany Dr	N	P	N	1"	2005	P	1.25"	4/21/2016	SF	UNK	O	4/21/2016	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2016	Visual Insp During Install or Repair
001-0743	W6578	Brittany Dr	Residential	W6578 Brittany Dr	N	P	N	1"	2005	P	1.25"	9/23/2013	SF	UNK	O	2013	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	9/23/2013	Visual Insp During Install or Repair
001-0744	W6570	Brittany Dr	Residential	W6570 Brittany Dr	N	P	N	1"	2005	P	1.25"	3/15/2012	SF	UNK	O	2012	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2012	Visual Insp During Install or Repair
001-0745	W6562	Brittany Dr	Residential	W6562 Brittany Dr	N	P	N	1"	2005	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/2023	Cross Connection Survey
001-0746	W6554	Brittany Dr	Residential	W6554 Brittany Dr	N	P	N	1"	2005	P	1.25"	5/13/2010	SF	N	O	2010	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/2022	Cross Connection Survey
001-0747	W6548	Brittany Dr	Residential	W6548 Brittany Dr	N	P	N	1"	2005	P	1.25"	1/26/2010	SF	UNK	O	2010	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/26/2010	Visual Insp During Install or Repair
001-0748	W6540	Brittany Dr	Residential	W6540 Brittany Dr	N	P	N	1"	2005	P	1.25"	1/29/2008	SF	N	O	2008	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
001-0749	W6532	Brittany Dr	Residential	W6532 Brittany Dr	N	P	N	1"	2005	P	1.25"	10/17/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	10/17/2006	Visual Insp During Install or Repair
001-0750	W6522	Brittany Dr	Residential	W6522 Brittany Dr	N	P	N	1"	2005	P	1.25"	8/8/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/2006	Visual Insp During Install or Repair
001-0751	W6523	Austin Dr	Residential	W6523 Austin Dr	N	P	N	1"	2005	P	1.25"	1/4/2009	SF	UNK	O	2009	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/4/2009	Visual Insp During Install or Repair
001-0752	W6533	Austin Dr	Residential	W6533 Austin Dr	N	P	N	1"	2005	P	1.25"	12/19/2008	SF	N	O	2008	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-0753	W6541	Austin Dr	Residential	W6541 Austin Dr	N	P	N	1"	2005	P	1.25"	9/12/2007	SF	UNK	O	2007	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	9/12/2007	Visual Insp During Install or Repair
001-0754	W6549	Austin Dr	Residential	W6549 Austin Dr	N	P	N	1"	2005	P	1.25"	7/27/2009	SF	N	O	2009	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2020	Cross Connection Survey
001-0755	W6555	Austin Dr	Residential	W6555 Austin Dr	N	P	N	1"	2005	P	1.25"	3/16/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2006	Visual Insp During Install or Repair
001-0756	W6563	Austin Dr	Residential	W6563 Austin Dr	N	P	N	1"	2005	P	1.25"	5/9/2009	SF	UNK	O	2009	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2006	Visual Insp During Install or Repair
001-0757	W6571	Austin Dr	Residential	W6571 Austin Dr	N	P	N	1"	2005	P	1.25"	6/8/2006	SF	UNK	O	2006	Installation Record	Y	2005	Visual Insp During Install or Repair	Field Inspection Only	Y	6/8/2	

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0832	1207	Stillmeadow Ln	Residential	1207 Stillmeadow Ln	N	P	N	1"	2000	C	1"	10/12/2001	SF	N	C	Post-1984	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/3/2022	Cross Connection Survey
001-0833	1201	Stillmeadow Ln	Residential	1201 Stillmeadow Ln	N	P	N	1"	2000	P	1"	6/7/2002	SF	N	C	2002	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2024	Cross Connection Survey
001-0835	2412	Manitowoc Rd	Residential	2412 Manitowoc Rd	N	C	N	1"	2000	P	1"	2003	SF	N	C	2003	Installation Record	Y	1992	Visual Insp During Install or Repair	Field Inspection Only	Y	4/19/2023	Cross Connection Survey
001-0836	1200	Bluegrass Ln	Residential	1200 Bluegrass Ln	N	P	N	1"	2000	C	1"	2001	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/25/2024	Cross Connection Survey
001-0837	1204	Bluegrass Ln	Residential	1204 Bluegrass Ln	N	P	N	1"	2000	P	1"	2/22/2002	SF	UNK	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/22/2002	Visual Insp During Install or Repair
001-0838	1208	Bluegrass Ln	Residential	1208 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
001-0839	1212	Bluegrass Ln	Residential	1212 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2000	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2024	Cross Connection Survey
001-0840	1216	Bluegrass Ln	Residential	1216 Bluegrass Ln	N	P	N	1"	2000	P	1"	10/5/2001	SF	UNK	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2001	Visual Insp During Install or Repair
001-0841	1220	Bluegrass Ln	Residential	1220 Bluegrass Ln	N	P	N	1"	2000	P	1"	2004	SF	N	C	2004	Installation Record	Y	2004	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2024	Cross Connection Survey
001-0842	1224	Bluegrass Ln	Residential	1224 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/14/2023	Cross Connection Survey
001-0843	1228	Bluegrass Ln	Residential	1228 Bluegrass Ln	N	P	N	1"	2000	P	1"	2000	SF	N	C	2000	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/17/2023	Cross Connection Survey
001-0844	1234	Bluegrass Ln	Residential	1234 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/17/2023	Cross Connection Survey
001-0845	1238	Bluegrass Ln	Residential	1238 Bluegrass Ln	N	P	N	1"	2000	P	1"	2000	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
001-0846	1242	Bluegrass Ln	Residential	1242 Bluegrass Ln	N	P	N	1"	2000	P	1"	2000	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2024	Cross Connection Survey
001-0847	1246	Bluegrass Ln	Residential	1246 Bluegrass Ln	N	P	N	1"	2000	P	1"	11/6/2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/3/2024	Cross Connection Survey
001-0848	1250	Bluegrass Ln	Residential	1250 Bluegrass Ln	N	P	N	1"	2000	P	1"	2006	SF	N	C	2006	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/2023	Cross Connection Survey
001-0849	1254	Bluegrass Ln	Residential	1254 Bluegrass Ln	N	P	N	1"	2000	P	1"	11/29/2002	SF	UNK	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2002	Visual Insp During Install or Repair
001-0850	1258	Bluegrass Ln	Residential	1258 Bluegrass Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-0851	1262	Bluegrass Ln	Residential	1262 Bluegrass Ln	N	P	N	1"	2000	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-0852	1266	Bluegrass Ln	Residential	1266 Bluegrass Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/22/2024	Cross Connection Survey
001-0853	1256	Stillmeadow Ln	Residential	1256 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-0854	1252	Stillmeadow Ln	Residential	1252 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-0855	1248	Stillmeadow Ln	Residential	1248 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2/7/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2003	Visual Insp During Install or Repair
001-0856	1244	Stillmeadow Ln	Residential	1244 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2024	Cross Connection Survey
001-0857	1240	Stillmeadow Ln	Residential	1240 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2024	Cross Connection Survey
001-0858	1236	Stillmeadow Ln	Residential	1236 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2024	Cross Connection Survey
001-0859	1232	Stillmeadow Ln	Residential	1232 Stillmeadow Ln	N	P	N	1"	2000	C	1"	10/9/2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/22/2024	Cross Connection Survey
001-0860	1228	Stillmeadow Ln	Residential	1228 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2023	Cross Connection Survey
001-0861	1224	Stillmeadow Ln	Residential	1224 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2024	Cross Connection Survey
001-0862	1220	Stillmeadow Ln	Residential	1220 Stillmeadow Ln	N	P	N	1"	2000	P	1"	2004	SF	N	C	2004	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/2023	Cross Connection Survey
001-0863	1205	Bluegrass Ln	Residential	1205 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	Y	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-0864	1211	Bluegrass Ln	Residential	1211 Bluegrass Ln	N	P	N	1"	2000	P	1.25"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/6/2023	Cross Connection Survey
001-0865	1219	Bluegrass Ln	Residential	1219 Bluegrass Ln	N	P	N	1"	2000	P	1"	9/10/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	9/10/2003	Visual Insp During Install or Repair
001-0866	1223	Bluegrass Ln	Residential	1223 Bluegrass Ln	N	P	N	1"	2000	P	1"	6/27/2003	SF	N	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/17/2024	Cross Connection Survey
001-0867	1227	Bluegrass Ln	Residential	1227 Bluegrass Ln	N	P	N	1"	2000	P	1"	4/29/2002	SF	UNK	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2002	Visual Insp During Install or Repair
001-0868	1231	Bluegrass Ln	Residential	1231 Bluegrass Ln	N	P	N	1"	2000	P	1"	8/21/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/2003	Visual Insp During Install or Repair
001-0869	1235	Bluegrass Ln	Residential	1235 Bluegrass Ln	N	P	N	1"	2000	P	1"	3/10/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/2003	Visual Insp During Install or Repair
001-0870	1239	Bluegrass Ln	Residential	1239 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/21/2024	Cross Connection Survey
001-0871	1243	Bluegrass Ln	Residential	1243 Bluegrass Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2024	Cross Connection Survey
001-0872	1247	Bluegrass Ln	Residential	1247 Bluegrass Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/6/2024	Cross Connection Survey
001-0873	1251	Bluegrass Ln	Residential	1251 Bluegrass Ln	N	P	N	1"	2000	C	1"	8/21/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	8/21/2003	Visual Insp During Install or Repair
001-0874	1255	Bluegrass Ln	Residential	1255 Bluegrass Ln	N	P	N	1"	2000	P	1.25"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2004	Cross Connection Survey
001-0875	2510	Hazelnut Ln	Residential	2510 Hazelnut Ln	N	P	N	1"	2000	C	1"	8/27/2004	SF	UNK	C	2004	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2004	Visual Insp During Install or Repair
001-0876	2514	Hazelnut Ln	Residential	2514 Hazelnut Ln	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/9/2023	Cross Connection Survey
001-0877	2518	Hazelnut Ln	Residential	2518 Hazelnut Ln	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/9/2023	Cross Connection Survey
001-0878	1250	Honey Bunch Ct	Residential	1250 Honey Bunch Ct	N	P	N	1"	2000	P	1"	2002	SF	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2024	Cross Connection Survey
001-0880	1240	Honey Bunch Ct	Residential	1240 Honey Bunch Ct	N	P	N	1"	2000	C	1"	2/7/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2003	Visual Insp During Install or Repair
001-0881	1236	Honey Bunch Ct	Residential	1236 Honey Bunch Ct	N	P	N	1"	2000	C	1"	2001	SF	Y	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/2023	Cross Connection Survey
001-0882	1230	Honey Bunch Ct	Residential	1230 Honey Bunch Ct	N	P	N	1"	2000	C	1"	10/10/2006	SF	UNK	C	2006	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	10/10/2006	Visual Insp During Install or Repair
001-0883	1226	Honey Bunch Ct	Residential	1226 Honey Bunch Ct	N	P	N	1"	2000	P	1.25"	7/13/1905	SF	N	O	2021	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/28/2021	Visual Insp During Install or Repair
001-0885	1216	Honey Bunch Ct	Residential	1216 Honey Bunch Ct	N	P	N	1"	2000	P	1"	2001	SF	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-0901	1053	Manitoba St	Residential	1053 Manitoba St	N	P	N	1"	2002	P	1"	11/2/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/2/2004	Visual Insp During Install or Repair
001-0902	1049	Manitoba St	Residential	1049 Manitoba St	N	P	N	1"	2002	P	1"	10/4/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/4/2004	Visual Insp During Install or Repair
001-0903	1045	Manitoba St	Residential	1045 Manitoba St	N	P	N	1"	2002	P	1"	6/21/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/21/2004	Visual Insp During Install or Repair
001-0904	1041	Manitoba St	Residential	1041 Manitoba St	N	P	N	1"	2002	P	1"	8/12/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2003	Visual Insp During Install or Repair
001-0905	1037	Manitoba St	Residential	1037 Manitoba St	N	P	N	1"	2002	P	1"	10/5/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2004	Visual Insp During Install or Repair
001-0906	1033	Manitoba St	Residential	1033 Manitoba St	N	P	N	1"	2002	P	1"	11/2/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/2/2004	Visual Insp During Install or Repair
001-0907	1029	Manitoba St	Residential	1029 Manitoba St	N	P	N	1"	2002	P	1"	11/4/2024	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/4/2024	Visual Insp During Install or Repair
001-0908	1025	Manitoba St	Residential	1025 Manitoba St																				



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-0943	1056	Lugano St	Residential	1056 Lugano St	N	P	N	1"	2002	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-0944	3073	Winnipeg St	Residential	3073 Winnipeg St	N	P	N	1"	2002	P	1"	7/9/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/9/2004	Visual Insp During Install or Repair
001-0945	3069	Winnipeg St	Residential	3069 Winnipeg St	N	P	N	1"	2002	P	1"	4/30/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/30/2004	Visual Insp During Install or Repair
001-0946	3065	Winnipeg St	Residential	3065 Winnipeg St	N	P	N	1"	2002	P	1"	11/17/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/2003	Visual Insp During Install or Repair
001-0947	3061	Winnipeg St	Residential	3061 Winnipeg St	N	P	N	1"	2002	P	1.25"	10/5/2009	SF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2020	Cross Connection Survey
001-0948	3057	Winnipeg St	Residential	3057 Winnipeg St	N	P	N	1"	2002	P	1.25"	5/30/2006	SF	Y	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2020	Cross Connection Survey
001-0949	3053	Winnipeg St	Residential	3053 Winnipeg St	N	P	N	1"	2002	P	1"	7/15/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2005	Visual Insp During Install or Repair
001-0950	3049	Winnipeg St	Residential	3049 Winnipeg St	N	P	N	1"	2002	P	1.25"	1/17/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2006	Visual Insp During Install or Repair
001-0951	3045	Winnipeg St	Residential	3045 Winnipeg St	N	P	N	1"	2002	P	1"	10/5/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2005	Visual Insp During Install or Repair
001-0952	3041	Winnipeg St	Residential	3041 Winnipeg St	N	P	N	1"	2002	P	1.25"	7/18/2007	SF	UNK	C	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/18/2007	Visual Insp During Install or Repair
001-0953	3037	Winnipeg St	Residential	3037 Winnipeg St	N	P	N	1"	2002	P	1.25"	7/16/2010	SF	UNK	C	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/16/2010	Visual Insp During Install or Repair
001-0954	1029	Tana Ln	Residential	1029 Tana Ln	N	P	N	1"	2002	P	1.25"	1/21/2009	SF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2020	Cross Connection Survey
001-0955	1025	Tana Ln	Residential	1025 Tana Ln	N	P	N	1"	2002	P	1"	5/21/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/21/2004	Visual Insp During Install or Repair
001-0956	1021	Tana Ln	Residential	1021 Tana Ln	N	P	N	1"	2002	P	1"	9/21/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2004	Visual Insp During Install or Repair
001-0957	1017	Tana Ln	Residential	1017 Tana Ln	N	P	N	1"	2002	P	1"	6/8/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/8/2005	Visual Insp During Install or Repair
001-0958	1013	Tana Ln	Residential	1013 Tana Ln	N	P	N	1"	2002	P	1"	6/6/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2005	Visual Insp During Install or Repair
001-0959	1009	Tana Ln	Residential	1009 Tana Ln	N	P	N	1"	2002	P	1"	2/11/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2004	Visual Insp During Install or Repair
001-0960	1005	Tana Ln	Residential	1005 Tana Ln	N	P	N	1"	2002	P	1"	2/11/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2004	Visual Insp During Install or Repair
001-0961	1008	Tana Ln	Residential	1008 Tana Ln	N	P	N	1"	2002	P	1.25"	11/14/2007	SF	UNK	C	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/14/2007	Visual Insp During Install or Repair
001-0962	1012	Tana Ln	Residential	1012 Tana Ln	N	P	N	1"	2002	P	1"	9/27/2010	SF	N	O	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/8/2022	Cross Connection Survey
001-0963	1016	Tana Ln	Residential	1016 Tana Ln	N	P	N	1"	2002	P	1.25"	3/16/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2006	Visual Insp During Install or Repair
001-0964	1020	Tana Ln	Residential	1020 Tana Ln	N	P	N	1"	2002	P	1.25"	10/9/2012	SF	UNK	O	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/9/2012	Visual Insp During Install or Repair
001-0965	1024	Tana Ln	Residential	1024 Tana Ln	N	P	N	1"	2002	P	1"	11/2/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/2/2004	Visual Insp During Install or Repair
001-0966	3026	Winnipeg St	Residential	3026 Winnipeg St	N	P	N	1"	2002	P	1.25"	5/12/2010	SF	N	O	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2022	Cross Connection Survey
001-0967	3030	Winnipeg St	Residential	3030 Winnipeg St	N	P	N	1"	2002	P	1.25"	9/30/2009	SF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/31/2021	Cross Connection Survey
001-0968	3034	Winnipeg St	Residential	3034 Winnipeg St	N	P	N	1"	2002	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/24/2023	Cross Connection Survey
001-0969	3038	Winnipeg St	Residential	3038 Winnipeg St	N	P	N	1"	2002	P	1.25"	3/7/2008	SF	N	C	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/7/2019	Cross Connection Survey
001-0970	1044	Tahoe Ct	Residential	1044 Tahoe Ct	N	P	N	1"	2002	P	1.25"	4/16/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/25/2019	Cross Connection Survey
001-0971	1048	Tahoe Ct	Residential	1048 Tahoe Ct	N	P	N	1"	2002	P	1.25"	2011	SF	Y	O	2011	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2023	Cross Connection Survey
001-0972	1052	Tahoe Ct	Residential	1052 Tahoe Ct	N	P	N	1"	2002	P	1.25"	2/5/2010	SF	Y	O	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2010	Visual Insp During Install or Repair
001-0973	1056	Tahoe Ct	Residential	1056 Tahoe Ct	N	P	N	1"	2002	P	1"	9/15/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/15/2004	Visual Insp During Install or Repair
001-0974	1060	Tahoe Ct	Residential	1060 Tahoe Ct	N	P	N	1"	2002	P	1"	9/14/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/14/2005	Visual Insp During Install or Repair
001-0975	3046	Winnipeg St	Residential	3046 Winnipeg St	N	P	N	1"	2002	P	1"	11/18/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/18/2005	Visual Insp During Install or Repair
001-0976	3050	Winnipeg St	Residential	3050 Winnipeg St	N	P	N	1"	2002	P	1"	12/22/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/22/2004	Visual Insp During Install or Repair
001-0977	3054	Winnipeg St	Residential	3054 Winnipeg St	N	P	N	1"	2002	P	1"	1/5/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/5/2005	Visual Insp During Install or Repair
001-0978	3058	Winnipeg St	Residential	3058 Winnipeg St	N	P	N	1"	2002	P	1.25"	11/4/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
001-0979	3062	Winnipeg St	Residential	3062 Winnipeg St	N	P	N	1"	2002	P	1"	10/5/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2004	Visual Insp During Install or Repair
001-0980	3066	Winnipeg St	Residential	3066 Winnipeg St	N	P	N	1"	2002	P	1"	4/13/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2005	Visual Insp During Install or Repair
001-0981	3070	Winnipeg St	Residential	3070 Winnipeg St	N	P	N	1"	2002	P	1"	4/23/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/23/2004	Visual Insp During Install or Repair
001-0982	3074	Winnipeg St	Residential	3074 Winnipeg St	N	P	N	1"	2002	P	1.25"	6/23/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/23/2017	Visual Insp During Install or Repair
001-0983	3082	Winnipeg St	Residential	3082 Winnipeg St	N	P	N	1"	2002	P	1"	3/29/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/29/2004	Visual Insp During Install or Repair
001-0984	3086	Winnipeg St	Residential	3086 Winnipeg St	N	P	N	1"	2002	P	1"	11/29/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2005	Visual Insp During Install or Repair
001-1001	3058	Villa Way	Residential	3058 Villa Way	N	P	N	1.25"	2011	P	1.25"	6/20/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	6/20/2014	Visual Insp During Install or Repair
001-1002	3054	Villa Way	Residential	3054 Villa Way	N	P	N	1.25"	2011	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2023	Cross Connection Survey
001-1003	3050	Villa Way	Residential	3050 Villa Way	N	P	N	1.25"	2011	P	1.25"	2/24/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	2/24/2014	Visual Insp During Install or Repair
001-1004	3046	Villa Way	Residential	3046 Villa Way	N	P	N	1.25"	2011	P	1.25"	7/3/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	7/3/2013	Visual Insp During Install or Repair
001-1005	3042	Villa Way	Residential	3042 Villa Way	N	P	N	1.25"	2011	P	1.25"	7/29/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	7/29/2013	Visual Insp During Install or Repair
001-1006	3038	Villa Way	Residential	3038 Villa Way	N	P	N	1.25"	2011	P	1.25"	3/14/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2013	Visual Insp During Install or Repair
001-1007	3034	Villa Way	Residential	3034 Villa Way	N	P	N	1.25"	2011	P	1.25"	9/24/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	9/24/2013	Visual Insp During Install or Repair
001-1008	3030	Villa Way	Residential	3030 Villa Way	N	P	N	1.25"	2011	P	1.25"	7/7/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	7/7/2014	Visual Insp During Install or Repair
001-1009	3026	Villa Way	Residential	3026 Villa Way	N	P	N	1.25"	2011	P	1.25"	8/20/2012	SF	UNK	O	2012	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	8/20/2012	Visual Insp During Install or Repair
001-1010	3022	Villa Way	Residential	3022 Villa Way	N	P	N	1.25"	2011	P	1.25"	6/4/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	6/4/2014	Visual Insp During Install or Repair
001-1011	3019	Villa Way	Residential	3019 Villa Way	N	P	N	1.25"	2011	P	1.25"	1/22/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2014	Visual Insp During Install or Repair
001-1012	3023	Villa Way	Residential	3023 Villa Way	N	P	N	1.25"	2011	P	1.25"	6/20/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	6/20/2013	Visual Insp During Install or Repair
001-1013	3027	Villa Way	Residential	3027 Villa Way	N	P	N	1.25"	2011	P	1.25"	3/5/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2013	Visual Insp During Install or Repair
001-1014	3031	Villa Way	Residential	3031 Villa Way	N	P	N	1.25"	2011	P	1.25"	9/10/2014	SF	UNK	O	2014	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y	9/10/2014	Visual Insp During Install or Repair
001-1015	3035	Villa Way	Residential	3035 Villa Way	N	P	N	1.25"	2011	P	1.25"	8/12/2013	SF	UNK	O	2013	Installation Record	Y	2011	Visual Insp During Install or Repair	Field Inspection Only	Y		

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-1169	917	Clover Ct	Residential	917 Clover Ct	N	P	N	1"	2002	P	1.25"	1/5/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/5/2018	Visual Insp During Install or Repair
001-1170	913	Clover Ct	Residential	913 Clover Ct	N	P	N	1.25"	2002	P	1.25"	3/18/2019	SF	UNK	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/18/2019	Visual Insp During Install or Repair
001-1171	909	Clover Ct	Residential	909 Clover Ct	N	P	N	1"	2002	P	1.25"	11/23/2022	SF	UNK	O	2022	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/23/2022	Visual Insp During Install or Repair
001-1172	905	Clover Ct	Residential	905 Clover Ct	N	P	N	1"	2002	P	1.25"	1/19/2024	SF	UNK	O	2024	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2024	Cross Connection Survey
001-1173	901	Clover Ct	Residential	901 Clover Ct	N	P	N	1"	2002	P	1.25"	6/30/2023	SF	UNK	O	2023	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/30/2023	Visual Insp During Install or Repair
001-1174	882	Fountain Way	Residential	882 Fountain Way	N	P	N	1"	2002	P	1.25"	4/11/2023	SF	UNK	O	2023	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/11/2023	Visual Insp During Install or Repair
001-1175	886	Fountain Way	Residential	886 Fountain Way	N	P	N	1"	2002	P	1.25"	12/6/2016	SF	UNK	O	2016	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/6/2016	Visual Insp During Install or Repair
001-1168	920	Clover Ct	Residential	920 Clover Ct	N	P	N	1"	2002	P	1.25"	7/16/1905	SF	N	O	2024	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/3/2024	Cross Connection Survey
001-1177	912	Whisper Falls Ct	Residential	912 Whisper Falls Ct	N	P	N	1"	2002	P	1"	4/20/2005	SF	UNK	C	2002	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/20/2005	Visual Insp During Install or Repair
001-1178	916	Whisper Falls Ct	Residential	916 Whisper Falls Ct	N	P	N	1"	2002	P	1"	1/6/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/6/2004	Visual Insp During Install or Repair
001-1179	920	Whisper Falls Ct	Residential	920 Whisper Falls Ct	N	P	N	1"	2002	P	1.25"	6/13/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/13/2014	Visual Insp During Install or Repair
001-1180	925	Whisper Falls Ct	Residential	925 Whisper Falls Ct	N	P	N	1"	2002	P	1.25"	5/1/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/2017	Visual Insp During Install or Repair
001-1181	921	Whisper Falls Ct	Residential	921 Whisper Falls Ct	N	P	N	1"	2002	P	1.25"	3/11/2020	SF	UNK	O	2020	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/11/2020	Visual Insp During Install or Repair
001-1182	917	Whisper Falls Ct	Residential	917 Whisper Falls Ct	N	P	N	1"	2002	P	1.25"	1/23/2023	SF	UNK	O	2023	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/23/2023	Visual Insp During Install or Repair
001-1183	870	Eden Ct	Residential	870 Eden Ct	N	P	N	1"	2002	P	1"	8/12/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2004	Visual Insp During Install or Repair
001-1184	866	Eden Ct	Residential	866 Eden Ct	N	P	N	1"	2002	P	1"	2004	SF	N	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2024	Cross Connection Survey
001-1185	862	Eden Ct	Residential	862 Eden Ct	N	P	N	1"	2002	P	1"	2002	SF	UNK	O	2002	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/23/2024	Cross Connection Survey
001-1186	858	Eden Ct	Residential	858 Eden Ct	N	P	N	1"	2002	P	1"	11/17/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/2003	Visual Insp During Install or Repair
001-1187	861	Eden Ct	Residential	861 Eden Ct	N	P	N	1"	2002	P	1"	4/13/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2005	Visual Insp During Install or Repair
001-1188	865	Eden Ct	Residential	865 Eden Ct	N	P	N	1"	2002	P	1.25"	1/6/2023	SF	UNK	O	2023	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/6/2023	Visual Insp During Install or Repair
001-1189	869	Eden Ct	Residential	869 Eden Ct	N	P	N	1"	2002	P	1.25"	5/13/2016	SF	UNK	O	2016	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/13/2016	Visual Insp During Install or Repair
001-1190	873	Eden Ct	Residential	873 Eden Ct	N	P	N	1"	2002	P	1.25"	10/3/2022	SF	UNK	O	2022	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/3/2022	Visual Insp During Install or Repair
001-1191	873	Fountain Way	Residential	873 Fountain Way	N	P	N	1"	2002	P	1.25"	12/7/2016	SF	UNK	O	2016	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/7/2016	Visual Insp During Install or Repair
001-1192	877	Fountain Way	Residential	877 Fountain Way	N	P	N	1"	2002	P	1"	2/9/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/9/2004	Visual Insp During Install or Repair
001-1193	881	Fountain Way	Residential	881 Fountain Way	N	P	N	1"	2002	P	1.25"	8/12/2021	SF	UNK	O	2021	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2021	Visual Insp During Install or Repair
001-1195	878	Whisper Falls Ln	Residential	878 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	11/12/2019	SF	UNK	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/12/2019	Visual Insp During Install or Repair
001-1196	874	Whisper Falls Ln	Residential	874 Whisper Falls Ln	N	P	N	1"	2002	P	1"	11/29/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2005	Visual Insp During Install or Repair
001-1197	870	Whisper Falls Ln	Residential	870 Whisper Falls Ln	N	P	N	1"	2002	P	1"	3/23/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/23/2005	Visual Insp During Install or Repair
001-1198	866	Whisper Falls Ln	Residential	866 Whisper Falls Ln	N	P	N	1"	2002	P	1"	3/2/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2005	Visual Insp During Install or Repair
001-1199	854	Whisper Falls Ln	Residential	854 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	10/30/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/2017	Visual Insp During Install or Repair
001-1200	850	Whisper Falls Ln	Residential	850 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	11/14/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/14/2007	Visual Insp During Install or Repair
001-1201	846	Whisper Falls Ln	Residential	846 Whisper Falls Ln	N	P	N	1"	2002	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-1202	842	Whisper Falls Ln	Residential	842 Whisper Falls Ln	N	P	N	1"	2002	P	1"	11/24/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/24/2004	Visual Insp During Install or Repair
001-1203	838	Whisper Falls Ln	Residential	838 Whisper Falls Ln	N	P	N	1"	2002	P	1"	10/14/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2004	Visual Insp During Install or Repair
001-1204	834	Whisper Falls Ln	Residential	834 Whisper Falls Ln	N	P	N	1"	2002	P	1"	10/29/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/29/2003	Visual Insp During Install or Repair
001-1205	830	Whisper Falls Ln	Residential	830 Whisper Falls Ln	N	P	N	1"	2002	P	1"	12/17/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/17/2003	Visual Insp During Install or Repair
001-1206	826	Whisper Falls Ln	Residential	826 Whisper Falls Ln	N	P	N	1"	2002	P	1"	1/6/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/6/2004	Visual Insp During Install or Repair
001-1207	818	Whisper Falls Ln	Residential	818 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	8/11/2020	SF	UNK	O	2020	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/2020	Visual Insp During Install or Repair
001-1208	814	Whisper Falls Ln	Residential	814 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	6/25/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/25/2018	Visual Insp During Install or Repair
001-1209	810	Whisper Falls Ln	Residential	810 Whisper Falls Ln	N	P	N	1"	2002	P	1.25"	11/29/2022	SF	UNK	O	2022	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/29/2022	Visual Insp During Install or Repair
001-1210	3020	Georgetown Pl	Residential	3020 Georgetown Pl	N	P	N	1"	2002	P	1.25"	11/6/2019	SF	UNK	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/6/2019	Visual Insp During Install or Repair
001-1213	821	Kelsey Brook Ct	Residential	821 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	6/10/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/10/2004	Visual Insp During Install or Repair
001-1214	825	Kelsey Brook Ct	Residential	825 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	11/23/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/23/2005	Visual Insp During Install or Repair
001-1215	829	Kelsey Brook Ct	Residential	829 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	10/4/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/4/2005	Visual Insp During Install or Repair
001-1216	833	Kelsey Brook Ct	Residential	833 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	10/14/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2003	Visual Insp During Install or Repair
001-1217	840	Kelsey Brook Ct	Residential	840 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	1/30/2003	SF	UNK	C	2003	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2003	Visual Insp During Install or Repair
001-1218	836	Kelsey Brook Ct	Residential	836 Kelsey Brook Ct	N	P	N	1"	2002	P	1.25"	3/28/2019	SF	UNK	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/28/2019	Visual Insp During Install or Repair
001-1219	832	Kelsey Brook Ct	Residential	832 Kelsey Brook Ct	N	P	N	1"	2002	P	1"	11/9/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/9/2005	Visual Insp During Install or Repair
001-1220	824	Kelsey Brook Ct	Residential	824 Kelsey Brook Ct	N	P	N	1"	2002	P	1.25"	6/25/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/25/2018	Visual Insp During Install or Repair
001-1221	820	Kelsey Brook Ct	Residential	820 Kelsey Brook Ct	N	P	N	1"	2002	P	1.25"	10/30/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/2017	Visual Insp During Install or Repair
001-1223	3004	Georgetown Pl	Residential	3004 Georgetown Pl	N	P	N	1"	2002	P	1.25"	4/23/2019	SF	UNK	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/23/2019	Visual Insp During Install or Repair
001-1224	3000	Georgetown Pl	Residential	3000 Georgetown Pl	N	P	N	1"	2002	P	1.25"	6/25/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/25/2018	Visual Insp During Install or Repair
001-1225	2996	Georgetown Pl	Residential	2996 Georgetown Pl	N	P	N	1"	2002	P	1.25"	2/12/2020	SF	UNK	O	2020	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/12/2020	Visual Insp During Install or Repair
001-1227	837	Fountain Way	Residential	837 Fountain Way	N	P	N	1"	2002	P	1.25"	5/2/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2006	Visual Insp During Install or Repair
001-1228	841	Fountain Way	Residential	841 Fountain Way	N	P	N	1"	2002	P	1.25"	5/9/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2006	Visual Insp During Install or Repair
001-1229	845	Fountain Way	Residential	845 Fountain Way	N	P	N	1"	2002	P	1.25"	6/7/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2018	Visual Insp During Install or Repair
001-1231	853	Fountain Way	Residential	853 Fountain Way	N	P	N	1"	2002	P	1.25"	6/8/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/8/2018	Visual Insp During Install or Repair
001-1232	857																							



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-1608	2421	Woodland Hills Dr	Residential	2421 Woodland Hills Dr	N	P	N	1"	2002	P	1.25"	5/20/2020	SF	UNK	O	2020	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/20/2020	Cross Connection Survey
001-1609	968	Kernan Ave	Residential	968 Kernan Ave	N	P	N	1"	2002	P	1"	5/17/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2004	Visual Insp During Install or Repair
001-1610	960	Kernan Ave	Residential	960 Kernan Ave	N	P	N	1"	2002	P	1"	1/16/2009	SF	Y	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2020	Cross Connection Survey
001-1611	948	Kernan Ave	Residential	948 Kernan Ave	N	P	N	1"	2002	P	1"	7/13/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/13/2006	Visual Insp During Install or Repair
001-1612	932	Kernan Ave	Residential	932 Kernan Ave	N	P	N	1"	2002	P	1.25"	8/29/2012	SF	UNK	O	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2012	Visual Insp During Install or Repair
001-1613	916	Kernan Ave	Residential	916 Kernan Ave	N	P	N	1"	2002	P	1.25"	8/29/2012	SF	UNK	O	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2012	Visual Insp During Install or Repair
001-1614	900	Kernan Ave	Residential	900 Kernan Ave	N	P	N	1"	2002	P	1"	7/27/2010	SF	N	C	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/11/2022	Cross Connection Survey
001-1615	884	Kernan Ave	Residential	884 Kernan Ave	N	P	N	1"	2002	P	1"	7/27/2010	SF	UNK	C	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/27/2010	Visual Insp During Install or Repair
001-1616	868	Kernan Ave	Residential	868 Kernan Ave	N	P	N	1"	2002	P	1"	8/25/2008	SF	N	C	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2019	Cross Connection Survey
001-1618	2464	Kelly Lake Dr	Residential	2464 Kelly Lake Dr	N	P	N	1"	2002	P	1"	10/25/2016	SF	UNK	O	2016	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/25/2016	Cross Connection Survey
001-1619	841	Kernan Ave	Residential	841 Kernan Ave	N	P	N	1"	2002	P	1.25"	3/21/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/21/2013	Visual Insp During Install or Repair
001-1620	857	Kernan Ave	Residential	857 Kernan Ave	N	P	N	1"	2002	P	1.25"	8/11/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/2017	Visual Insp During Install or Repair
001-1621	889	Kernan Ave	Residential	889 Kernan Ave	N	P	N	1"	2002	P	1"	1/19/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/19/2005	Visual Insp During Install or Repair
001-1622	905	Kernan Ave	Residential	905 Kernan Ave	N	P	N	1"	2002	P	1"	1/11/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/11/2005	Visual Insp During Install or Repair
001-1623	921	Kernan Ave	Residential	921 Kernan Ave	N	P	N	1"	2002	P	1"	8/19/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/19/2004	Visual Insp During Install or Repair
001-1624	929	Kernan Ave	Residential	929 Kernan Ave	N	P	N	1"	2002	P	1.25"	2/10/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/10/2014	Visual Insp During Install or Repair
001-1625	937	Kernan Ave	Residential	937 Kernan Ave	N	P	N	1"	2002	P	1"	4/30/2010	SF	N	O	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/7/2022	Cross Connection Survey
001-1626	953	Kernan Ave	Residential	953 Kernan Ave	N	P	N	1"	2002	P	1.25"	2/11/2020	SF	UNK	O	2020	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2020	Visual Insp During Install or Repair
001-1627	969	Kernan Ave	Residential	969 Kernan Ave	N	P	N	1"	2002	P	1"	7/20/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/20/2004	Visual Insp During Install or Repair
001-1628	985	Kernan Ave	Residential	985 Kernan Ave	N	P	N	1"	2002	P	1.25"	7/13/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/13/2017	Visual Insp During Install or Repair
001-1629	2441	Whistling Swan Ct	Residential	2441 Whistling Swan Ct	N	P	N	1"	2002	P	1.25"	9/11/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/11/2014	Visual Insp During Install or Repair
001-1630	2449	Whistling Swan Ct	Residential	2449 Whistling Swan Ct	N	P	N	1"	2002	P	1"	9/22/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/22/2005	Visual Insp During Install or Repair
001-1631	2457	Whistling Swan Ct	Residential	2457 Whistling Swan Ct	N	P	N	1"	2002	P	1"	7/27/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/27/2004	Visual Insp During Install or Repair
001-1632	2463	Whistling Swan Ct	Residential	2463 Whistling Swan Ct	N	P	N	1"	2002	P	1"	5/17/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2004	Visual Insp During Install or Repair
001-1633	2471	Whistling Swan Ct	Residential	2471 Whistling Swan Ct	N	P	N	1"	2002	P	1"	6/6/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/6/2005	Visual Insp During Install or Repair
001-1634	2475	Whistling Swan Ct	Residential	2475 Whistling Swan Ct	N	P	N	1"	2002	P	1"	5/25/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/25/2006	Visual Insp During Install or Repair
001-1635	2479	Whistling Swan Ct	Residential	2479 Whistling Swan Ct	N	P	N	1"	2002	P	1"	12/12/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/12/2006	Visual Insp During Install or Repair
001-1636	2483	Whistling Swan Ct	Residential	2483 Whistling Swan Ct	N	P	N	1"	2002	P	1"	1/9/2007	SF	UNK	C	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2007	Visual Insp During Install or Repair
001-1637	2487	Whistling Swan Ct	Residential	2487 Whistling Swan Ct	N	P	N	1"	2002	P	1.25"	1/30/2017	SF	UNK	O	2017	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2017	Visual Insp During Install or Repair
001-1638	2491	Whistling Swan Ct	Residential	2491 Whistling Swan Ct	N	P	N	1"	2002	P	1"	7/15/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2005	Visual Insp During Install or Repair
001-1639	2488	Whistling Swan Ct	Residential	2488 Whistling Swan Ct	N	P	N	1"	2002	P	1"	7/29/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/29/2005	Visual Insp During Install or Repair
001-1640	2480	Whistling Swan Ct	Residential	2480 Whistling Swan Ct	N	P	N	1"	2002	P	1"	8/3/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/3/2006	Visual Insp During Install or Repair
001-1641	2472	Whistling Swan Ct	Residential	2472 Whistling Swan Ct	N	P	N	1"	2002	P	1"	2/6/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2004	Visual Insp During Install or Repair
001-1642	2464	Whistling Swan Ct	Residential	2464 Whistling Swan Ct	N	P	N	1"	2002	P	1"	1/29/2007	SF	UNK	C	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2007	Visual Insp During Install or Repair
001-1643	2456	Whistling Swan Ct	Residential	2456 Whistling Swan Ct	N	P	N	1"	2002	P	1"	11/21/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/21/2006	Visual Insp During Install or Repair
001-1644	2448	Whistling Swan Ct	Residential	2448 Whistling Swan Ct	N	P	N	1"	2002	P	1"	11/4/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/4/2005	Visual Insp During Install or Repair
001-1645	1017	Kernan Ave	Residential	1017 Kernan Ave	N	P	N	1"	2002	P	1"	12/15/2003	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/15/2003	Visual Insp During Install or Repair
001-1646	1025	Kernan Ave	Residential	1025 Kernan Ave	N	P	N	1"	2002	P	1"	11/17/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/2004	Visual Insp During Install or Repair
001-1647	1033	Kernan Ave	Residential	1033 Kernan Ave	N	P	N	1"	2002	P	1"	2/14/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/14/2005	Visual Insp During Install or Repair
001-1648	1041	Kernan Ave	Residential	1041 Kernan Ave	N	P	N	1"	2002	P	1"	10/15/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/15/2013	Visual Insp During Install or Repair
001-1649	2484	Whistling Swan Ct	Residential	2484 Whistling Swan Ct	N	P	N	1"	2002	P	1"	1/28/2019	SF	N	O	2019	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-1651	1032	Kernan Ave	Residential	1032 Kernan Ave	N	P	N	1"	2002	P	1"	3/23/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/23/2005	Visual Insp During Install or Repair
001-1652	1016	Kernan Ave	Residential	1016 Kernan Ave	N	P	N	1"	2002	P	1"	2006	SF	N	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2023	Cross Connection Survey
001-1653	1000	Kernan Ave	Residential	1000 Kernan Ave	N	P	N	1"	2002	P	1"	7/2/2007	SF	UNK	C	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/2/2007	Visual Insp During Install or Repair
001-1654	2412	Woodland Hills Dr	Residential	2412 Woodland Hills Dr	N	P	N	1"	2002	P	1"	12/17/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/17/2004	Visual Insp During Install or Repair
001-1655	2404	Woodland Hills Dr	Residential	2404 Woodland Hills Dr	N	P	N	1"	2002	P	1.25"	9/4/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/4/2014	Visual Insp During Install or Repair
001-1656	2383	Trumpeter Swan Ln	Residential	2383 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	7/13/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/13/2006	Visual Insp During Install or Repair
001-1657	2391	Trumpeter Swan Ln	Residential	2391 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	8/27/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/27/2004	Visual Insp During Install or Repair
001-1658	2399	Trumpeter Swan Ln	Residential	2399 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	11/2/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/2/2004	Visual Insp During Install or Repair
001-1659	2407	Trumpeter Swan Ln	Residential	2407 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	1/20/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2005	Visual Insp During Install or Repair
001-1660	2415	Trumpeter Swan Ln	Residential	2415 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	6/30/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/30/2005	Visual Insp During Install or Repair
001-1661	1064	Kernan Ave	Residential	1064 Kernan Ave	N	P	N	1"	2002	P	1"	3/1/2004	SF	UNK	C	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/1/2004	Visual Insp During Install or Repair
001-1662	2432	Trumpeter Swan Ln	Residential	2432 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	10/24/2012	SF	UNK	C	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/24/2012	Visual Insp During Install or Repair
001-1663	2424	Trumpeter Swan Ln	Residential	2424 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	2/7/2006	SF	UNK	C	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2006	Visual Insp During Install or Repair
001-1664	2416	Trumpeter Swan Ln	Residential	2416 Trumpeter Swan Ln	N	P	N	1"	2002	P	1"	10/3/2005	SF	UNK	C	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/3/2005	Visual Insp During Install or Repair
001-1665	2408	Trumpeter Swan Ln	Residential	2408 Trumpeter Swan Ln	N	P	N	1"	2002	P	1.25"	4/3/2018	SF	UNK	O	2018	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/3/2018	Visual Insp During Install or Repair
001-1666	2400	Trumpeter Swan Ln	Residential	2400 Trumpeter Swan Ln	N	P	N	1"	2002	P	1.25"	5/30/2018	SF	UNK	O	2018	Installation Record	Y</						







LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-3006	1161	Silver Birch Dr	Residential	1161 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	7/1/2008	SF	UNK	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	7/1/2008	Visual Insp During Install or Repair
001-3007	1153	Silver Birch Dr	Residential	1153 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	6/7/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2012	Visual Insp During Install or Repair
001-3008	1145	Silver Birch Dr	Residential	1145 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	5/17/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2012	Visual Insp During Install or Repair
001-3009	1137	Silver Birch Dr	Residential	1137 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	10/18/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/2012	Visual Insp During Install or Repair
001-3010	1129	Silver Birch Dr	Residential	1129 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	3/1/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/1/2013	Visual Insp During Install or Repair
001-3011	1121	Silver Birch Dr	Residential	1121 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	3/1/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/1/2013	Visual Insp During Install or Repair
001-3012	1113	Silver Birch Dr	Residential	1113 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	3/1/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/1/2013	Visual Insp During Install or Repair
001-3013	1105	Silver Birch Dr	Residential	1105 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	4/30/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/30/2013	Visual Insp During Install or Repair
001-3014	1097	Silver Birch Dr	Residential	1097 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	4/25/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2013	Visual Insp During Install or Repair
001-3015	1089	Silver Birch Dr	Residential	1089 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	4/25/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2013	Visual Insp During Install or Repair
001-3016	1081	Silver Birch Dr	Residential	1081 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	4/25/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/25/2013	Visual Insp During Install or Repair
001-3017	1073	Silver Birch Dr	Residential	1073 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	8/26/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2020	Cross Connection Survey
001-3018	1065	Silver Birch Dr	Residential	1065 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	1/27/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/8/2020	Cross Connection Survey
001-3019	1068	Silver Birch Dr	Residential	1068 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	12/19/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
001-3020	2926	Silver Birch Ct	Residential	2926 Silver Birch Ct	N	P	N	1.25"	2006	P	1.25"	8/30/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/30/2007	Visual Insp During Install or Repair
001-3021	2934	Silver Birch Ct	Residential	2934 Silver Birch Ct	N	P	N	1.25"	2006	P	1.25"	9/14/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/14/2007	Visual Insp During Install or Repair
001-3022	2942	Silver Birch Ct	Residential	2942 Silver Birch Ct	N	P	N	1.25"	2006	P	1.25"	8/5/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2019	Cross Connection Survey
001-3023	2950	Silver Birch Ct	Residential	2950 Silver Birch Ct	N	P	N	1.25"	2006	P	1.25"	10/22/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/13/2020	Cross Connection Survey
001-3024	1092	Silver Birch Dr	Residential	1092 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	5/29/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	5/29/2013	Visual Insp During Install or Repair
001-3025	1100	Silver Birch Dr	Residential	1100 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	8/8/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/2007	Visual Insp During Install or Repair
001-3026	1108	Silver Birch Dr	Residential	1108 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	7/7/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2019	Cross Connection Survey
001-3027	1116	Silver Birch Dr	Residential	1116 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	10/23/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/23/2007	Visual Insp At Meter
001-3028	1124	Silver Birch Dr	Residential	1124 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	4/24/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
001-3029	1132	Silver Birch Dr	Residential	1132 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	10/3/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/3/2012	Visual Insp During Install or Repair
001-3030	1140	Silver Birch Dr	Residential	1140 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	10/30/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/30/2012	Visual Insp During Install or Repair
001-3031	1148	Silver Birch Dr	Residential	1148 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	3/2/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2007	Visual Insp During Install or Repair
001-3032	1156	Silver Birch Dr	Residential	1156 Silver Birch Dr	N	P	N	1.25"	2006	P	1.25"	7/16/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/4/2019	Cross Connection Survey
001-3033	1149	Birling Dr	Residential	1149 Birling Dr	N	P	N	1.25"	2006	P	1.25"	9/19/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/19/2012	Visual Insp During Install or Repair
001-3034	1141	Birling Dr	Residential	1141 Birling Dr	N	P	N	1.25"	2006	P	1.25"	4/16/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/16/2012	Visual Insp During Install or Repair
001-3035	2959	Birling Ct	Residential	2959 Birling Ct	N	P	N	1.25"	2006	P	1.25"	1/26/2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2022	Cross Connection Survey
001-3036	2951	Birling Ct	Residential	2951 Birling Ct	N	P	N	1.25"	2006	P	1.25"	4/2/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/21/2020	Cross Connection Survey
001-3037	2943	Birling Ct	Residential	2943 Birling Ct	N	P	N	1.25"	2006	P	1.25"	7/18/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	7/18/2013	Visual Insp During Install or Repair
001-3038	2935	Birling Ct	Residential	2935 Birling Ct	N	P	N	1.25"	2006	P	1.25"	9/24/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/24/2013	Visual Insp During Install or Repair
001-3039	2927	Birling Ct	Residential	2927 Birling Ct	N	P	N	1.25"	2006	P	1.25"	9/12/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/12/2007	Visual Insp During Install or Repair
001-3040	2919	Birling Ct	Residential	2919 Birling Ct	N	P	N	1.25"	2006	P	1.25"	3/7/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-3041	2911	Birling Ct	Residential	2911 Birling Ct	N	P	N	1.25"	2006	P	1.25"	10/10/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
001-3042	2903	Birling Ct	Residential	2903 Birling Ct	N	P	N	1.25"	2006	P	1.25"	12/5/2007	SF	UNK	O	2007	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	12/5/2007	Visual Insp During Install or Repair
001-3043	1124	Birling Dr	Residential	1124 Birling Dr	N	P	N	1.25"	2006	P	1.25"	9/11/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/11/2012	Visual Insp During Install or Repair
001-3044	1132	Birling Dr	Residential	1132 Birling Dr	N	P	N	1.25"	2006	P	1.25"	4/4/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2012	Visual Insp During Install or Repair
001-3045	1140	Birling Dr	Residential	1140 Birling Dr	N	P	N	1.25"	2006	P	1.25"	4/4/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2012	Visual Insp During Install or Repair
001-3046	1148	Birling Dr	Residential	1148 Birling Dr	N	P	N	1.25"	2006	P	1.25"	9/10/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/10/2012	Visual Insp During Install or Repair
001-3047	1156	Birling Dr	Residential	1156 Birling Dr	N	P	N	1.25"	2006	P	1.25"	9/10/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/10/2012	Visual Insp During Install or Repair
001-3048	1164	Birling Dr	Residential	1164 Birling Dr	N	P	N	1.25"	2006	P	1.25"	3/5/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/20/2019	Cross Connection Survey
001-3049	2891	Birling Ct	Residential	2891 Birling Ct	N	P	N	1.25"	2006	P	1.25"	10/22/2015	SF	UNK	O	2015	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/22/2015	Visual Insp During Install or Repair
001-4000	W6254	HWY 10 & 114	Commercial	W6254 HWY 10 & 114	N	P	N	8"	2003	P	8"	2003	NONRES	C	3/18/2003	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	11/16/2022	Cross Connection Survey	
001-4002	N8728	S Coop Rd	Commercial	N8728 S Coop Rd	N	P	N	2"	2004	P	2"	2004	NONRES	UNK	C	2004	Installation Record	Y	2004	Visual Insp During Install or Repair	Field Inspection Only	Y	12/20/2023	Cross Connection Survey
001-4005	N8722	Lake Park Rd	Public Auth.	N8722 Lake Park Rd	N	P	N	4"	2000	P	4"	2001	NONRES	N	C	2001	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2001	Visual Insp During Install or Repair
001-4010	N8770	Lake Park Rd	Commercial	N8770 Lake Park Rd	N	P	N	2"	2000	P	2"	2014	NONRES	UNK	C	2014	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	12/28/2022	Cross Connection Survey
001-4020	N8904	Lake Park Rd	Commercial	N8904 Lake Park Rd	N	P	N	1"	2000	P	1"	2002	NONRES	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2023	Cross Connection Survey
001-4023	N8930	Lake Park Rd	Commercial	N8930 Lake Park Rd	N	P	N	1"	2000	P	1"	2002	NONRES	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/25/2024	Cross Connection Survey
001-4024	N8918	Lake Park Rd	Residential	N8918 Lake Park Rd	N	P	N	1"	2000	P	1"	9/26/2002	SF	UNK	O	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	9/26/2002	Visual Insp During Install or Repair
001-4025	N8924	Lake Park Rd	Commercial	N8924 Lake Park Rd	N	P	N	1.5"	2000	P	1.5"	2002	NONRES	N	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	11/13/2022	Cross Connection Survey
001-4026	N8924	Lake Park Rd	Commercial	N8924 Lake Park Rd	N	P	N	2"	2000	P	2"	7/11/2002	NONRES	UNK	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	11/13/2023	Cross Connection Survey
001-4030	N8956	Lake Park Rd	Residential	N8956 Lake Park Rd	N	P	N	1"	2000	P	1"	3/21/2002	SF	UNK	C	2002	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	3/21/2002	Visual Insp During Install or Repair
001-4035	N8974	Lake Park Rd	Residential	N8974 Lake Park Rd	N	P	N	1"	2000	P	1"	5/6/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	5/6/2003	Visual Insp During Install or Repair
001-4040	N8990	Lake Park Rd	Residential	N8990 Lake Park Rd	N	P	N	1"	2000	P	1"	4/8/2003	SF	UNK	C	2003	Installation Record	Y	2000	Visual Insp During Install or Repair	Field Inspection Only	Y	4/8/2003	Visual Insp During Install or Repair
001-4042	N9009	Lake Park Rd	Residential	N9009 Lake Park Rd	N	P	N																	



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-4126	W6393	Sonny Dr	Multifam Res	W6393 Sonny Dr	N	P	N	4"	2014	p	4"	2/23/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4127	W6395	Sonny Dr	Multifam Res	W6395 Sonny Dr	N	P	N	4"	2014	p	4"	4/20/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4128	W6397	Sonny Dr	Multifam Res	W6397 Sonny Dr	N	P	N	4"	2014	p	4"	6/5/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4129	W6391	Sonny Dr	Multifam Res	W6391 Sonny Dr	N	P	N	4"	2014	p	4"	8/2/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4130	W6389	Sonny Dr	Multifam Res	W6389 Sonny Dr	N	P	N	4"	2014	p	4"	9/21/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4131	W6347	Sonny Dr	Multifam Res	W6347 Sonny Dr	N	P	N	4"	2014	p	4"	9/20/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4132	W6349	Sonny Dr	Multifam Res	W6349 Sonny Dr	N	P	N	4"	2014	p	4"	9/20/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4133	W6351	Sonny Dr	Multifam Res	W6351 Sonny Dr	N	P	N	4"	2014	p	4"	9/20/2017	MF	N	O	2017	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4134	W6399	Sonny Dr	Commercial	W6399 Sonny Dr	N	P	N	1.25"	2014	p	1.25"	11/14/2014	NONRES	N	O	2014	Visual Insp During Install or Repair	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2023	Cross Connection Survey
001-4201	W6120	Hemlock Ln	Residential	W6120 Hemlock Ln	N	P	N	1.5"	2002	P	1.25"	7/13/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/13/2006	Visual Insp During Install or Repair
001-4202	W6128	Hemlock Ln	Residential	W6128 Hemlock Ln	N	P	N	1.5"	2002	P	1"	3/2/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2004	Visual Insp During Install or Repair
001-4203	W6136	Hemlock Ln	Residential	W6136 Hemlock Ln	N	P	N	1.5"	2002	P	1"	7/9/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/9/2004	Visual Insp During Install or Repair
001-4204	W6144	Hemlock Ln	Residential	W6144 Hemlock Ln	N	P	N	1.5"	2002	P	1"	7/20/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/20/2004	Visual Insp During Install or Repair
001-4205	W6152	Hemlock Ln	Residential	W6152 Hemlock Ln	N	P	N	1.5"	2002	P	1"	9/21/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2004	Visual Insp During Install or Repair
001-4206	W6153	Maple Bluff Ln	Residential	W6153 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	11/24/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/24/2004	Visual Insp During Install or Repair
001-4207	W6145	Maple Bluff Ln	Residential	W6145 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	10/14/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/14/2004	Visual Insp During Install or Repair
001-4208	W6137	Maple Bluff Ln	Residential	W6137 Maple Bluff Ln	N	P	N	1.5"	2002	P	1.25"	9/12/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/12/2007	Visual Insp During Install or Repair
001-4209	W6129	Maple Bluff Ln	Residential	W6129 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	4/13/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/13/2005	Visual Insp During Install or Repair
001-4210	W6121	Maple Bluff Ln	Residential	W6121 Maple Bluff Ln	N	P	N	1.5"	2002	P	1.25"	6/7/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2007	Visual Insp During Install or Repair
001-4211	W6117	Wild Cherry Ct	Residential	W6117 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	11/30/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/30/2005	Visual Insp During Install or Repair
001-4212	W6125	Wild Cherry Ct	Residential	W6125 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	5/19/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/19/2005	Visual Insp During Install or Repair
001-4213	W6133	Wild Cherry Ct	Residential	W6133 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	4/10/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/10/2006	Visual Insp During Install or Repair
001-4214	W6141	Wild Cherry Ct	Residential	W6141 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	6/29/2010	SF	UNK	O	2010	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/29/2010	Visual Insp During Install or Repair
001-4215	W6149	Wild Cherry Ct	Residential	W6149 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.5"	7/29/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	2/15/2019	Cross Connection Survey
001-4216	W6157	Wild Cherry Ct	Residential	W6157 Wild Cherry Ct	N	P	N	1.5"	2002	P	1"	8/12/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2004	Visual Insp During Install or Repair
001-4217	W6158	Wild Cherry Ct	Residential	W6158 Wild Cherry Ct	N	P	N	1.5"	2002	P	1"	3/12/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2004	Visual Insp During Install or Repair
001-4218	W6150	Wild Cherry Ct	Residential	W6150 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	11/30/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/30/2005	Visual Insp During Install or Repair
001-4219	W6142	Wild Cherry Ct	Residential	W6142 Wild Cherry Ct	N	P	N	1.5"	2002	P	1.25"	4/10/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/10/2006	Visual Insp During Install or Repair
001-4220	W6134	Wild Cherry Ct	Residential	W6134 Wild Cherry Ct	N	P	N	1.5"	2002	P	1"	7/20/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/20/2004	Visual Insp During Install or Repair
001-4221	W6126	Wild Cherry Ct	Residential	W6126 Wild Cherry Ct	N	P	N	1.5"	2002	P	1"	1/20/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2005	Visual Insp During Install or Repair
001-4222	W6118	Wild Cherry Ct	Residential	W6118 Wild Cherry Ct	N	P	N	1.5"	2002	P	1"	4/19/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/19/2004	Visual Insp During Install or Repair
001-4223	W6119	Hemlock Ln	Residential	W6119 Hemlock Ln	N	P	N	1.5"	2002	P	1.25"	11/6/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	11/6/2007	Visual Insp During Install or Repair
001-4224	W6127	Hemlock Ln	Residential	W6127 Hemlock Ln	N	P	N	1.5"	2002	P	1.25"	7/14/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/14/2005	Visual Insp During Install or Repair
001-4225	W6135	Hemlock Ln	Residential	W6135 Hemlock Ln	N	P	N	1.5"	2002	P	1.5"	2005	SF	N	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/26/2023	Cross Connection Survey
001-4226	W6143	Hemlock Ln	Residential	W6143 Hemlock Ln	N	P	N	1.5"	2002	P	1.25"	12/28/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/28/2005	Visual Insp During Install or Repair
001-4227	W6151	Hemlock Ln	Residential	W6151 Hemlock Ln	N	P	N	1.5"	2002	P	1"	9/21/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2004	Visual Insp During Install or Repair
001-4228	W6159	Hemlock Ln	Residential	W6159 Hemlock Ln	N	P	N	1.5"	2002	P	1"	6/10/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/10/2004	Visual Insp During Install or Repair
001-4229	N8941	Box Elder Way	Residential	N8941 Box Elder Way	N	P	N	1.5"	2002	P	1"	12/17/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/17/2004	Visual Insp During Install or Repair
001-4230	N8947	Box Elder Way	Residential	N8947 Box Elder Way	N	P	N	1.5"	2002	P	1"	7/7/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/7/2004	Visual Insp During Install or Repair
001-4231	N8953	Box Elder Way	Residential	N8953 Box Elder Way	N	P	N	1.5"	2002	P	1.25"	2011	SF	N	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/16/2023	Cross Connection Survey
001-4232	N8959	Box Elder Way	Residential	N8959 Box Elder Way	N	P	N	1.5"	2002	P	1.25"	8/17/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/17/2007	Visual Insp During Install or Repair
001-4233	W6162	Maple Bluff Ln	Residential	W6162 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	8/12/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/12/2004	Visual Insp During Install or Repair
001-4234	W6154	Maple Bluff Ln	Residential	W6154 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	10/5/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2004	Visual Insp During Install or Repair
001-4235	W6146	Maple Bluff Ln	Residential	W6146 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	10/5/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2004	Visual Insp During Install or Repair
001-4236	W6138	Maple Bluff Ln	Residential	W6138 Maple Bluff Ln	N	P	N	1.5"	2002	P	1.25"	4/21/2006	SF	UNK	O	2006	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2006	Visual Insp During Install or Repair
001-4237	W6130	Maple Bluff Ln	Residential	W6130 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	12/21/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/21/2004	Visual Insp During Install or Repair
001-4238	W6122	Maple Bluff Ln	Residential	W6122 Maple Bluff Ln	N	P	N	1.5"	2002	P	1"	5/17/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2004	Visual Insp During Install or Repair
001-4239	W6123	Shagbark Hickory Ln	Residential	W6123 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1"	7/24/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	7/24/2004	Visual Insp During Install or Repair
001-4240	W6131	Shagbark Hickory Ln	Residential	W6131 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1"	6/10/2005	SF	UNK	O	2005	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/10/2005	Visual Insp During Install or Repair
001-4241	W6139	Shagbark Hickory Ln	Residential	W6139 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1.25"	9/12/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/12/2007	Visual Insp During Install or Repair
001-4242	W6147	Shagbark Hickory Ln	Residential	W6147 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1"	5/17/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2004	Visual Insp During Install or Repair
001-4243	W6155	Shagbark Hickory Ln	Residential	W6155 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1"	5/17/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/17/2004	Visual Insp During Install or Repair
001-4244	W6163	Shagbark Hickory Ln	Residential	W6163 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1.5"	7/1/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/31/2019	Cross Connection Survey
001-4245	W6171	Shagbark Hickory Ln	Residential	W6171 Shagbark Hickory Ln	N	P	N	1.5"	2002	P	1.25"	6/7/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2007	Visual Insp During Install or Repair
001-4246	N8906	Sugar Maple Way	Residential	N8906 Sugar Maple Way	N	P	N	1.5"	2002	P	1"	3/12/2004	SF	UNK	O	2004	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/12/2004	Visual Insp During Install or Repair
001-4247	N8914	Sugar Maple Way	Residential	N8914 Sugar Maple Way	N	P	N	1.5"	2002	P	1.25"	4/17/2006	SF	UNK	O	2006	Installation Record	Y						

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING G TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-4414	N8591	Winding Trail Dr	Residential	N8591 Winding Trail Dr	N	P	N	1"	2003	P	1"	10/23/2018	SF	UNK	O	2018	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/26/2018	Visual Insp During Install or Repair
001-4415	N8585	Winding Trail Dr	Residential	N8585 Winding Trail Dr	N	P	N	1"	2003	P	1"	1/20/2015	SF	UNK	O	2015	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	9/11/2014	Visual Insp During Install or Repair
001-4416	N8579	Winding Trail Dr	Residential	N8579 Winding Trail Dr	N	P	N	1"	2003	P	1"	5/6/2014	SF	UNK	O	2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/6/2014	Visual Insp During Install or Repair
001-4417	N8573	Winding Trail Dr	Residential	N8573 Winding Trail Dr	N	P	N	1"	2003	P	1"	6/12/2014	SF	UNK	O	2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/2014	Visual Insp During Install or Repair
001-4418	N8569	Winding Trail Dr	Residential	N8569 Winding Trail Dr	N	P	N	1"	2003	P	1"	5/10/2006	SF	UNK	O	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/10/2006	Visual Insp During Install or Repair
001-4419	N8572	Winding Trail Dr	Residential	N8572 Winding Trail Dr	N	P	N	1"	2003	P	1"	7/31/2014	SF	UNK	O	2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	5/21/2014	Visual Insp During Install or Repair
001-4420	N8578	Winding Trail Dr	Residential	N8578 Winding Trail Dr	N	P	N	1"	2003	P	1"	6/25/2015	SF	UNK	O	2015	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/17/2015	Visual Insp During Install or Repair
001-4421	N8586	Winding Trail Dr	Residential	N8586 Winding Trail Dr	N	P	N	1"	2003	P	1"	1/22/2020	SF	UNK	O	2020	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/27/2020	Visual Insp During Install or Repair
001-4422	N8594	Winding Trail Dr	Residential	N8594 Winding Trail Dr	N	P	N	1"	2003	P	1"	10/20/2016	SF	UNK	O	2016	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/5/2016	Visual Insp During Install or Repair
001-4423	N8602	Winding Trail Dr	Residential	N8602 Winding Trail Dr	N	P	N	1"	2003	P	1"	9/7/2010	SF	UNK	O	2010	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	9/7/2010	Visual Insp During Install or Repair
001-4424	N8608	Winding Trail Dr	Residential	N8608 Winding Trail Dr	N	P	N	1"	2003	P	1"	9/26/2016	SF	UNK	O	2016	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/23/2016	Visual Insp During Install or Repair
001-4425	N8616	Winding Trail Dr	Residential	N8616 Winding Trail Dr	N	P	N	1"	2003	P	1.25"	11/1/2011	SF	Y	O	2011	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2024	Cross Connection Survey
001-4426	N8626	Winding Trail Dr	Residential	N8626 Winding Trail Dr	N	P	N	1"	2003	P	1"	9/29/2015	SF	UNK	O	2015	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	7/29/2015	Visual Insp During Install or Repair
001-4427	N8634	Winding Trail Dr	Residential	N8634 Winding Trail Dr	N	P	N	1"	2003	P	1"	4/27/2005	SF	UNK	O	2005	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	4/27/2005	Visual Insp During Install or Repair
001-4428	N8642	Winding Trail Dr	Residential	N8642 Winding Trail Dr	N	P	N	1"	2003	P	1"	3/3/2009	SF	N	O	2009	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/22/2020	Cross Connection Survey
001-4429	N8648	Winding Trail Dr	Residential	N8648 Winding Trail Dr	N	P	N	1"	2003	P	1"	11/26/2014	SF	UNK	O	2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/7/2014	Visual Insp During Install or Repair
001-4430	N8654	Winding Trail Dr	Residential	N8654 Winding Trail Dr	N	P	N	1"	2003	P	1"	10/7/2014	SF	UNK	O	2014	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	8/11/2014	Visual Insp During Install or Repair
001-4435	N8486	North Shore Rd	Residential	N8486 North Shore Rd	N	P	N	1"	2003	P	1"	1/3/2006	SF	UNK	C	2006	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	1/3/2006	Visual Insp During Install or Repair
001-4440	N8526	North Shore Rd	Residential	N8526 North Shore Rd	N	P	N	1.25"	2003	P	1.25"	10/21/2009	SF	N	C	2009	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2020	Cross Connection Survey
001-4445	N8566	North Shore Rd	Residential	N8566 North Shore Rd	N	P	N	1"	2003	P	1.25"	10/11/2012	SF	UNK	O	2012	Installation Record	Y	2003	Visual Insp During Install or Repair	Field Inspection Only	Y	10/11/2012	Visual Insp During Install or Repair
001-4501	W6174	Education Way	Residential	W6174 Education Way	N	P	N	1"	2002	P	1.25"	6/10/2015	SF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	4/30/2015	Visual Insp During Install or Repair
001-4502	N9028	Spring Valley Rd	Residential	N9028 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	8/20/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/20/2013	Visual Insp During Install or Repair
001-4503	N9034	Spring Valley Rd	Residential	N9034 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	6/10/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/10/2013	Visual Insp During Install or Repair
001-4504	N9040	Spring Valley Rd	Residential	N9040 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	6/7/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/7/2013	Visual Insp During Install or Repair
001-4505	N9046	Spring Valley Rd	Residential	N9046 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	8/14/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/14/2013	Visual Insp During Install or Repair
001-4506	N9050	Spring Valley Rd	Residential	N9050 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	6/5/2012	SF	UNK	O	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/5/2012	Visual Insp During Install or Repair
001-4507	N9052	Spring Valley Rd	Residential	N9052 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	6/5/2012	SF	UNK	O	2012	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/5/2012	Visual Insp During Install or Repair
001-4508	N9060	Spring Valley Rd	Residential	N9060 Spring Valley Rd	N	P	N	1"	2002	P	1"	6/19/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/6/2019	Cross Connection Survey
001-4509	N9062	Spring Valley Rd	Residential	N9062 Spring Valley Rd	N	P	N	1"	2002	P	1"	6/19/2008	SF	N	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
001-4510	N9070	Spring Valley Rd	Residential	N9070 Spring Valley Rd	N	P	N	1"	2002	P	1"	10/9/2015	SF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/16/2015	Visual Insp During Install or Repair
001-4511	N9072	Spring Valley Rd	Residential	N9072 Spring Valley Rd	N	P	N	1"	2002	P	1"	10/9/2015	SF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/17/2015	Visual Insp During Install or Repair
001-4512	N9078	Spring Valley Rd	Residential	N9078 Spring Valley Rd	N	P	N	1"	2002	P	1"	10/18/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/18/2007	Visual Insp During Install or Repair
001-4513	N9080	Spring Valley Rd	Residential	N9080 Spring Valley Rd	N	P	N	1"	2002	P	1"	6/18/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/18/2007	Visual Insp During Install or Repair
001-4514	N9088	Spring Valley Rd	Residential	N9088 Spring Valley Rd	N	P	N	1"	2002	P	1"	11/19/2015	SF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2015	Visual Insp During Install or Repair
001-4515	N9090	Spring Valley Rd	Residential	N9090 Spring Valley Rd	N	P	N	1"	2002	P	1"	11/19/2015	SF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/21/2015	Visual Insp During Install or Repair
001-4516	N9089	Spring Valley Rd	Residential	N9089 Spring Valley Rd	N	P	N	1"	2002	P	1.25"	9/9/2015	MF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/9/2015	Visual Insp During Install or Repair
001-4517	N9087	Spring Valley Rd	Residential	N9087 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	9/9/2015	MF	UNK	O	2015	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	9/9/2015	Visual Insp During Install or Repair
001-4518	N9081	Spring Valley Rd	Residential	N9081 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	8/11/2011	SF	N	O	2011	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/9/2023	Cross Connection Survey
001-4519	N9079	Spring Valley Rd	Residential	N9079 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	8/11/2011	SF	N	O	2011	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/15/2023	Cross Connection Survey
001-4520	N9073	Spring Valley Rd	Residential	N9073 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	8/8/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/2013	Visual Insp During Install or Repair
001-4521	N9069	Spring Valley Rd	Residential	N9069 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	1/10/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/10/2014	Visual Insp During Install or Repair
001-4522	N9063	Spring Valley Rd	Residential	N9063 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	12/2/2013	SF	UNK	O	2013	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/2/2013	Visual Insp During Install or Repair
001-4523	N9059	Spring Valley Rd	Residential	N9059 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	12/3/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	12/3/2014	Visual Insp During Install or Repair
001-4524	N9055	Spring Valley Rd	Residential	N9055 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	5/7/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/7/2014	Visual Insp During Install or Repair
001-4526	N9049	Spring Valley Rd	Residential	N9049 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	3/5/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2007	Visual Insp During Install or Repair
001-4527	N9047	Spring Valley Rd	Residential	N9047 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	3/15/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2007	Visual Insp During Install or Repair
001-4528	N9039	Spring Valley Rd	Residential	N9039 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	10/13/2009	MF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2022	Cross Connection Survey
001-4529	N9037	Spring Valley Rd	Residential	N9037 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	9/28/2009	MF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
001-4530	N9031	Spring Valley Rd	Residential	N9031 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	10/2/2008	SF	UNK	O	2008	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	10/2/2008	Visual Insp During Install or Repair
001-4531	N9029	Spring Valley Rd	Residential	N9029 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	10/2/2008	MF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-4532	N9023	Spring Valley Rd	Residential	N9023 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	7/27/2009	MF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	1/16/2020	Cross Connection Survey
001-4533	N9021	Spring Valley Rd	Residential	N9021 Spring Valley Rd	N	P	N	1.5"	2002	P	1.5"	7/27/2009	MF	N	O	2009	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/10/2020	Cross Connection Survey
001-4534	N9009	Spring Valley Rd	Residential	N9009 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	3/15/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2007	Visual Insp During Install or Repair
001-4535	N9007	Spring Valley Rd	Residential	N9007 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	3/15/2007	SF	UNK	O	2007	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2007	Visual Insp During Install or Repair
001-4536	N8999	Spring Valley Rd	Residential	N8999 Spring Valley Rd	N	P	N	1.5"	2002	P	1.25"	5/30/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	5/30/2014	Visual Insp During Install or Repair
001-4537	N8993	Spring Valley Rd	Residential	N8993 Spring Valley Rd	N	P	N	1.25"	2002	P	1.25"	6/3/2014	SF	UNK	O	2014	Installation Record	Y	2002	Visual Insp During Install or Repair	Field Inspection Only	Y	6/3/2014	Visual Insp During Install or Repair
001-4538	N8989	Spring Valley Rd	Residential	N8989 Spring Valley Rd	N	P	N	1.5"	2002</															





LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-6011	N9005	Blackoak St	Residential	N9005 Blackoak St	N	P	N	1.25"	2006	P	1.25"	11/1/2011	SF	Y	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/13/2024	Cross Connection Survey
001-6012	W6437	Cherrybark Cir	Residential	W6437 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	5/13/2010	SF	Y	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/12/2022	Cross Connection Survey
001-6013	W6441	Cherrybark Cir	Residential	W6441 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	7/15/2010	SF	UNK	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2010	Visual Insp During Install or Repair
001-6014	W6445	Cherrybark Cir	Residential	W6445 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	6/16/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/4/2019	Cross Connection Survey
001-6015	W6449	Cherrybark Cir	Residential	W6449 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/29/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/29/2012	Visual Insp During Install or Repair
001-6016	W6453	Cherrybark Cir	Residential	W6453 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/7/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2019	Cross Connection Survey
001-6017	W6457	Cherrybark Cir	Residential	W6457 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	1/30/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2019	Cross Connection Survey
001-6019	W6461	Cherrybark Cir	Residential	W6461 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	11/22/2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2022	Cross Connection Survey
001-6019	W6465	Cherrybark Cir	Residential	W6465 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/7/2009	SF	UNK	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/2009	Visual Insp During Install or Repair
001-6020	W6471	Cherrybark Cir	Residential	W6471 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/5/2023	Cross Connection Survey
001-6021	W6475	Cherrybark Cir	Residential	W6475 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	9/17/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/9/2020	Cross Connection Survey
001-6022	W6480	Cherrybark Cir	Residential	W6480 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/24/2011	SF	N	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/6/2024	Cross Connection Survey
001-6023	W6484	Cherrybark Cir	Residential	W6484 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/2/2023	Cross Connection Survey
001-6024	W6488	Cherrybark Cir	Residential	W6488 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/2023	Cross Connection Survey
001-6025	W6492	Cherrybark Cir	Residential	W6492 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	1/7/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/7/2013	Visual Insp During Install or Repair
001-6026	N9057	Blackoak St	Residential	N9057 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2023	Cross Connection Survey
001-6027	N9063	Blackoak St	Residential	N9063 Blackoak St	N	P	N	1.25"	2006	P	1.25"	10/31/2011	SF	UNK	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/31/2011	Cross Connection Survey
001-6028	W6429	Sawtooth Ct	Residential	W6429 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	9/25/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/25/2013	Visual Insp During Install or Repair
001-6029	W6437	Sawtooth Ct	Residential	W6437 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	3/28/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2019	Cross Connection Survey
001-6030	W6447	Sawtooth Ct	Residential	W6447 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	11/4/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/1/2019	Cross Connection Survey
001-6031	W6455	Sawtooth Ct	Residential	W6455 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	5/7/2014	SF	N	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-6032	W6456	Sawtooth Ct	Residential	W6456 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	1/31/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/15/2019	Cross Connection Survey
001-6033	W6448	Sawtooth Ct	Residential	W6448 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	6/24/2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/3/2022	Cross Connection Survey
001-6034	W6438	Sawtooth Ct	Residential	W6438 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	7/15/2014	SF	UNK	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	7/15/2014	Visual Insp During Install or Repair
001-6035	W6430	Sawtooth Ct	Residential	W6430 Sawtooth Ct	N	P	N	1.25"	2006	P	1.25"	4/15/2016	SF	UNK	O	2016	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/15/2016	Visual Insp During Install or Repair
001-6036	N9088	Blackoak St	Residential	N9088 Blackoak St	N	P	N	1.25"	2006	P	1.25"	12/22/2015	SF	UNK	O	2015	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	12/22/2015	Visual Insp During Install or Repair
001-6037	N9080	Blackoak St	Residential	N9080 Blackoak St	N	P	N	1.25"	2006	P	1.25"	3/18/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/18/2013	Visual Insp During Install or Repair
001-6038	N9072	Blackoak St	Residential	N9072 Blackoak St	N	P	N	1.25"	2006	P	1.25"	1/21/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/21/2013	Visual Insp During Install or Repair
001-6039	N9064	Blackoak St	Residential	N9064 Blackoak St	N	P	N	1.25"	2006	P	1.25"	6/22/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	6/22/2012	Visual Insp During Install or Repair
001-6040	N9058	Blackoak St	Residential	N9058 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/21/2023	Cross Connection Survey
001-6041	N9052	Blackoak St	Residential	N9052 Blackoak St	N	P	N	1.25"	2006	P	1.25"	12/18/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	12/18/2012	Visual Insp During Install or Repair
001-6042	N9046	Blackoak St	Residential	N9046 Blackoak St	N	P	N	1.25"	2006	P	1.25"	10/26/2009	SF	N	O	2009	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Cross Connection Survey
001-6043	N9040	Blackoak St	Residential	N9040 Blackoak St	N	P	N	1.25"	2006	P	1.25"	10/3/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/28/2019	Cross Connection Survey
001-6044	N9034	Blackoak St	Residential	N9034 Blackoak St	N	P	N	1.25"	2006	P	1.25"	8/15/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/2013	Visual Insp During Install or Repair
001-6045	N9028	Blackoak St	Residential	N9028 Blackoak St	N	P	N	1.25"	2006	P	1.25"	9/26/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/26/2013	Visual Insp During Install or Repair
001-6046	N9022	Blackoak St	Residential	N9022 Blackoak St	N	P	N	1.25"	2006	P	1.25"	6/20/2014	SF	UNK	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	6/20/2014	Visual Insp During Install or Repair
001-6047	N9016	Blackoak St	Residential	N9016 Blackoak St	N	P	N	1.25"	2006	P	1.25"	9/5/2014	SF	UNK	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	9/5/2014	Visual Insp During Install or Repair
001-6048	N9010	Blackoak St	Residential	N9010 Blackoak St	N	P	N	1.25"	2006	P	1.25"	8/8/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/8/2012	Visual Insp During Install or Repair
001-6049	N9004	Blackoak St	Residential	N9004 Blackoak St	N	P	N	1.25"	2006	P	1.25"	10/3/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2019	Cross Connection Survey
001-6050	N8994	Blackoak St	Residential	N8994 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/3/2023	Cross Connection Survey
001-6052	W6404	Dogwood Ln	Residential	W6404 Dogwood Ln	N	P	N	1"	2001	P	1"	2/2/2010	SF	UNK	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/2/2010	Visual Insp During Install or Repair
001-6053	W6411	Dogwood Ln	Residential	W6411 Dogwood Ln	N	P	N	1.25"	2006	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2023	Cross Connection Survey
001-6054	N8976	Blackoak St	Residential	N8976 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2/4/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2019	Cross Connection Survey
001-6055	N8968	Blackoak St	Residential	N8968 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/9/2023	Cross Connection Survey
001-6056	N8960	Blackoak St	Residential	N8960 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2011	SF	N	O	2011	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/2/2023	Cross Connection Survey
001-6057	N8952	Blackoak St	Residential	N8952 Blackoak St	N	P	N	1.25"	2006	P	1.25"	10/5/2021	SF	UNK	O	2021	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/5/2021	Visual Insp During Install or Repair
001-6058	N8944	Blackoak St	Residential	N8944 Blackoak St	N	P	N	1.25"	2006	P	1.25"	8/3/2021	SF	UNK	O	2021	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/3/2021	Visual Insp During Install or Repair
001-6059	N8936	Blackoak St	Residential	N8936 Blackoak St	N	P	N	1.25"	2006	P	1.25"	8/1/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/1/2013	Visual Insp During Install or Repair
001-6060	N8928	Blackoak St	Residential	N8928 Blackoak St	N	P	N	1.25"	2006	P	1.25"	2/20/2014	SF	UNK	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/20/2014	Visual Insp During Install or Repair
001-6061	W6434	Cherrybark Cir	Residential	W6434 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/28/2013	SF	UNK	O	2013	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	8/28/2013	Visual Insp During Install or Repair
001-6062	W6438	Cherrybark Cir	Residential	W6438 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	6/12/2012	SF	UNK	O	2012	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/2012	Visual Insp During Install or Repair
001-6063	W6442	Cherrybark Cir	Residential	W6442 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	8/27/2010	SF	N	O	2010	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/2021	Cross Connection Survey
001-6064	W6446	Cherrybark Cir	Residential	W6446 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	4/28/2014	SF	UNK	O	2014	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	4/28/2014	Visual Insp During Install or Repair
001-6065	W6464	Cherrybark Cir	Residential	W6464 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	10/20/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	2/19/2019	Cross Connection Survey
001-6066	W6468	Cherrybark Cir	Residential	W6468 Cherrybark Cir	N	P	N	1.25"	2006	P	1.25"	11/20/2008	SF	N	O	2008	Installation Record	Y	2006	Visual Insp During Install or Repair	Field Inspection Only	Y	3/14/2019	Cross Connection Survey
001-6067	W6472	Cherrybark Cir	Residential	W6472 Cherrybark Cir																				



LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-7009	N8840	S Coop Rd	Residential	N8840 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	12/29/2010	SF	N	O	2010	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	4/27/2023	Cross Connection Survey
001-7010	N8820	S Coop Rd	Residential	N8820 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	11/18/2019	SF	UNK	O	2019	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	11/18/2019	Visual Insp During Install or Repair
001-7029	N8847	S Coop Rd	Residential	N8847 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	12/21/2018	SF	UNK	O	2018	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	12/21/2018	Visual Insp During Install or Repair
001-7030	N8881	S Coop Rd	Residential	N8881 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	5/3/2018	SF	UNK	O	2018	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2018	Visual Insp During Install or Repair
001-7031	N8831	S Coop Rd	Residential	N8831 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	12/28/2010	SF	N	CLS	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	2/16/2023	Cross Connection Survey
001-7032	N8827	S Coop Rd	Residential	N8827 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	12/28/2010	SF	N	CLS	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	2/16/2023	Cross Connection Survey
001-7033	N8830	S Coop Rd	Residential	N8830 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	1/20/2011	SF	UNK	C	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	1/20/2011	Visual Insp During Install or Repair
001-7034	N8801	S Coop Rd	Residential	N8801 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	1/6/2011	SF	N	CLS	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-7035	N8789	S Coop Rd	Residential	N8789 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	1/21/2011	SF	N	C	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	2/6/2023	Cross Connection Survey
001-7036	N8781	S Coop Rd	Residential	N8781 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	12/2/2011	SF	N	CLS	Pre 1984	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	3/27/2024	Cross Connection Survey
001-7037	N8777	S Coop Rd	Residential	N8777 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	1/13/2011	SF	N	C	2011	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	2/8/2024	Cross Connection Survey
001-7038	N8761	S Coop Rd	Residential	N8761 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	6/17/2020	SF	UNK	O	2020	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	6/17/2020	Visual Insp During Install or Repair
001-7039	N8747	S Coop Rd	Residential	N8747 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	6/25/2018	SF	UNK	O	2018	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	6/25/2018	Visual Insp During Install or Repair
001-7040	W6132	Wilz Ct	Residential	W6132 Wilz Ct	N	P	N	1.25"	2018	P	1.25"	2/26/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	2/26/2018	Visual Insp During Install or Repair
001-7042	N8838	S Coop Rd	Residential	N8838 S Coop Rd	N	P	N	1.25"	2010	P	1.25"	10/7/2021	SF	UNK	O	2021	Installation Record	Y	2010	Visual Insp During Install or Repair	Field Inspection Only	Y	10/7/2021	Visual Insp During Install or Repair
001-8001	N9094	Papermaker Pass	Residential	N9094 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/29/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2016	Visual Insp During Install or Repair
001-8002	N9088	Papermaker Pass	Residential	N9088 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/29/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2016	Visual Insp During Install or Repair
001-8003	N9084	Papermaker Pass	Residential	N9084 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/14/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/14/2016	Visual Insp During Install or Repair
001-8004	N9078	Papermaker Pass	Residential	N9078 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	1/25/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	1/25/2013	Visual Insp During Install or Repair
001-8005	N9074	Papermaker Pass	Residential	N9074 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	7/15/2015	SF	UNK	O	2015	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	7/17/2015	Visual Insp During Install or Repair
001-8006	N9068	Papermaker Pass	Residential	N9068 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	12/27/2012	SF	UNK	O	2012	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/27/2012	Visual Insp During Install or Repair
001-8007	N9064	Papermaker Pass	Residential	N9064 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/29/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/29/2014	Visual Insp During Install or Repair
001-8008	N9060	Papermaker Pass	Residential	N9060 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/30/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/30/2014	Visual Insp During Install or Repair
001-8009	N9054	Papermaker Pass	Residential	N9054 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	3/11/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	3/11/2013	Visual Insp During Install or Repair
001-8010	N9048	Papermaker Pass	Residential	N9048 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	5/1/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/2014	Visual Insp During Install or Repair
001-8011	N9042	Papermaker Pass	Residential	N9042 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	4/4/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/4/2013	Visual Insp During Install or Repair
001-8012	N9036	Papermaker Pass	Residential	N9036 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	5/2/2023	SF	UNK	O	2023	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2023	Visual Insp During Install or Repair
001-8013	N9030	Papermaker Pass	Residential	N9030 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	2/19/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2024	Cross Connection Survey
001-8015	N9016	Papermaker Pass	Residential	N9016 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	12/21/2012	SF	UNK	O	2012	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/21/2012	Visual Insp During Install or Repair
001-8016	W6301	Kimberly Trl	Residential	W6301 Kimberly Trl	N	P	N	1.25"	2012	P	1.25"	9/8/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	9/8/2016	Visual Insp During Install or Repair
001-8017	W6307	Kimberly Trl	Residential	W6307 Kimberly Trl	N	P	N	1.25"	2012	P	1.25"	9/8/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	9/8/2016	Visual Insp During Install or Repair
001-8018	N9003	Lilac Rd	Residential	N9003 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	12/31/2012	SF	UNK	O	2012	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/31/2012	Visual Insp During Install or Repair
001-8019	N9014	Lilac Rd	Residential	N9014 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	5/1/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/1/2014	Visual Insp During Install or Repair
001-8020	N9015	Papermaker Pass	Residential	N9015 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	10/8/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	10/8/2013	Visual Insp During Install or Repair
001-8021	N9023	Papermaker Pass	Residential	N9023 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	9/5/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	9/5/2013	Visual Insp During Install or Repair
001-8022	N9029	Papermaker Pass	Residential	N9029 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	11/17/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	11/17/2016	Visual Insp During Install or Repair
001-8023	N9035	Papermaker Pass	Residential	N9035 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	12/5/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/5/2016	Visual Insp During Install or Repair
001-8024	N9041	Papermaker Pass	Residential	N9041 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	1/29/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	1/29/2013	Visual Insp During Install or Repair
001-8025	N9047	Papermaker Pass	Residential	N9047 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	3/6/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	3/6/2014	Visual Insp During Install or Repair
001-8026	N9053	Papermaker Pass	Residential	N9053 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	7/16/2015	SF	UNK	O	2015	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	7/16/2015	Visual Insp During Install or Repair
001-8027	N9059	Papermaker Pass	Residential	N9059 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	11/21/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	11/21/2016	Visual Insp During Install or Repair
001-8028	N9063	Papermaker Pass	Residential	N9063 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	9/26/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	9/26/2013	Visual Insp During Install or Repair
001-8029	N9067	Papermaker Pass	Residential	N9067 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	12/5/2012	SF	UNK	O	2012	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/5/2012	Visual Insp During Install or Repair
001-8030	N9073	Papermaker Pass	Residential	N9073 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	12/12/2013	SF	UNK	O	2013	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	12/12/2013	Visual Insp During Install or Repair
001-8031	N9079	Papermaker Pass	Residential	N9079 Papermaker Pass	N	P	N	1.25"	2012	P	1.25"	2/11/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	2/11/2014	Visual Insp During Install or Repair
001-8032	W6298	Champion Trl	Residential	W6298 Champion Trl	N	P	N	1.25"	2012	P	1.25"	8/18/2014	SF	UNK	O	2014	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	8/18/2014	Visual Insp During Install or Repair
001-8033	W6302	Champion Trl	Residential	W6302 Champion Trl	N	P	N	1.25"	2012	P	1.25"	5/3/2018	SF	UNK	O	2018	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2018	Visual Insp During Install or Repair
001-8034	W6308	Champion Trl	Residential	W6308 Champion Trl	N	P	N	1.25"	2012	P	1.25"	5/4/2018	SF	UNK	O	2018	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/4/2018	Visual Insp During Install or Repair
001-8035	W6312	Champion Trl	Residential	W6312 Champion Trl	N	P	N	1.25"	2012	P	1.25"	6/12/2017	SF	UNK	O	2017	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	6/12/2017	Visual Insp During Install or Repair
001-8036	N9087	Lilac Rd	Residential	N9087 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	6/24/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	6/24/2016	Visual Insp During Install or Repair
001-8037	N9083	Lilac Rd	Residential	N9083 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	11/1/2017	SF	UNK	O	2017	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	11/1/2017	Visual Insp During Install or Repair
001-8038	N9077	Lilac Rd	Residential	N9077 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	5/3/2018	SF	UNK	O	2018	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	5/3/2018	Visual Insp During Install or Repair
001-8039	N9071	Lilac Rd	Residential	N9071 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	1/17/2017	SF	UNK	O	2017	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	1/17/2017	Visual Insp During Install or Repair
001-8040	N9065	Lilac Rd	Residential	N9065 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	11/10/2015	SF	UNK	O	2015	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	11/10/2015	Visual Insp During Install or Repair
001-8041	N9059	Lilac Rd	Residential	N9059 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	4/26/2016	SF	UNK	O	2016	Installation Record	Y	2012	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2016	Visual Insp During Install or Repair
001-8042	N9053	Lilac Rd	Residential	N9053 Lilac Rd	N	P	N	1.25"	2012	P	1.25"	8												

LCRR Master Customer Account List (as of 2024.09.12)  
As of 9/12/2024

Account Nbr	Street #	Street	PSC Classification	LOCATIONAL IDENTIFIER (EPA Col. B)	LEAD GOOSENECK CURRENTLY PRESENT? (EPA Col. C)	CURRENT STREET SIDE SERVICE LINE MATERIAL (EPA Col. D)	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD? (EPA Col. E)	STREET SIDE SERVICE LINE SIZE (EPA Col. F)	STREET SIDE SERVICE LINE INSTALL DATE (EPA Col. G)	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL (EPA Col. H)	PROPERTY SIDE SERVICE LINE SIZE (EPA Col. I)	PROPERTY SIDE SERVICE LINE INSTALL DATE (EPA Col. J)	BUILDING TYPE (EPA Col. K)	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT? (EPA Col. L)	BUILDING PLUMBING MATERIAL 1 (EPA Col. M)	BUILDING PLUMBING MATERIAL INSTALL DATE (EPA Col. O)	BASIS OF STREET SIDE MATERIAL CLASSIFICATION (EPA Col. Q)	WAS STREET SIDE MATERIAL FIELD VERIFIED? (EPA Col. R)	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. S)	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. T)	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION (EPA Col. U)	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED? (EPA Col. V)	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. W)	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE (EPA Col. X)
001-9021	W6092	Zach St	Residential	W6092 Zach St	N	P	N	1"	2018	P	1.25"	7/27/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	7/27/2018	Visual Insp During Install or Repair
001-9022	W6084	Zach St	Residential	W6084 Zach St	N	P	N	1"	2018	P	1.25"	4/24/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	4/24/2018	Visual Insp During Install or Repair
001-9023	W6078	Zach St	Residential	W6078 Zach St	N	P	N	1"	2018	P	1.25"	6/5/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	6/5/2018	Visual Insp During Install or Repair
001-9024	W6070	Zach St	Residential	W6070 Zach St	N	P	N	1"	2018	P	1.25"	10/25/2017	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/25/2017	Visual Insp During Install or Repair
001-9025	W6064	Zach St	Residential	W6064 Zach St	N	P	N	1"	2018	P	1.25"	10/18/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/2017	Visual Insp During Install or Repair
001-9026	W6056	Zach St	Residential	W6056 Zach St	N	P	N	1"	2018	P	1.25"	2/5/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2018	Visual Insp During Install or Repair
001-9027	W6050	Zach St	Residential	W6050 Zach St	N	P	N	1"	2018	P	1.25"	7/24/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	7/24/2018	Visual Insp During Install or Repair
001-9028	W6044	Zach St	Residential	W6044 Zach St	N	P	N	1"	2018	P	1.25"	11/7/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/2017	Visual Insp During Install or Repair
001-9029	W6036	Zach St	Residential	W6036 Zach St	N	P	N	1"	2018	P	1.25"	10/19/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/19/2017	Visual Insp During Install or Repair
001-9030	W6030	Zach St	Residential	W6030 Zach St	N	P	N	1"	2018	P	1.25"	7/25/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	7/25/2018	Visual Insp During Install or Repair
001-9031	W6029	Zach St	Residential	W6029 Zach St	N	P	N	1"	2018	P	1.25"	1/30/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	1/30/2018	Visual Insp During Install or Repair
001-9032	W6035	Zach St	Residential	W6035 Zach St	N	P	N	1"	2018	P	1.25"	5/2/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	5/2/2018	Visual Insp During Install or Repair
001-9033	W6043	Zach St	Residential	W6043 Zach St	N	P	N	1"	2018	P	1.25"	8/7/2019	SF	UNK	O	2019	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	8/7/2019	Visual Insp During Install or Repair
001-9034	W6049	Zach St	Residential	W6049 Zach St	N	P	N	1"	2018	P	1.25"	12/20/2019	SF	UNK	O	2019	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	12/20/2019	Visual Insp During Install or Repair
001-9035	W6055	Zach St	Residential	W6055 Zach St	N	P	N	1"	2018	P	1.25"	10/17/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/17/2017	Visual Insp During Install or Repair
001-9036	W6063	Zach St	Residential	W6063 Zach St	N	P	N	1"	2018	P	1.25"	10/26/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/26/2017	Visual Insp During Install or Repair
001-9037	W6069	Zach St	Residential	W6069 Zach St	N	P	N	1"	2018	P	1.25"	11/7/2019	SF	UNK	O	2019	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	11/7/2019	Visual Insp During Install or Repair
001-9038	W6077	Zach St	Residential	W6077 Zach St	N	P	N	1"	2018	P	1.25"	8/15/2019	SF	UNK	O	2019	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	8/15/2019	Visual Insp During Install or Repair
001-9039	W6083	Zach St	Residential	W6083 Zach St	N	P	N	1"	2018	P	1.25"	5/10/2018	SF	UNK	O	2018	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	5/10/2018	Visual Insp During Install or Repair
001-9040	W6091	Zach St	Residential	W6091 Zach St	N	P	N	1"	2018	P	1.25"	10/18/2017	SF	UNK	O	2017	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/18/2017	Visual Insp During Install or Repair
001-9041	W6024	Ryford St	Residential	W6024 Ryford St	N	P	N	1.25"	2014	P	1.25"	2/5/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2020	Visual Insp During Install or Repair
001-9042	W6018	Ryford St	Residential	W6018 Ryford St	N	P	N	1.25"	2014	P	1.25"	10/21/2021	SF	UNK	O	2021	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	10/21/2021	Visual Insp During Install or Repair
001-9043	W6010	Ryford St	Residential	W6010 Ryford St	N	P	N	1.25"	2014	P	1.25"	8/25/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2020	Visual Insp During Install or Repair
001-9044	W6004	Ryford St	Residential	W6004 Ryford St	N	P	N	1.25"	2014	P	1.25"	1/14/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	1/14/2020	Visual Insp During Install or Repair
001-9045	W5996	Ryford St	Residential	W5996 Ryford St	N	P	N	1.25"	2014	P	1.25"	7/17/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	7/17/2020	Visual Insp During Install or Repair
001-9046	W5995	Ryford St	Residential	W5995 Ryford St	N	P	N	1.25"	2014	P	1.25"	5/4/2021	SF	UNK	O	2021	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	5/4/2021	Visual Insp During Install or Repair
001-9047	W6003	Ryford St	Residential	W6003 Ryford St	N	P	N	1.25"	2014	P	1.25"	6/1/2021	SF	UNK	O	2021	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	6/1/2021	Visual Insp During Install or Repair
001-9048	W6009	Ryford St	Residential	W6009 Ryford St	N	P	N	1.25"	2014	P	1.25"	3/4/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	3/4/2020	Visual Insp During Install or Repair
001-9049	W6017	Ryford St	Residential	W6017 Ryford St	N	P	N	1.25"	2014	P	1.25"	6/15/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	6/15/2020	Visual Insp During Install or Repair
001-9050	W6023	Ryford St	Residential	W6023 Ryford St	N	P	N	1.25"	2014	P	1.25"	2/5/2020	SF	UNK	O	2020	Installation Record	Y	2014	Visual Insp During Install or Repair	Field Inspection Only	Y	2/5/2020	Visual Insp During Install or Repair
001-9051	W6022	Zach St	Residential	W6022 Zach St	N	P	N	1"	2018	P	1.25"	9/8/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	9/8/2020	Visual Insp During Install or Repair
001-9052	W6016	Zach St	Residential	W6016 Zach St	N	P	N	1"	2018	P	1.25"	10/9/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	10/9/2020	Visual Insp During Install or Repair
001-9053	W6008	Zach St	Residential	W6008 Zach St	N	P	N	1"	2018	P	1.25"	6/8/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	6/8/2020	Visual Insp During Install or Repair
001-9054	W6002	Zach St	Residential	W6002 Zach St	N	P	N	1"	2018	P	1.25"	5/26/2022	SF	UNK	O	2022	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	5/26/2022	Visual Insp During Install or Repair
001-9055	W5994	Zach St	Residential	W5994 Zach St	N	P	N	1"	2018	P	1.25"	5/13/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	5/13/2020	Visual Insp During Install or Repair
001-9056	W6021	Zach St	Residential	W6021 Zach St	N	P	N	1"	2018	P	1.25"	11/14/2019	SF	UNK	O	2019	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	11/14/2019	Visual Insp During Install or Repair
001-9057	W6015	Zach St	Residential	W6015 Zach St	N	P	N	1"	2018	P	1.25"	2/17/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	2/17/2020	Visual Insp During Install or Repair
001-9058	W6007	Zach St	Residential	W6007 Zach St	N	P	N	1"	2018	P	1.25"	2/7/2022	SF	UNK	O	2022	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	2/7/2022	Visual Insp During Install or Repair
001-9059	W6001	Zach St	Residential	W6001 Zach St	N	P	N	1"	2018	P	1.25"	9/22/2020	SF	UNK	O	2020	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	9/22/2020	Visual Insp During Install or Repair
001-9060	W5993	Zach St	Residential	W5993 Zach St	N	P	N	1"	2018	P	1.25"	6/2/2021	SF	UNK	O	2021	Installation Record	Y	2018	Visual Insp During Install or Repair	Field Inspection Only	Y	6/2/2021	Visual Insp During Install or Repair
001-9061	N8771	Connor Cir	Residential	N8771 Connor Cir	N	P	N	1.25"	2019	P	1.25"	9/9/2020	SF	UNK	O	2020	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	9/9/2020	Visual Insp During Install or Repair
001-9063	N8763	Connor Cir	Residential	N8763 Connor Cir	N	P	N	1.25"	2019	P	1.25"	5/9/2023	SF	UNK	O	2023	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	5/9/2023	Visual Insp During Install or Repair
001-9064	N8786	Connor Cir	Residential	N8786 Connor Cir	N	P	N	1.25"	2019	P	1.25"	3/3/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	3/3/2022	Visual Insp During Install or Repair
001-9065	N8782	Connor Cir	Residential	N8782 Connor Cir	N	P	N	1.25"	2019	P	1.25"	5/16/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	5/16/2022	Visual Insp During Install or Repair
001-9066	N8778	Connor Cir	Residential	N8778 Connor Cir	N	P	N	1.25"	2019	P	1.25"	2/28/2023	SF	UNK	O	2023	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	2/28/2023	Visual Insp During Install or Repair
001-9067	N8774	Connor Cir	Residential	N8774 Connor Cir	N	P	N	1.25"	2019	P	1.25"	11/7/2023	SF	UNK	O	2024	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	2/27/2024	Cross Connection Survey
001-9069	N8739	Connor Cir	Residential	N8739 Connor Cir	N	P	N	1.25"	2019	P	1.25"	9/13/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	9/13/2022	Visual Insp During Install or Repair
001-9070	N8733	Connor Cir	Residential	N8733 Connor Cir	N	P	N	1.25"	2019	P	1.25"	4/18/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	4/18/2022	Visual Insp During Install or Repair
001-9071	N8727	Connor Cir	Residential	N8727 Connor Cir	N	P	N	1.25"	2019	P	1.25"	4/26/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	4/26/2022	Visual Insp During Install or Repair
001-9072	N8723	Connor Cir	Residential	N8723 Connor Cir	N	P	N	1.25"	2019	P	1.25"	3/5/2021	SF	UNK	O	2021	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2021	Visual Insp During Install or Repair
001-9073	N8719	Connor Cir	Residential	N8719 Connor Cir	N	P	N	1.25"	2019	P	1.25"	6/22/2022	SF	UNK	O	2022	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	6/22/2022	Visual Insp During Install or Repair
001-9074	W5982	Ryford St	Residential	W5982 Ryford St	N	P	N	1.25"	2019	P	1.25"	9/13/2021	SF	UNK	O	2021	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	9/13/2021	Visual Insp During Install or Repair
001-9075	W5972	Ryford St	Residential	W5972 Ryford St	N	P	N	1.25"	2019	P	1.25"	2/22/2021	SF	UNK	O	2021	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	2/22/2021	Visual Insp During Install or Repair
001-9076	W5964	Ryford St	Residential	W5964 Ryford St	N	P	N	1.25"	2019	P	1.25"	3/5/2021	SF	UNK	O	2021	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	3/5/2021	Visual Insp During Install or Repair
001-9077	W5954	Ryford St	Residential	W5954 Ryford St	N	P	N	1.25"	2019	P	1.25"	8/25/2020	SF	UNK	O	2020	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y	8/25/2020	Visual Insp During Install or Repair
001-9078	N8718	Connor Cir	Residential	N8718 Connor Cir	N	P	N	1.25"	2019	P	1.25"	9/30/2021	SF	UNK	O	2021	Installation Record	Y	2019	Visual Insp During Install or Repair	Field Inspection Only	Y		









